MOB I LUBE 360™ OIL DIAGNOSTICS

OIL ANALYSIS REPORT

WEAR	NORMAL
CONTAMINATION	NORMAL
FLUID CONDITION	NORMAL

Machine Id
CATERPILLAR 980H 2231005
Component
Front Differential
Fluid
PETRO CANADA DURATRAN (--- GAL)

RECOMMENDATION

Resample at the next service interval to monitor.

WEAR

All component wear rates are normal.

CONTAMINATION

There is no indication of any contamination in the oil.

FLUID CONDITION

The condition of the oil is acceptable for the time in service.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		PC0088736	---	---
Sample Date		Client Info		30 Apr 2024	---	---
Machine Age	hrs	Client Info		21133	---	---
Oil Age	hrs	Client Info		300	---	---
Filter Age	hrs	Client Info		0	---	---
Oil Changed		Client Info		N/A	---	---
Filter Changed		Client Info		Changed	---	---
Sample Status				NORMAL	---	---
Iron	ppm	ASTM D5185(m)	>500	31	---	---
Chromium	ppm	ASTM D5185(m)	>3	0	---	---
Nickel	ppm	ASTM D5185(m)	>3	<1	---	---
Titanium	ppm	ASTM D5185(m)	>2	0	---	---
Silver	ppm	ASTM D5185(m)	>2	0	---	---
Aluminum	ppm	ASTM D5185(m)	>30	3	---	---
Lead	ppm	ASTM D5185(m)	>13	0	---	---
Copper	ppm	ASTM D5185(m)	>103	19	---	---
Tin	ppm	ASTM D5185(m)	>5	0	---	---
Vanadium	ppm	ASTM D5185(m)		0	---	---
White Metal	scalar	Visual*	NONE	VLITE	---	---
Yellow Metal	scalar	Visual*	NONE	NONE	---	---
Silicon	ppm	ASTM D5185(m)	>100	20	---	---
Potassium	ppm	ASTM D5185(m)	>20	<1	---	---
Water		WC Method	>.2	NEG	---	---
Silt	scalar	Visual*	NONE	NONE	---	---
Debris	scalar	Visual*	NONE	NONE	---	---
Sand/Dirt	scalar	Visual*	NONE	NONE	---	---
Appearance	scalar	Visual*	NORML	NORML	---	---
Odor	scalar	Visual*	NORML	NORML	---	---
Emulsified Water	scalar	Visual*	>.2	NEG	---	---
Sodium	ppm	ASTM D5185(m)		<1	---	---
Boron	ppm	ASTM D5185(m)	110	90	---	---
Barium	ppm	ASTM D5185(m)	0.0	0	---	---
Molybdenum	ppm	ASTM D5185(m)	0.0	0	---	---
Manganese	ppm	ASTM D5185(m)	1	<1	---	---
Magnesium	ppm	ASTM D5185(m)	13	26	---	---
Calcium	ppm	ASTM D5185(m)	3610	3663	---	---
Phosphorus	ppm	ASTM D5185(m)	1192	1089	---	---
Zinc	ppm	ASTM D5185(m)	1455	1393	---	---
Sulfur	ppm	ASTM D5185(m)	2641	7097	---	---
Visc @ 40°C	cSt	ASTM D7279(m)	55.14	60.3	---	---
Visc @ 100°C	cSt	ASTM D7279(m)	9.38	8.8	---	---
Viscosity Index (VI)	Scale	ASTM D2270*	153	120	---	---

Viscosity @ 100°C



Viscosity @ 40°C



Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 40°C



Additives



ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : PC0088736 **Received** : 03 May 2024
Lab Number : 02633292 **Tested** : 03 May 2024
Unique Number : 5774445 **Diagnosed** : 03 May 2024 - Wes Davis
Test Package : MOB 1 (Additional Tests: KV100, VI)

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

LAVIS CONTRACTING
37462A HURON ROAD
CLINTON, ON
CA N0M 1L0
Contact: Doug Francis
dfrancis@lavis.ca
T: (519)482-3694
F: (519)482-7886