MOB

LIEBHERR

OIL ANALYSIS REPORT

WEAR	NORMAL
CONTAMINATION	NORMAL
FLUID CONDITION	NORMAL

Area
(348643)
Machine Id
LIEBHERR PR736LGP 018793-1155
Component
Left Final Drive
Fluid
GEAR OIL SAE 75W90 (--- GAL)

RECOMMENDATION

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 75W90. Please confirm.

WEAR

All component wear rates are normal.

CONTAMINATION

There is no indication of any contamination in the oil.

FLUID CONDITION

The condition of the oil is acceptable for the time in service.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		**LH0199304**	LH0199296	LH0199288
Sample Date		Client Info		**29 Apr 2024**	06 Feb 2023	06 Dec 2021
Machine Age	hrs	Client Info		**3004**	1978	1074
Oil Age	hrs	Client Info		**0**	0	0
Filter Age	hrs	Client Info		**0**	0	0
Oil Changed		Client Info		**Not Changd**	Changed	Changed
Filter Changed		Client Info		**None**	None	N/A
Sample Status				**NORMAL**	NORMAL	NORMAL
Iron	ppm	ASTM D5185(m)	>500	**26**	51	109
Chromium	ppm	ASTM D5185(m)	>10	**0**	<1	1
Nickel	ppm	ASTM D5185(m)	>10	**0**	<1	<1
Titanium	ppm	ASTM D5185(m)		**0**	0	0
Silver	ppm	ASTM D5185(m)		**0**	0	<1
Aluminum	ppm	ASTM D5185(m)	>25	**<1**	1	2
Lead	ppm	ASTM D5185(m)	>25	**0**	<1	<1
Copper	ppm	ASTM D5185(m)	>50	**11**	26	28
Tin	ppm	ASTM D5185(m)	>10	**<1**	1	2
Vanadium	ppm	ASTM D5185(m)		**0**	0	0
White Metal	scalar	Visual*	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	Visual*	NONE	**NONE**	NONE	NONE
Silicon	ppm	ASTM D5185(m)	>75	**1**	3	6
Potassium	ppm	ASTM D5185(m)	>20	**<1**	<1	1
Water		WC Method	>0.2	**NEG**	NEG	NEG
Silt	scalar	Visual*	NONE	**NONE**	NONE	NONE
Debris	scalar	Visual*	NONE	**NONE**	NONE	LIGHT
Sand/Dirt	scalar	Visual*	NONE	**NONE**	NONE	NONE
Appearance	scalar	Visual*	NORML	**NORML**	NORML	NORML
Odor	scalar	Visual*	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	Visual*	>0.2	**NEG**	NEG	NEG
Sodium	ppm	ASTM D5185(m)		**<1**	2	3
Boron	ppm	ASTM D5185(m)	400	**131**	176	4
Barium	ppm	ASTM D5185(m)	200	**5**	18	58
Molybdenum	ppm	ASTM D5185(m)	12	**0**	0	<1
Manganese	ppm	ASTM D5185(m)		**0**	<1	1
Magnesium	ppm	ASTM D5185(m)	12	**<1**	0	2
Calcium	ppm	ASTM D5185(m)	150	**5**	3	12
Phosphorus	ppm	ASTM D5185(m)	1650	**969**	1454	1194
Zinc	ppm	ASTM D5185(m)	125	**24**	10	20
Sulfur	ppm	ASTM D5185(m)	22500	**19337**	24916	24847
Visc @ 40°C	cSt	ASTM D7279(m)	109	**80.1**	129	331

Viscosity @ 40°C



Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 40°C



Additives



ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : LH0199304
Lab Number : 02635355
Unique Number : 5776508
Test Package : MOBCE

Received : 14 May 2024
Tested : 14 May 2024
Diagnosed : 14 May 2024 - Wes Davis

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

COUNTY OF ST. PAUL NO. 19
5015 - 49 AVENUE
ST. PAUL, AB
CA T0A 3A4
Contact: DD SKAWRONSKI-MUNRO
DSKAWRONSKI@COUNTY.STPAUL.AB.CA
T: (780)645-3006
F: (780)645-1800