MOB I LUBE 360™ OIL DIAGNOSTICS

OIL ANALYSIS REPORT

WEAR	NORMAL
CONTAMINATION	NORMAL
FLUID CONDITION	NORMAL

Area
GFL216
Machine Id
911049
Component
Diesel Engine
Fluid
DIESEL ENGINE OIL SAE 15W40 (--- GAL)

RECOMMENDATION

Resample at the next service interval to monitor.

WEAR

Metal levels are typical for a new component breaking in.

CONTAMINATION

Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. There is no indication of any contamination in the oil.

FLUID CONDITION

The condition of the oil is acceptable for the time in service.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		**GFL0121958**	GFL0099670	GFL0089252
Sample Date		Client Info		**05 Jun 2024**	22 Nov 2023	11 Aug 2023
Machine Age	kms	Client Info		**47707**	29928	20338
Oil Age	kms	Client Info		**0**	0	0
Filter Age	kms	Client Info		**0**	0	0
Oil Changed		Client Info		**Changed**	Changed	Changed
Filter Changed		Client Info		**Changed**	Changed	Changed
Sample Status				**NORMAL**	NORMAL	NORMAL
Iron	ppm	ASTM D5185(m)	>120	**41**	19	25
Chromium	ppm	ASTM D5185(m)	>20	**1**	<1	<1
Nickel	ppm	ASTM D5185(m)	>5	**3**	2	2
Titanium	ppm	ASTM D5185(m)	>2	**0**	0	0
Silver	ppm	ASTM D5185(m)	>2	**0**	<1	<1
Aluminum	ppm	ASTM D5185(m)	>20	**8**	2	2
Lead	ppm	ASTM D5185(m)	>40	**<1**	<1	1
Copper	ppm	ASTM D5185(m)	>330	**11**	16	39
Tin	ppm	ASTM D5185(m)	>15	**2**	1	1
Vanadium	ppm	ASTM D5185(m)		**0**	0	0
Silicon	ppm	ASTM D5185(m)	>25	**4**	4	8
Potassium	ppm	ASTM D5185(m)	>20	**23**	3	3
Fuel		WC Method	>3.0	**<1.0**	<1.0	<1.0
Water		WC Method	>0.2	**NEG**	NEG	NEG
Glycol		WC Method		**NEG**	NEG	NEG
Soot %	%	ASTM D7844*	>4	**1.1**	0.6	0.5
Nitration	Abs/cm	ASTM D7624*	>20	**10.2**	8.4	8.1
Sulfation	Abs/.1mm	ASTM D7415*	>30	**23.1**	20.2	20.4
Emulsified Water	scalar	Visual*	>0.2	**NEG**	NEG	NEG
Sodium	ppm	ASTM D5185(m)	>158	**7**	5	5
Boron	ppm	ASTM D5185(m)	250	**2**	4	4
Barium	ppm	ASTM D5185(m)	10	**0**	<1	0
Molybdenum	ppm	ASTM D5185(m)	100	**62**	59	57
Manganese	ppm	ASTM D5185(m)		**1**	<1	1
Magnesium	ppm	ASTM D5185(m)	450	**1011**	937	888
Calcium	ppm	ASTM D5185(m)	3000	**1098**	1029	1142
Phosphorus	ppm	ASTM D5185(m)	1150	**960**	906	969
Zinc	ppm	ASTM D5185(m)	1350	**1195**	1144	1162
Sulfur	ppm	ASTM D5185(m)	4250	**2012**	2087	2026
Oxidation	Abs/.1mm	ASTM D7414*	>25	**19.3**	15.9	16.3
Visc @ 100°C	cSt	ASTM D7279(m)	14.4	**13.3**	13.4	13.2

FT-IR (Direct Trend)



Viscosity @ 100°C



Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



Soot %



ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : GFL0121958
Lab Number : 02640407
Unique Number : 5789569
Test Package : MOB 1

Received : 07 Jun 2024
Tested : 07 Jun 2024
Diagnosed : 07 Jun 2024 - Wes Davis

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

GFL Environmental - 252 - GTA Hauling
3668 Weston Road
North York, ON
CA M9L 1W2
Contact: Amanda Cipollone
acipollone@gflenv.com
T:
F: