MOBIL WEAR CHECK

OIL ANALYSIS REPORT

WEAR	NORMAL
CONTAMINATION	NORMAL
FLUID CONDITION	NORMAL

Machine Id
KOVATERRA MC100D FMC-004 (S/N 6092)
Component
Diesel Engine
Fluid
MOBIL 15W40 (8 LTR)

RECOMMENDATION

Resample at the next service interval to monitor.

WEAR

Metal levels are typical for a new component breaking in.

CONTAMINATION

There is no indication of any contamination in the oil.

FLUID CONDITION

The condition of the oil is acceptable for the time in service.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		**WC0931356**	WC0928374	WC0892430
Sample Date		Client Info		**09 Jun 2024**	06 Apr 2024	27 Jan 2024
Machine Age	hrs	Client Info		**144**	1524	1320
Oil Age	hrs	Client Info		**0**	250	0
Filter Age	hrs	Client Info		**0**	250	0
Oil Changed		Client Info		**Changed**	Changed	Changed
Filter Changed		Client Info		**Changed**	Changed	N/A
Sample Status				**NORMAL**	ABNORMAL	NORMAL
Iron	ppm	ASTM D5185(m)	>100	**26**	55	13
Chromium	ppm	ASTM D5185(m)	>20	**1**	4	<1
Nickel	ppm	ASTM D5185(m)	>4	**<1**	<1	<1
Titanium	ppm	ASTM D5185(m)		**<1**	<1	0
Silver	ppm	ASTM D5185(m)	>3	**0**	0	0
Aluminum	ppm	ASTM D5185(m)	>20	**6**	18	2
Lead	ppm	ASTM D5185(m)	>40	**0**	0	<1
Copper	ppm	ASTM D5185(m)	>330	**1**	2	2
Tin	ppm	ASTM D5185(m)	>15	**0**	0	0
Vanadium	ppm	ASTM D5185(m)		**0**	0	0
Silicon	ppm	ASTM D5185(m)	>25	**19**	▲ 56	9
Potassium	ppm	ASTM D5185(m)	>20	**2**	8	1
Fuel		WC Method	>5	**<1.0**	<1.0	<1.0
Water		WC Method	>0.2	**NEG**	NEG	NEG
Glycol		WC Method		**NEG**	NEG	NEG
Soot %	%	ASTM D7844*	>3	**0.5**	0.7	0.5
Nitration	Abs/cm	ASTM D7624*	>20	**7.4**	7.8	6.9
Sulfation	Abs/.1mm	ASTM D7415*	>30	**23.0**	23.5	22.7
Emulsified Water	scalar	Visual*	>0.2	**NEG**	NEG	NEG
Sodium	ppm	ASTM D5185(m)	>118	**5**	8	4
Boron	ppm	ASTM D5185(m)		**36**	36	37
Barium	ppm	ASTM D5185(m)		**0**	<1	0
Molybdenum	ppm	ASTM D5185(m)		**40**	39	40
Manganese	ppm	ASTM D5185(m)		**<1**	1	0
Magnesium	ppm	ASTM D5185(m)		**520**	512	524
Calcium	ppm	ASTM D5185(m)		**1739**	1730	1651
Phosphorus	ppm	ASTM D5185(m)		**736**	739	766
Zinc	ppm	ASTM D5185(m)		**879**	883	871
Sulfur	ppm	ASTM D5185(m)		**2233**	2116	2247
Oxidation	Abs/.1mm	ASTM D7414*	>25	**21.0**	20.6	20.0
Visc @ 100°C	cSt	ASTM D7279(m)		**13.8**	14.2	13.6

FT-IR (Direct Trend)



Viscosity @ 100°C



Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



Soot %



ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0931356
Lab Number : 02641016
Unique Number : 5798555
Test Package : MOB 1

Received : 11 Jun 2024
Tested : 11 Jun 2024
Diagnosed : 11 Jun 2024 - Wes Davis

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

Agnico Eagle Canada
1350 Government Rd. W, MACASSA COMPLEX
Kirkland Lake, ON
CA P2N 3J1
Contact: Jay Gould
MacassaMobileUGPlanning@agnicoeagle.com
T: (705)567-5208
F: (705)567-5221