MOB I

OIL ANALYSIS REPORT

WEAR	NORMAL
CONTAMINATION	NORMAL
FLUID CONDITION	NORMAL

Area
COGECO [156393]
Machine Id
16601001362
Component
Diesel Engine
Fluid
VALVOLINE 15W40 (--- GAL)

RECOMMENDATION

Resample at the next service interval to monitor.

WEAR

Metal levels are typical for a new component breaking in.

CONTAMINATION

There is no indication of any contamination in the oil.

FLUID CONDITION

The condition of the oil is acceptable for the time in service.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		**CU0023724**	CU0019556	CU0016124
Sample Date		Client Info		**11 Jun 2024**	13 Jun 2023	28 Jan 2020
Machine Age	hrs	Client Info		**588**	499	234
Oil Age	hrs	Client Info		**0**	0	150
Filter Age	hrs	Client Info		**0**	0	150
Oil Changed		Client Info		**Changed**	Changed	Changed
Filter Changed		Client Info		**Changed**	Changed	Changed
Sample Status				**NORMAL**	NORMAL	NORMAL
Iron	ppm	ASTM D5185(m)	>100	**3**	3	4
Chromium	ppm	ASTM D5185(m)	>20	**0**	0	<1
Nickel	ppm	ASTM D5185(m)	>4	**0**	<1	<1
Titanium	ppm	ASTM D5185(m)		**0**	<1	12
Silver	ppm	ASTM D5185(m)	>3	**0**	0	0
Aluminum	ppm	ASTM D5185(m)	>20	**1**	<1	1
Lead	ppm	ASTM D5185(m)	>40	**0**	<1	<1
Copper	ppm	ASTM D5185(m)	>330	**1**	1	10
Tin	ppm	ASTM D5185(m)	>15	**0**	0	0
Vanadium	ppm	ASTM D5185(m)		**0**	0	<1
Silicon	ppm	ASTM D5185(m)	>25	**3**	4	3
Potassium	ppm	ASTM D5185(m)	>20	**<1**	<1	<1
Fuel		WC Method	>5	**<1.0**	<1.0	<1.0
Water		WC Method	>0.2	**NEG**	NEG	NEG
Glycol		WC Method		**NEG**	NEG	NEG
Soot %	%	ASTM D7844*	>3	**0**	0	0
Nitration	Abs/cm	ASTM D7624*	>20	**7.0**	6.9	7.2
Sulfation	Abs/.1mm	ASTM D7415*	>30	**20.4**	20.3	20.9
Emulsified Water	scalar	Visual*	>0.2	**NEG**	NEG	NEG
Sodium	ppm	ASTM D5185(m)		**3**	3	3
Boron	ppm	ASTM D5185(m)	39	**33**	37	23
Barium	ppm	ASTM D5185(m)	1	**0**	0	<1
Molybdenum	ppm	ASTM D5185(m)	49	**47**	46	47
Manganese	ppm	ASTM D5185(m)	1	**<1**	<1	<1
Magnesium	ppm	ASTM D5185(m)	616	**777**	793	809
Calcium	ppm	ASTM D5185(m)	1554	**1185**	1223	1396
Phosphorus	ppm	ASTM D5185(m)	899	**684**	769	1050
Zinc	ppm	ASTM D5185(m)	1069	**834**	841	1240
Sulfur	ppm	ASTM D5185(m)	2624	**1915**	2019	2871
Oxidation	Abs/.1mm	ASTM D7414*	>25	**17.0**	17.3	14.0
Visc @ 100°C	cSt	ASTM D7279(m)	13.6	**14.1**	13.9	13.9

FT-IR (Direct Trend)



Viscosity @ 100°C



Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



Soot %



ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : CU0023724
Lab Number : 02643354
Unique Number : 5800893
Test Package : MOB 1

Received : 21 Jun 2024
Tested : 21 Jun 2024
Diagnosed : 21 Jun 2024 - Wes Davis

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

CUMMINS CANADA ULC - GENERATOR DIVISION
7175 PACIFIC CIRCLE
MISSISSAUGA, ON
CA L5T 2A5
Contact: Elisia Johnson
elisia.johnson@cummins.com
T: (905)795-0050
F: (905)795-9252