# IDEALEASE FLEET

## OIL ANALYSIS REPORT

| | |
|---|---|
| WEAR | NORMAL |
| CONTAMINATION | NORMAL |
| FLUID CONDITION | NORMAL |

Machine Id
**162103**
Component
**Diesel Engine**
Fluid
**DIESEL ENGINE OIL SAE 40 (--- QTS)**

## RECOMMENDATION

Resample at the next service interval to monitor. Please specify the component make and model with your next sample. Please specify the brand, type, and viscosity of the oil on your next sample.

## WEAR

All component wear rates are normal.

## CONTAMINATION

Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. There is no indication of any contamination in the oil.

## FLUID CONDITION

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

| Test | UOM | Method | Limit/Abn | Current | History1 | History2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **IL06055297** | IL05739473 | IL05500730 |
| Sample Date | | Client Info | | **12 Dec 2023** | 21 Dec 2022 | 03 Mar 2022 |
| Machine Age | hrs | Client Info | | **6710** | 4727 | 2771 |
| Oil Age | hrs | Client Info | | **0** | 0 | 0 |
| Filter Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Changed | | Client Info | | **N/A** | N/A | N/A |
| Filter Changed | | Client Info | | **N/A** | N/A | N/A |
| Sample Status | | | | **NORMAL** | ABNORMAL | NORMAL |
| Iron | ppm | ASTM D5185m | >100 | **40** | 48 | 49 |
| Chromium | ppm | ASTM D5185m | >20 | **2** | 4 | 6 |
| Nickel | ppm | ASTM D5185m | >4 | **1** | 0 | 0 |
| Titanium | ppm | ASTM D5185m | | **<1** | 0 | 0 |
| Silver | ppm | ASTM D5185m | >3 | **0** | 0 | 0 |
| Aluminum | ppm | ASTM D5185m | >20 | **19** | 32 | 75 |
| Lead | ppm | ASTM D5185m | >40 | **4** | 3 | 1 |
| Copper | ppm | ASTM D5185m | >330 | **3** | 5 | 14 |
| Tin | ppm | ASTM D5185m | >15 | **1** | <1 | <1 |
| Vanadium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Silicon | ppm | ASTM D5185m | >25 | **7** | 7 | 5 |
| Potassium | ppm | ASTM D5185m | >20 | **51** | 85 | 179 |
| Fuel | | WC Method | >5 | **<1.0** | <1.0 | <1.0 |
| Water | | WC Method | >0.2 | **NEG** | NEG | NEG |
| Glycol | | WC Method | | **NEG** | NEG | NEG |
| Soot % | % | *ASTM D7844 | >3 | **2.9** | ▲ 3 | 2.4 |
| Nitration | Abs/cm | *ASTM D7624 | >20 | **13.1** | 12.6 | 11.2 |
| Sulfation | Abs/.1mm | *ASTM D7415 | >30 | **29.4** | 28.6 | 26.8 |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Debris | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.2 | **NEG** | NEG | NEG |
| Sodium | ppm | ASTM D5185m | >216 | **0** | <1 | 2 |
| Boron | ppm | ASTM D5185m | 250 | **10** | <1 | 6 |
| Barium | ppm | ASTM D5185m | 10 | **0** | 1 | 0 |
| Molybdenum | ppm | ASTM D5185m | 100 | **64** | 65 | 60 |
| Manganese | ppm | ASTM D5185m | | **1** | 1 | 2 |
| Magnesium | ppm | ASTM D5185m | 450 | **912** | 929 | 962 |
| Calcium | ppm | ASTM D5185m | 3000 | **1214** | 1196 | 1324 |
| Phosphorus | ppm | ASTM D5185m | 1150 | **845** | 1019 | 1083 |
| Zinc | ppm | ASTM D5185m | 1350 | **1214** | 1247 | 1333 |
| Sulfur | ppm | ASTM D5185m | 4250 | **3106** | 2915 | 2632 |
| Oxidation | Abs/.1mm | *ASTM D7414 | >25 | **21.7** | 20.3 | 19.0 |
| Base Number (BN) | mg KOH/g | ASTM D2896 | 8.5 | **6.6** | 6.5 | 9.0 |
| Visc @ 100°C | cSt | ASTM D445 | 14.4 | **14.4** | 14.4 | 13.9 |

Base Number




Viscosity @ 100°C




Ferrous Alloys




Non-ferrous Metals




Viscosity @ 100°C




Base Number




Certificate L2367

| | | | |
|---|---|---|---|
| **Laboratory** | : WearCheck USA - 501 Madison Ave., Cary, NC 27513 | | |
| **Sample No.** | : IL06055297 | **Recieved** | : 09 Jan 2024 |
| **Lab Number** | : 06055297 | **Diagnosed** | : 10 Jan 2024 |
| **Unique Number** | : 10821246 | **Diagnostician** | : Wes Davis |
| **Test Package** | : FLEET | | |

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**RUSH TRUCK LEASING - CINCINNATI IDEALEASE**
11777 HIGHWAY DRIVE
CINCINNATI, OH
US 45241
Contact: ROBERT BAIER
baierr@rushenterprises.com
T: (513)657-7901
F: (513)733-0537