# OIL ANALYSIS REPORT

| | |
|---|---|
| WEAR | NORMAL |
| CONTAMINATION | NORMAL |
| FLUID CONDITION | NORMAL |

Machine Id
## PETERBILT 846-4608
Component
## Diesel Engine
Fluid
## MOBIL DELVAC 1 5W40 (--- QTS)

## RECOMMENDATION

Resample at the next service interval to monitor.

## WEAR

All component wear rates are normal.

## CONTAMINATION

There is no indication of any contamination in the oil.

## FLUID CONDITION

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

| Test | UOM | Method | Limit/Abn | Current | History1 | History2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | RPL0017579 | RPL0016382 | RPL0014981 |
| Sample Date | | Client Info | | 24 Jan 2024 | 11 Nov 2023 | 31 Aug 2023 |
| Machine Age | mls | Client Info | | 229282 | 217104 | 206172 |
| Oil Age | mls | Client Info | | 12178 | 26584 | 15652 |
| Filter Age | mls | Client Info | | 12178 | 26584 | 15652 |
| Oil Changed | | Client Info | | Not Changd | Not Changd | Not Changd |
| Filter Changed | | Client Info | | Not Changd | Not Changd | Not Changd |
| Sample Status | | | | NORMAL | NORMAL | NORMAL |
| Iron | ppm | ASTM D5185m | >110 | 7 | 18 | 10 |
| Chromium | ppm | ASTM D5185m | >4 | 0 | 0 | 0 |
| Nickel | ppm | ASTM D5185m | >2 | <1 | <1 | <1 |
| Titanium | ppm | ASTM D5185m | | <1 | 0 | 0 |
| Silver | ppm | ASTM D5185m | >2 | 0 | <1 | 0 |
| Aluminum | ppm | ASTM D5185m | >25 | 2 | 4 | 1 |
| Lead | ppm | ASTM D5185m | >45 | <1 | <1 | 0 |
| Copper | ppm | ASTM D5185m | >85 | 4 | 10 | 6 |
| Tin | ppm | ASTM D5185m | >4 | <1 | 2 | <1 |
| Vanadium | ppm | ASTM D5185m | | 0 | <1 | 0 |
| White Metal | scalar | *Visual | NONE | NONE | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | NONE | NONE | NONE |
| Silicon | ppm | ASTM D5185m | >30 | 5 | 12 | 13 |
| Potassium | ppm | ASTM D5185m | >20 | 6 | 11 | 10 |
| Fuel | | WC Method | >5 | <1.0 | <1.0 | <1.0 |
| Water | | WC Method | >0.2 | NEG | NEG | NEG |
| Glycol | | WC Method | | NEG | NEG | NEG |
| Soot % | % | *ASTM D7844 | >3 | 0.2 | 0.3 | 0.1 |
| Nitration | Abs/cm | *ASTM D7624 | >20 | 8.4 | 9.6 | 8.3 |
| Sulfation | Abs/.1mm | *ASTM D7415 | >30 | 20.3 | 22.2 | 18.9 |
| Silt | scalar | *Visual | NONE | NONE | NONE | NONE |
| Debris | scalar | *Visual | NONE | NONE | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | NONE | NONE | NONE |
| Appearance | scalar | *Visual | NORML | NORML | NORML | NORML |
| Odor | scalar | *Visual | NORML | NORML | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.2 | NEG | NEG | NEG |
| Sodium | ppm | ASTM D5185m | | 0 | 12 | 14 |
| Boron | ppm | ASTM D5185m | 291 | 4 | 30 | 90 |
| Barium | ppm | ASTM D5185m | 0.0 | <1 | <1 | 0 |
| Molybdenum | ppm | ASTM D5185m | 8.0 | 54 | 24 | 19 |
| Manganese | ppm | ASTM D5185m | | <1 | 1 | 1 |
| Magnesium | ppm | ASTM D5185m | 624 | 895 | 828 | 808 |
| Calcium | ppm | ASTM D5185m | 2158 | 1103 | 1282 | 1342 |
| Phosphorus | ppm | ASTM D5185m | 1132 | 987 | 714 | 783 |
| Zinc | ppm | ASTM D5185m | 1300 | 1140 | 932 | 916 |
| Sulfur | ppm | ASTM D5185m | 3616 | 3336 | 2808 | 3816 |
| Oxidation | Abs/.1mm | *ASTM D7414 | >25 | 16.8 | 18.8 | 14.1 |
| Base Number (BN) | mg KOH/g | ASTM D2896 | 11.0 | 8.1 | 6.3 | 8.3 |
| Visc @ 100°C | cSt | ASTM D445 | 15.0 | 13.6 | 14.3 | 13.8 |

Base Number




Viscosity @ 100°C




Ferrous Alloys




Non-ferrous Metals




Viscosity @ 100°C




Base Number




Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : RPL0017579
**Lab Number** : 06083360
**Unique Number** : 10870805
**Test Package** : FLEET

**Received** : 08 Feb 2024
**Tested** : 08 Feb 2024
**Diagnosed** : 08 Feb 2024 - Wes Davis

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**RTL PACLEASE - 7006 - Pico Rivera**
7837 Telegraph Rd
Pico Rivera, CA
US 90660
Contact: Rudy Trevizo
TrevizoR@RushEnterprises.Com
T:
F:

Report Id: PAC7006 [WUSCAR] 06083360 (Generated: 02/08/2024 20:50:40) Rev: 1

Submitted By: TECHNICIAN ACCOUNT