MOB II WEAR CHECK

OIL ANALYSIS REPORT

WEAR	NORMAL
CONTAMINATION	ATTENTION
FLUID CONDITION	NORMAL

Machine Id
27267
Component
Diesel Engine
Fluid
{not provided} (--- GAL)

RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

WEAR

All component wear rates are normal.

CONTAMINATION

There is a moderate amount of particulates present in the oil.

FLUID CONDITION

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		KL0012144	KL0012112	KL0011940
Sample Date		Client Info		02 Feb 2024	31 Oct 2023	27 Jul 2023
Machine Age	mls	Client Info		59794	59339	56390
Oil Age	mls	Client Info		59339	0	0
Filter Age	mls	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Filter Changed		Client Info		N/A	N/A	N/A
Sample Status				ATTENTION	NORMAL	ATTENTION
Iron	ppm	ASTM D5185m	>100	25	15	61
Chromium	ppm	ASTM D5185m	>20	<1	<1	2
Nickel	ppm	ASTM D5185m	>4	<1	0	0
Titanium	ppm	ASTM D5185m		<1	<1	<1
Silver	ppm	ASTM D5185m	>3	0	0	0
Aluminum	ppm	ASTM D5185m	>20	5	4	14
Lead	ppm	ASTM D5185m	>40	0	<1	0
Copper	ppm	ASTM D5185m	>330	<1	<1	2
Tin	ppm	ASTM D5185m	>15	<1	0	<1
Vanadium	ppm	ASTM D5185m		0	<1	0
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Silicon	ppm	ASTM D5185m	>25	6	5	12
Potassium	ppm	ASTM D5185m	>20	6	8	23
Fuel		WC Method	>5	<1.0	<1.0	<1.0
Water		WC Method	>0.2	NEG	NEG	NEG
Glycol		WC Method		NEG	NEG	NEG
Soot %	%	*ASTM D7844	>3	0.6	0.5	1.4
Nitration	Abs/cm	*ASTM D7624	>20	8.5	8.1	14.1
Sulfation	Abs/.1mm	*ASTM D7415	>30	21.9	21.7	31.3
Particles >4µm		ASTM D7647		10683	1044	10875
Particles >6µm		ASTM D7647	>5000	▲ 5820	569	▲ 5924
Particles >14µm		ASTM D7647	>640	▲ 990	97	▲ 1008
Particles >21µm		ASTM D7647	>160	▲ 334	33	▲ 340
Particles >38µm		ASTM D7647	>40	▲ 52	5	▲ 52
Particles >71µm		ASTM D7647	>10	5	1	5
Oil Cleanliness		ISO 4406 (c)	>19/16	▲ 20/17	16/14	▲ 20/17
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Sodium	ppm	ASTM D5185m		3	4	7
Boron	ppm	ASTM D5185m		48	93	20
Barium	ppm	ASTM D5185m		5	0	0
Molybdenum	ppm	ASTM D5185m		52	61	66
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		875	1153	1120
Calcium	ppm	ASTM D5185m		768	1001	1082
Phosphorus	ppm	ASTM D5185m		826	1159	1085
Zinc	ppm	ASTM D5185m		1041	1364	1356
Sulfur	ppm	ASTM D5185m		2934	3674	4038
Oxidation	Abs/.1mm	*ASTM D7414	>25	18.9	18.6	32.0
Base Number (BN)	mg KOH/g	ASTM D2896		10.82	11.31	7.06
Visc @ 100°C	cSt	ASTM D445		14.0	14.2	13.8

Particle Count



Particle Trend



Base Number



Viscosity @ 100°C



Ferrous Alloys



Non-ferrous Metals



Viscosity @ 100°C



Particle Count



Base Number



Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : KL0012144
Lab Number : 06089616
Unique Number : 10877061
Test Package : MOB 2 (Additional Tests: PrtCount)

Received : 14 Feb 2024
Tested : 15 Feb 2024
Diagnosed : 16 Feb 2024 - Sean Felton

Certificate L2367

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

CITY & COUNTY HONOLULU
99-999 IWAENA RD
AIEA, HI
US 96701
Contact: CLYDE OMIJA
comija@honolulu.gov
T: (575)623-9952
F:

Report Id: CITAIE [WUSCAR] 06089616 (Generated: 02/16/2024 12:11:44) Rev: 1

Submitted By: Mike Richardson