IND II

Hilcorp Alaska, LLC

OIL ANALYSIS REPORT

WEAR	NORMAL
CONTAMINATION	ABNORMAL
FLUID CONDITION	NORMAL

Area
IRIG [6697448]
Machine Id
ACCUMULATOR RESERVOIR IRIG-ACU-ACUM-2301 ACCUMULATOR RESERVOIR
Component
Hydraulic System
Fluid
MOBIL DTE 10 EXCEL 32 (350 GAL)

RECOMMENDATION

We recommend you service the filters on this component. We recommend an early resample to monitor this condition.

WEAR

All component wear rates are normal.

CONTAMINATION

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The system cleanliness is above the acceptable limit for the target ISO 4406 cleanliness code.

FLUID CONDITION

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		HLC0003034	HLC0003041	HLC0003039
Sample Date		Client Info		16 Mar 2024	08 Feb 2024	01 Jan 2024
Machine Age	days	Client Info		0	0	0
Oil Age	days	Client Info		0	0	0
Filter Age	days	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Filter Changed		Client Info		N/A	N/A	Changed
Sample Status				ABNORMAL	ATTENTION	ABNORMAL
Iron	ppm	ASTM D5185m	>20	6	4	3
Chromium	ppm	ASTM D5185m	>20	<1	0	0
Nickel	ppm	ASTM D5185m	>20	<1	0	0
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>20	1	0	0
Lead	ppm	ASTM D5185m	>20	1	0	0
Copper	ppm	ASTM D5185m	>20	3	3	2
Tin	ppm	ASTM D5185m	>20	1	0	0
Vanadium	ppm	ASTM D5185m		<1	0	0
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Silicon	ppm	ASTM D5185m	>15	<1	1	<1
Potassium	ppm	ASTM D5185m	>20	2	0	2
Water		WC Method	>0.05	NEG	NEG	NEG
Particles >4µm		ASTM D7647	>1300	▲ 7155	● 1329	▲ 4875
Particles >6µm		ASTM D7647	>320	● 478	113	● 322
Particles >14µm		ASTM D7647	>80	18	8	17
Particles >21µm		ASTM D7647	>20	5	2	6
Particles >38µm		ASTM D7647	>4	0	0	0
Particles >71µm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>17/15/13	▲ 20/16/11	● 18/14/10	▲ 19/16/11
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Sodium	ppm	ASTM D5185m		3	6	6
Boron	ppm	ASTM D5185m		1	0	0
Barium	ppm	ASTM D5185m		<1	<1	0
Molybdenum	ppm	ASTM D5185m		<1	0	0
Manganese	ppm	ASTM D5185m		<1	0	<1
Magnesium	ppm	ASTM D5185m		1	0	0
Calcium	ppm	ASTM D5185m	120	101	89	74
Phosphorus	ppm	ASTM D5185m	475	462	418	392
Zinc	ppm	ASTM D5185m		45	35	12
Sulfur	ppm	ASTM D5185m	1275	1832	1200	1012
Acid Number (AN)	mg KOH/g	ASTM D8045		0.091	0.137	0.11
Visc @ 40°C	cSt	ASTM D445	32	31.0	31.1	31.1

Particle Count



Particle Trend



Acid Number



Viscosity @ 40°C



Ferrous Alloys



Non-ferrous Metals



Viscosity @ 40°C



Particle Count



Acid Number



Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : HLC0003034
Lab Number : 06147283
Unique Number : 10977361
Test Package : IND 2

Received : 12 Apr 2024
Tested : 15 Apr 2024
Diagnosed : 15 Apr 2024 - Wes Davis

Certificate L2367

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

HILCORP EXPLORATION ALASKA - MILNE POINT
1000 MILNE POINT RD
PRUDOE BAY, AK
US 99734
Contact: Evan Reilly
evan.reilly@hilcorp.com
T: (907)670-3231
F: x: