MOB

James River Equipment

OIL ANALYSIS REPORT

| | |
|---|---|
| WEAR | NORMAL |
| CONTAMINATION | ABNORMAL |
| FLUID CONDITION | NORMAL |

Area
**[DARREL RAINS]**
Machine Id
**JOHN DEERE 3025E C276842 (S/N 1LV3025EPJJ125676)**
Component
**Diesel Engine**
Fluid
**{not provided} (--- GAL)**

## RECOMMENDATION

The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample.

## WEAR

Metal levels are typical for a new component breaking in.

## CONTAMINATION

There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.

## FLUID CONDITION

The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.

| Test | UOM | Method | Limit/Abn | Current | History1 | History2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **JR0191498** | JR0144364 | --- |
| Sample Date | | Client Info | | **22 Apr 2024** | 02 Feb 2023 | --- |
| Machine Age | hrs | Client Info | | **147** | 147 | --- |
| Oil Age | hrs | Client Info | | **0** | 0 | --- |
| Filter Age | hrs | Client Info | | **0** | 0 | --- |
| Oil Changed | | Client Info | | **Changed** | Changed | --- |
| Filter Changed | | Client Info | | **Changed** | Changed | --- |
| Sample Status | | | | **ABNORMAL** | ABNORMAL | --- |
| Iron | ppm | ASTM D5185m | >51 | **9** | 7 | --- |
| Chromium | ppm | ASTM D5185m | >11 | **<1** | <1 | --- |
| Nickel | ppm | ASTM D5185m | >5 | **<1** | 0 | --- |
| Titanium | ppm | ASTM D5185m | | **<1** | <1 | --- |
| Silver | ppm | ASTM D5185m | >3 | **0** | 0 | --- |
| Aluminum | ppm | ASTM D5185m | >31 | **5** | 2 | --- |
| Lead | ppm | ASTM D5185m | >26 | **1** | 1 | --- |
| Copper | ppm | ASTM D5185m | >26 | **6** | 4 | --- |
| Tin | ppm | ASTM D5185m | >4 | **<1** | 0 | --- |
| Vanadium | ppm | ASTM D5185m | | **<1** | 0 | --- |
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | --- |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | --- |
| Silicon | ppm | ASTM D5185m | >22 | **21** | 11 | --- |
| Potassium | ppm | ASTM D5185m | >20 | **2** | 3 | --- |
| Fuel | % | ASTM D3524 | >2.1 | ▲ **2.9** | ▲ 5.6 | --- |
| Water | | WC Method | >0.21 | **NEG** | NEG | --- |
| Glycol | | WC Method | | **NEG** | NEG | --- |
| Soot % | % | *ASTM D7844 | >3 | **0.1** | 0.1 | --- |
| Nitration | Abs/cm | *ASTM D7624 | >20 | **6.8** | 7.0 | --- |
| Sulfation | Abs/.1mm | *ASTM D7415 | >30 | **18.9** | 19.3 | --- |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | --- |
| Debris | scalar | *Visual | NONE | **NONE** | NONE | --- |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | --- |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | --- |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | --- |
| Emulsified Water | scalar | *Visual | >0.21 | **NEG** | NEG | --- |
| Sodium | ppm | ASTM D5185m | >31 | **3** | 2 | --- |
| Boron | ppm | ASTM D5185m | | **297** | 276 | --- |
| Barium | ppm | ASTM D5185m | | **0** | 0 | --- |
| Molybdenum | ppm | ASTM D5185m | | **233** | 232 | --- |
| Manganese | ppm | ASTM D5185m | | **<1** | 1 | --- |
| Magnesium | ppm | ASTM D5185m | | **781** | 766 | --- |
| Calcium | ppm | ASTM D5185m | | **1372** | 1439 | --- |
| Phosphorus | ppm | ASTM D5185m | | **952** | 804 | --- |
| Zinc | ppm | ASTM D5185m | | **1038** | 994 | --- |
| Sulfur | ppm | ASTM D5185m | | **3539** | 3249 | --- |
| Oxidation | Abs/.1mm | *ASTM D7414 | >25 | **14.2** | 14.3 | --- |
| Base Number (BN) | mg KOH/g | ASTM D2896 | | **10.3** | 10.4 | --- |
| Visc @ 100°C | cSt | ASTM D445 | | **12.5** | ▲ 12.2 | --- |

Fuel Dilution




FT-IR (Direct Trend)




Base Number




Viscosity @ 100°C




Iron (ppm)




Lead (ppm)




Aluminum (ppm)




Chromium (ppm)




Copper (ppm)




Silicon (ppm)




Viscosity @ 100°C




Base Number




Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : JR0191498 **Received** : 25 Apr 2024
**Lab Number** : 06161085 **Tested** : 29 Apr 2024
**Unique Number** : 10996508 **Diagnosed** : 29 Apr 2024 - Wes Davis
**Test Package** : MOBCE ( Additional Tests: PercentFuel, TBN )

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**JRE - ROCK HILL**
380 ANDERSON ROAD
ROCK HILL, SC
US 29730
Contact: EVAN THOMAS
evan.thomas@jamesriverequipment.com
T:
F: (803)325-1506