OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL

Machine Id
6024
Component
Rear Diesel Engine
Fluid
PETRO CANADA DURON HP 15W40 (18 LTR)

DIAGNOSIS

Recommendation
Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition.

Wear
Les taux d'usure de tous les composants sont normaux.

Contamination
Il n`y a aucun indice de contamination dans l'huile.

Fluid Condition
Le résultat pour le BN indique que la réserve d'alcalinité est acceptable pour l'huile. L'état de l'huile permet d'en prolonger l'utilisation.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**PC0073965**	PC0073533	PC0062803
Sample Date		Client Info		**12 Jun 2023**	01 May 2023	07 Nov 2022
Machine Age	kms	Client Info		**0**	0	0
Oil Age	kms	Client Info		**6905**	8949	7386
Oil Changed		Client Info		**Changed**	Changed	Changed
Sample Status				**NORMAL**	ABNORMAL	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Fuel		WC Method	>3.0	**<1.0**	<1.0	<1.0
Glycol		WC Method		**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>130	**25**	57	6
Chromium	ppm	ASTM D5185(m)	>10	**4**	▲ 11	0
Nickel	ppm	ASTM D5185(m)	>4	**<1**	<1	<1
Titanium	ppm	ASTM D5185(m)	>2	**<1**	<1	0
Silver	ppm	ASTM D5185(m)	>2	**0**	0	0
Aluminum	ppm	ASTM D5185(m)	>20	**4**	▲ 12	2
Lead	ppm	ASTM D5185(m)	>20	**0**	2	0
Copper	ppm	ASTM D5185(m)	>125	**14**	70	0
Tin	ppm	ASTM D5185(m)	>4	**<1**	3	0
Antimony	ppm	ASTM D5185(m)		**0**	0	<1
Vanadium	ppm	ASTM D5185(m)		**0**	0	0
Beryllium	ppm	ASTM D5185(m)		**0**	0	0
Cadmium	ppm	ASTM D5185(m)		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	**2**	4	2
Barium	ppm	ASTM D5185(m)	0	**0**	<1	0
Molybdenum	ppm	ASTM D5185(m)	60	**59**	58	59
Manganese	ppm	ASTM D5185(m)	0	**<1**	2	<1
Magnesium	ppm	ASTM D5185(m)	1010	**987**	921	970
Calcium	ppm	ASTM D5185(m)	1070	**1053**	1100	1074
Phosphorus	ppm	ASTM D5185(m)	1150	**1074**	1041	1090
Zinc	ppm	ASTM D5185(m)	1270	**1220**	1186	1179
Sulfur	ppm	ASTM D5185(m)	2060	**2572**	2395	2682
Lithium	ppm	ASTM D5185(m)		**<1**	<1	<1

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	**11**	▲ 30	2
Sodium	ppm	ASTM D5185(m)		**5**	23	2
Potassium	ppm	ASTM D5185(m)	>20	**<1**	4	<1

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>6	**0.3**	0.5	0
Nitration	Abs/cm	ASTM D7624*	>20	**7.0**	8.7	5.6
Sulfation	Abs/.1mm	ASTM D7415*	>30	**19.6**	20.7	19.5

OIL ANALYSIS REPORT

Viscosity @ 40°C



Viscosity @ 100°C



Viscosity @ 40°C



FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	**14.7**	16.0	14.2
Base Number (BN)	mg KOH/g	ASTM D2896*	9.8	**9.48**	8.72	9.09

VISUAL		method	limit/base	current	history1	history2
Emulsified Water	scalar	Visual*	>0.2	**NEG**	NEG	NEG
Free Water	scalar	Visual*		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	118.2	**107**	104	107
Visc @ 100°C	cSt	ASTM D7279(m)	15.6	**14.5**	14.2	14.7
Viscosity Index (VI)	Scale	ASTM D2270*	139	**139**	139	141

GRAPHS

Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



Base Number



CALA
ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : PC0073965 **Received** : 18 Jul 2023
Lab Number : 02570537 **Diagnosed** : 19 Jul 2023
Unique Number : 5607583 **Diagnostician** : Wes Davis
Test Package : MOB 2 (Additional Tests: KV40, VI)

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

TRANSDEV ST-JEAN
720 TROTTER
ST-JEAN-SUR-RICHELIEU, QC
CA J3B 8T2
Contact: Eric Breton
eric.breton@transdev.com
T:
F: