# OIL ANALYSIS REPORT

Sample Rating Trend




NORMAL

Machine Id
**158613**
Component
**Unknown Component**
Fluid
**AW HYDRAULIC OIL ISO 46 (--- GAL)**

## DIAGNOSIS

**Recommendation**
Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Please specify the brand, type, and viscosity of the oil on your next sample.

**Wear**
All component wear rates are normal.

**Contamination**
The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable.

**Fluid Condition**
The AN level is acceptable for this fluid. The condition of the sample is suitable for further service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **PC0069912** | --- | --- |
| Sample Date | | Client Info | | **23 Aug 2023** | --- | --- |
| Machine Age | hrs | Client Info | | **0** | --- | --- |
| Oil Age | hrs | Client Info | | **0** | --- | --- |
| Oil Changed | | Client Info | | **N/A** | --- | --- |
| Sample Status | | | | **NORMAL** | --- | --- |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| PQ | | ASTM D8184* | | **0** | --- | --- |
| Iron | ppm | ASTM D5185(m) | | **3** | --- | --- |
| Chromium | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Nickel | ppm | ASTM D5185(m) | | **<1** | --- | --- |
| Titanium | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Silver | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Aluminum | ppm | ASTM D5185(m) | | **<1** | --- | --- |
| Lead | ppm | ASTM D5185(m) | | **4** | --- | --- |
| Copper | ppm | ASTM D5185(m) | | **2** | --- | --- |
| Tin | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Antimony | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Vanadium | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Beryllium | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Cadmium | ppm | ASTM D5185(m) | | **0** | --- | --- |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185(m) | 5 | **<1** | --- | --- |
| Barium | ppm | ASTM D5185(m) | 5 | **<1** | --- | --- |
| Molybdenum | ppm | ASTM D5185(m) | 5 | **0** | --- | --- |
| Manganese | ppm | ASTM D5185(m) | | **1** | --- | --- |
| Magnesium | ppm | ASTM D5185(m) | 25 | **1** | --- | --- |
| Calcium | ppm | ASTM D5185(m) | 200 | **42** | --- | --- |
| Phosphorus | ppm | ASTM D5185(m) | 300 | **350** | --- | --- |
| Zinc | ppm | ASTM D5185(m) | 370 | **429** | --- | --- |
| Sulfur | ppm | ASTM D5185(m) | 2500 | **1911** | --- | --- |
| Lithium | ppm | ASTM D5185(m) | | **<1** | --- | --- |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185(m) | | **<1** | --- | --- |
| Sodium | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Potassium | ppm | ASTM D5185(m) | >20 | **<1** | --- | --- |

| FLUID CLEANLINESS | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Particles >4µm | ASTM D7647 | >5000 | **502** | --- | --- |
| Particles >6µm | ASTM D7647 | >1300 | **74** | --- | --- |
| Particles >14µm | ASTM D7647 | >160 | **5** | --- | --- |
| Particles >21µm | ASTM D7647 | >40 | **1** | --- | --- |
| Particles >38µm | ASTM D7647 | >10 | **0** | --- | --- |
| Particles >71µm | ASTM D7647 | >3 | **0** | --- | --- |
| Oil Cleanliness | ISO 4406 (c) | >19/17/14 | **16/13/10** | --- | --- |

# OIL ANALYSIS REPORT
















| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Acid Number (AN) | mg KOH/g | ASTM D974* | 0.57 | **0.45** | --- | --- |

| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | Visual* | NONE | **NONE** | --- | --- |
| Yellow Metal | scalar | Visual* | NONE | **NONE** | --- | --- |
| Precipitate | scalar | Visual* | NONE | **NONE** | --- | --- |
| Silt | scalar | Visual* | NONE | **NONE** | --- | --- |
| Debris | scalar | Visual* | NONE | **NONE** | --- | --- |
| Sand/Dirt | scalar | Visual* | NONE | **NONE** | --- | --- |
| Appearance | scalar | Visual* | NORML | **NORML** | --- | --- |
| Odor | scalar | Visual* | NORML | **NORML** | --- | --- |
| Emulsified Water | scalar | Visual* | | **NEG** | --- | --- |
| Free Water | scalar | Visual* | | **NEG** | --- | --- |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D7279(m) | 46 | **45.5** | --- | --- |
| Visc @ 100°C | cSt | ASTM D7279(m) | 6.7 | **6.9** | --- | --- |
| Viscosity Index (VI) | Scale | ASTM D2270* | 97 | **107** | --- | --- |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | |  | *no image* | *no image* |
| Bottom | | |  | *no image* | *no image* |

## GRAPHS














ISO 17025:2017 Accredited Laboratory

**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
**Sample No.** : PC0069912 **Received** : 30 Aug 2023
**Lab Number** : 02579521 **Diagnosed** : 01 Sep 2023
**Unique Number** : 5632581 **Diagnostician** : Kevin Marson
**Test Package** : IND 2 ( Additional Tests: KV100, PQ, PrtCount, VI )

*To discuss this sample report, contact Customer Service at 1-800-268-2131.*
*Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.*
*Validity of results and interpretation are based on the sample and information as supplied.*

**Dryden Fibre**
Box 3001, 1 Duke Street
Dryden, ON
CA P8N 2Z7
Contact: Yvon St. Laurent
yvon.stlaurent@domtar.com
T: (807)223-9838
F: (807)223-9176