OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL

Machine Id
819000
Component
Transmission (Auto)
Fluid
PETRO CANADA DuraDrive HD Synthetic 668 (--- GAL)

DIAGNOSIS

Recommendation
Resample at the next service interval to monitor.

Wear
All component wear rates are normal.

Contamination
There is no indication of any contamination in the fluid.

Fluid Condition
The condition of the fluid is acceptable for the time in service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0084158**	GFL0063612	GFL0039309
Sample Date		Client Info		**15 Aug 2023**	16 Jan 2023	27 Dec 2021
Machine Age	hrs	Client Info		**10392**	8787	6038
Oil Age	hrs	Client Info		**0**	1200	3000
Oil Changed		Client Info		**N/A**	N/A	Changed
Sample Status				**NORMAL**	NORMAL	NORMAL

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>160	**51**	93	102
Chromium	ppm	ASTM D5185(m)	>5	**<1**	0	<1
Nickel	ppm	ASTM D5185(m)	>5	**0**	<1	<1
Titanium	ppm	ASTM D5185(m)		**<1**	<1	0
Silver	ppm	ASTM D5185(m)	>5	**0**	0	<1
Aluminum	ppm	ASTM D5185(m)	>50	**14**	19	19
Lead	ppm	ASTM D5185(m)	>50	**14**	27	29
Copper	ppm	ASTM D5185(m)	>225	**4**	15	19
Tin	ppm	ASTM D5185(m)	>10	**<1**	1	2
Antimony	ppm	ASTM D5185(m)		**0**	<1	<1
Vanadium	ppm	ASTM D5185(m)		**0**	0	0
Beryllium	ppm	ASTM D5185(m)		**0**	0	0
Cadmium	ppm	ASTM D5185(m)		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	78	**74**	94	184
Barium	ppm	ASTM D5185(m)		**0**	0	0
Molybdenum	ppm	ASTM D5185(m)	0	**<1**	0	<1
Manganese	ppm	ASTM D5185(m)		**<1**	<1	1
Magnesium	ppm	ASTM D5185(m)	0	**8**	11	9
Calcium	ppm	ASTM D5185(m)	113	**130**	133	142
Phosphorus	ppm	ASTM D5185(m)	222	**250**	298	492
Zinc	ppm	ASTM D5185(m)		**19**	20	26
Sulfur	ppm	ASTM D5185(m)	1326	**1425**	1529	2375
Lithium	ppm	ASTM D5185(m)		**<1**	<1	<1

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>20	**9**	10	10
Sodium	ppm	ASTM D5185(m)		**6**	10	11
Potassium	ppm	ASTM D5185(m)	>20	**2**	2	2

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	Visual*	NONE	**NONE**	NONE	NONE
Precipitate	scalar	Visual*	NONE	**NONE**	NONE	NONE
Silt	scalar	Visual*	NONE	**VLITE**	NONE	LIGHT
Debris	scalar	Visual*	NONE	**VLITE**	NONE	VLITE
Sand/Dirt	scalar	Visual*	NONE	**NONE**	NONE	NONE
Appearance	scalar	Visual*	NORML	**NORML**	NORML	NORML
Odor	scalar	Visual*	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	Visual*	>0.1	**NEG**	NEG	NEG
Free Water	scalar	Visual*		**NEG**	NEG	NEG

OIL ANALYSIS REPORT



FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	34.8	**34.1**	33.5	35.7

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color					
Bottom					



GRAPHS

















ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 **GFL Environmental - 573 - Vancouver Hauling**
Sample No. : GFL0084158 **Received** : 08 Sep 2023
Lab Number : 02581184 **Diagnosed** : 08 Sep 2023
Unique Number : 5642249 **Diagnostician** : Wes Davis
Test Package : MOB 1

70 Golden Drive,
Coquitlam, BC
CA V3K 6B5
Contact: Catia Klagenberg Alves
cklagenbergalves@gflenv.com
T:
F:

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.