PROBLEM SUMMARY

Sample Rating Trend

WEAR

Machine Id
SILO #28
Component
Gearbox
Fluid
PETRO CANADA ENDURATEX EP 220 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS

Sample Status				**ABNORMAL**	---	---
Iron	ppm	ASTM D5185(m)	>200	▲ **350**	---	---

Customer Id: TAVTAV
Sample No.: PC0077114
Lab Number: 02585660
Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:
Kevin Marson +1 (289)291-4644 x4644
Kevin.Marson@wearcheck.com

To change component or sample information:
Gloria Gonzalez +1 (289)291-4643 x4643
gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Fluid	---	---	?	We recommend that you drain the oil from the component if this has not already been done.
Resample	---	---	?	We recommend an early resample to monitor this condition.
Information Required	---	---	?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

HISTORICAL DIAGNOSIS

OIL ANALYSIS REPORT

Sample Rating Trend

WEAR

Machine Id
SILO #28
Component
Gearbox
Fluid
PETRO CANADA ENDURATEX EP 220 (--- GAL)

DIAGNOSIS

Recommendation

We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear

Iron ppm levels are abnormal. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion.

Contamination

There is no indication of any contamination in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**PC0077114**	---	---
Sample Date		Client Info		**11 Sep 2023**	---	---
Machine Age	hrs	Client Info		**0**	---	---
Oil Age	hrs	Client Info		**0**	---	---
Oil Changed		Client Info		**N/A**	---	---
Sample Status				**ABNORMAL**	---	---

WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		**87**	---	---
Iron	ppm	ASTM D5185(m)	>200	▲ **350**	---	---
Chromium	ppm	ASTM D5185(m)	>15	**3**	---	---
Nickel	ppm	ASTM D5185(m)	>15	**<1**	---	---
Titanium	ppm	ASTM D5185(m)		**0**	---	---
Silver	ppm	ASTM D5185(m)		**<1**	---	---
Aluminum	ppm	ASTM D5185(m)	>25	**<1**	---	---
Lead	ppm	ASTM D5185(m)	>100	**0**	---	---
Copper	ppm	ASTM D5185(m)	>200	**<1**	---	---
Tin	ppm	ASTM D5185(m)	>25	**0**	---	---
Antimony	ppm	ASTM D5185(m)	>5	**0**	---	---
Vanadium	ppm	ASTM D5185(m)		**0**	---	---
Beryllium	ppm	ASTM D5185(m)		**0**	---	---
Cadmium	ppm	ASTM D5185(m)		**0**	---	---

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	60	**40**	---	---
Barium	ppm	ASTM D5185(m)	0	**0**	---	---
Molybdenum	ppm	ASTM D5185(m)	0	**0**	---	---
Manganese	ppm	ASTM D5185(m)	0	**2**	---	---
Magnesium	ppm	ASTM D5185(m)	0	**<1**	---	---
Calcium	ppm	ASTM D5185(m)	0	**10**	---	---
Phosphorus	ppm	ASTM D5185(m)	270	**251**	---	---
Zinc	ppm	ASTM D5185(m)	0	**6**	---	---
Sulfur	ppm	ASTM D5185(m)	11200	**5861**	---	---
Lithium	ppm	ASTM D5185(m)		**<1**	---	---

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>50	**6**	---	---
Sodium	ppm	ASTM D5185(m)		**<1**	---	---
Potassium	ppm	ASTM D5185(m)	>20	**0**	---	---

FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	0.40	**0.38**	---	---

OIL ANALYSIS REPORT

Viscosity @ 100°C



Acid Number



Viscosity @ 100°C



Viscosity @ 40°C



PQ



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	**NONE**	---	---
Yellow Metal	scalar	Visual*	NONE	**NONE**	---	---
Precipitate	scalar	Visual*	NONE	**NONE**	---	---
Silt	scalar	Visual*	NONE	**NONE**	---	---
Debris	scalar	Visual*	NONE	**NONE**	---	---
Sand/Dirt	scalar	Visual*	NONE	**NONE**	---	---
Appearance	scalar	Visual*	NORML	**NORML**	---	---
Odor	scalar	Visual*	NORML	**NORML**	---	---
Emulsified Water	scalar	Visual*	>0.2	**NEG**	---	---
Free Water	scalar	Visual*		**NEG**	---	---

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	220	**218**	---	---
Visc @ 100°C	cSt	ASTM D7279(m)	19.35	**19.5**	---	---
Viscosity Index (VI)	Scale	ASTM D2270*	99	**101**	---	---

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color				*no image*	*no image*
Bottom				*no image*	*no image*

GRAPHS

Ferrous Alloys



Non-ferrous Metals

Viscosity @ 40°C



PQ



Acid Number



ISO 17025:2017 Accredited Laboratory

Laboratory	: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9		
Sample No.	: PC0077114	**Received**	: 27 Sep 2023
Lab Number	: 02585660	**Diagnosed**	: 28 Sep 2023
Unique Number	: 5646725	**Diagnostician**	: Kevin Marson
Test Package	: IND 2 (Additional Tests: KV100, TAN Man, VI)		

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

SAPUTO FOODS LTD
284 HOPE STREET WEST
TAVISTOCK, ON
CA N0B 2R0
Contact: Brian Schwartzentruber
bschwartzentruber@saputo.com
T: (519)655-2337
F: (519)655-3449