OIL ANALYSIS REPORT

Sample Rating Trend



DIRT

Area
CAPLAN
Machine Id
#427150
Component
Front Diesel Engine
Fluid
CASTROL 15W40 (40 LTR)

DIAGNOSIS

Recommendation

Nous vous recommandons de vérifier le filtre à air, le système d`induction d`air et tout endroit où la saleté peut entrer dans le composant. Nous vous recommandons de vérifier la présence de particules métalliques visibles dans l`huile. Nous avons pris note que la vidange d`huile a été effectuée au moment de l`échantillonnage. Nous vous recommandons d`échantillonner de nouveau dès que possible afin de contrôler la situation.

Wear

Présence d`une faible concentration de métal visible.

Contamination

La teneur en carburant est négligeable. Il y a une légère concentration de la saleté et débris visible, présente dans l`huile.

Fluid Condition

La viscosité de l'échantillon se situe dans la portée de l'SAE 30; nous vous conseillons de vérifier. l`huile n'est plus en état de service en raison d'une usure anomale et/ou sévère.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0091128**	GFL0079113	---
Sample Date		Client Info		**21 Dec 2023**	27 May 2023	---
Machine Age	hrs	Client Info		**25794**	25235	---
Oil Age	hrs	Client Info		**21**	291	---
Oil Changed		Client Info		**Changed**	Changed	---
Sample Status				**ABNORMAL**	NORMAL	---

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	NEG	---
Glycol		WC Method		**NEG**	NEG	---

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>85	**3**	8	---
Chromium	ppm	ASTM D5185(m)	>5	**0**	0	---
Nickel	ppm	ASTM D5185(m)	>4	**<1**	0	---
Titanium	ppm	ASTM D5185(m)	>2	**0**	<1	---
Silver	ppm	ASTM D5185(m)	>2	**0**	0	---
Aluminum	ppm	ASTM D5185(m)	>40	**2**	4	---
Lead	ppm	ASTM D5185(m)	>10	**<1**	<1	---
Copper	ppm	ASTM D5185(m)	>100	**<1**	<1	---
Tin	ppm	ASTM D5185(m)	>4	**0**	0	---
Antimony	ppm	ASTM D5185(m)		**0**	<1	---
Vanadium	ppm	ASTM D5185(m)		**0**	0	---
Beryllium	ppm	ASTM D5185(m)		**0**	0	---
Cadmium	ppm	ASTM D5185(m)		**0**	0	---

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		**17**	76	---
Barium	ppm	ASTM D5185(m)		**0**	0	---
Molybdenum	ppm	ASTM D5185(m)		**60**	72	---
Manganese	ppm	ASTM D5185(m)		**0**	<1	---
Magnesium	ppm	ASTM D5185(m)		**827**	193	---
Calcium	ppm	ASTM D5185(m)		**1177**	2134	---
Phosphorus	ppm	ASTM D5185(m)		**992**	1040	---
Zinc	ppm	ASTM D5185(m)		**1139**	1076	---
Sulfur	ppm	ASTM D5185(m)		**2786**	2956	---
Lithium	ppm	ASTM D5185(m)		**<1**	<1	---

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	**4**	4	---
Sodium	ppm	ASTM D5185(m)	>406	**1**	2	---
Potassium	ppm	ASTM D5185(m)	>20	**<1**	2	---
Fuel	%	ASTM D7593*	>5	**0.6**	<1.0	---

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>3	**0**	0.3	---
Nitration	Abs/cm	ASTM D7624*	>20	**5.0**	7.8	---
Sulfation	Abs/.1mm	ASTM D7415*	>30	**17.7**	19.0	---

OIL ANALYSIS REPORT





FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	**12.9**	12.9	---

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	▲ **LIGHT**	NONE	---
Yellow Metal	scalar	Visual*	NONE	**NONE**	NONE	---
Precipitate	scalar	Visual*	NONE	**NONE**	NONE	---
Silt	scalar	Visual*	NONE	**NONE**	NONE	---
Debris	scalar	Visual*	NONE	**NONE**	NONE	---
Sand/Dirt	scalar	Visual*	NONE	▲ **LIGHT**	NONE	---
Appearance	scalar	Visual*	NORML	**NORML**	NORML	---
Odor	scalar	Visual*	NORML	**NORML**	NORML	---
Emulsified Water	scalar	Visual*	>0.2	**NEG**	NEG	---
Free Water	scalar	Visual*		**NEG**	NEG	---

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D7279(m)		▲ **11.6**	13.3	---

GRAPHS

















ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : GFL0091128 **Recieved** : 27 Dec 2023
Lab Number : 02605199 **Diagnosed** : 28 Dec 2023
Unique Number : 5698284 **Diagnostician** : Kevin Marson
Test Package : MOB 1 (Additional Tests: BottomAnalysis, FILTERPATCH, FuelDilution, PercentFuel, Visual)

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

Matrec - 791 - Rimouski
350 Avenue de L`Industrie
Rimouski, QC
CA G5M 1W4
Contact: Vincent Maltais
info@foretsstar.com
T: 4(18)388-2626
F: (418)388-2038