OIL ANALYSIS REPORT

Sample Rating Trend



FUEL

Machine Id
5217
Component
Gasoline Engine
Fluid
SAE 5W30 (--- GAL)

DIAGNOSIS

Recommendation

Nous avons pris note que la vidange d`huile a été effectuée au moment de l`échantillonnage. Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Aucune autre mesure corrective n'est recommandée pour l'instant.

Wear

Les taux d'usure de tous les composants sont normaux.

Contamination

Légère dilution de carburant dans l'huile. Aucun autre contaminant n'a été détecté dans l'huile.

Fluid Condition

Le résultat pour le BN indique que la réserve d'alcalinité est acceptable pour l'huile. L'état de l'huile permet d'en prolonger l'utilisation.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**PC0079637**	PC0079253	PC0079176
Sample Date		Client Info		**19 Dec 2023**	21 Nov 2023	23 Oct 2023
Machine Age	kms	Client Info		**788951**	72967	67610
Oil Age	kms	Client Info		**5928**	5357	5418
Oil Changed		Client Info		**Changed**	Changed	Changed
Sample Status				**MARGINAL**	MARGINAL	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	NEG	NEG
Glycol		WC Method		**NEG**	0.0	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>150	**2**	2	3
Chromium	ppm	ASTM D5185(m)	>20	**0**	0	0
Nickel	ppm	ASTM D5185(m)	>5	**<1**	0	0
Titanium	ppm	ASTM D5185(m)		**0**	0	0
Silver	ppm	ASTM D5185(m)	>2	**0**	0	<1
Aluminum	ppm	ASTM D5185(m)	>40	**1**	1	2
Lead	ppm	ASTM D5185(m)	>50	**<1**	<1	<1
Copper	ppm	ASTM D5185(m)	>155	**<1**	<1	1
Tin	ppm	ASTM D5185(m)	>10	**0**	0	0
Antimony	ppm	ASTM D5185(m)		**0**	0	0
Vanadium	ppm	ASTM D5185(m)		**0**	0	0
Beryllium	ppm	ASTM D5185(m)		**0**	0	0
Cadmium	ppm	ASTM D5185(m)		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		**123**	123	124
Barium	ppm	ASTM D5185(m)		**0**	<1	0
Molybdenum	ppm	ASTM D5185(m)		**67**	66	70
Manganese	ppm	ASTM D5185(m)		**0**	0	0
Magnesium	ppm	ASTM D5185(m)		**464**	463	501
Calcium	ppm	ASTM D5185(m)		**1158**	1122	1168
Phosphorus	ppm	ASTM D5185(m)		**591**	581	646
Zinc	ppm	ASTM D5185(m)		**687**	704	740
Sulfur	ppm	ASTM D5185(m)		**2399**	2261	2333
Lithium	ppm	ASTM D5185(m)		**<1**	<1	<1

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>30	**12**	12	17
Sodium	ppm	ASTM D5185(m)	>400	**2**	2	2
Potassium	ppm	ASTM D5185(m)	>20	**<1**	0	0
Fuel	%	ASTM D7593*	>4.0	**2.1**	<1.0	<1.0

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*		**0**	0	0
Nitration	Abs/cm	ASTM D7624*	>20	**9.0**	9.1	8.8
Sulfation	Abs/.1mm	ASTM D7415*	>30	**18.7**	18.4	18.9

OIL ANALYSIS REPORT

Fuel Dilution



Viscosity @ 40°C



Viscosity @ 100°C



Viscosity @ 40°C



FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	**11.8**	11.7	12.3
Base Number (BN)	mg KOH/g	ASTM D2896*		**6.15**	4.40	4.93

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	**NONE**	---	NONE
Yellow Metal	scalar	Visual*	NONE	**NONE**	---	NONE
Precipitate	scalar	Visual*	NONE	**NONE**	---	NONE
Silt	scalar	Visual*	NONE	**NONE**	---	NONE
Debris	scalar	Visual*	NONE	**NONE**	---	NONE
Sand/Dirt	scalar	Visual*	NONE	**NONE**	---	VLITE
Appearance	scalar	Visual*	NORML	**NORML**	NORML	NORML
Odor	scalar	Visual*	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	Visual*	>0.2	**NEG**	NEG	NEG
Free Water	scalar	Visual*		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	60.0	**49.6**	48.5	49.9
Visc @ 100°C	cSt	ASTM D7279(m)	11.0	**9.2**	9	9.2
Viscosity Index (VI)	Scale	ASTM D2270*	177	**170**	168	168

GRAPHS

Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



Base Number



ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : PC0079637 **Received** : 28 Dec 2023
Lab Number : 02605518 **Tested** : 29 Dec 2023
Unique Number : 5698603 **Diagnosed** : 29 Dec 2023 - Wes Davis
Test Package : MOB 2 (Additional Tests: FuelDilution, KV40, PercentFuel, VI)

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

TRANSDEV ST-JEAN
720 TROTTER
ST-JEAN-SUR-RICHELIEU, QC
CA J3B 8T2
Contact: Eric Breton
eric.breton@transdev.com
T:
F: