# OIL ANALYSIS REPORT

Sample Rating Trend




NORMAL

Area
**TEAM 3**
Machine Id
**165171**
Component
**Bearing**
Fluid
**PETRO CANADA TURBOFLO R&O 220 (1 QTS)**

## DIAGNOSIS

**Recommendation**
Resample at the next service interval to monitor.

**Wear**
All component wear rates are normal.

**Contamination**
There is no indication of any contamination in the oil.

**Fluid Condition**
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **PC0077027** | PC0070420 | PC0058059 |
| Sample Date | | Client Info | | **13 Jan 2024** | 08 Aug 2023 | 17 Feb 2022 |
| Machine Age | mths | Client Info | | **0** | 0 | 0 |
| Oil Age | mths | Client Info | | **0** | 0 | 0 |
| Oil Changed | | Client Info | | **N/A** | N/A | N/A |
| Sample Status | | | | **NORMAL** | NORMAL | NORMAL |

| CONTAMINATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Water | | WC Method | >2 | **NEG** | NEG | NEG |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| PQ | | ASTM D8184* | | **0** | 0 | 0 |
| Iron | ppm | ASTM D5185(m) | >20 | **2** | <1 | 2 |
| Chromium | ppm | ASTM D5185(m) | >20 | **0** | 0 | 0 |
| Nickel | ppm | ASTM D5185(m) | >20 | **<1** | 0 | <1 |
| Titanium | ppm | ASTM D5185(m) | | **0** | 0 | 0 |
| Silver | ppm | ASTM D5185(m) | | **0** | 0 | 0 |
| Aluminum | ppm | ASTM D5185(m) | >20 | **<1** | <1 | 0 |
| Lead | ppm | ASTM D5185(m) | >20 | **0** | 0 | 4 |
| Copper | ppm | ASTM D5185(m) | >20 | **0** | 0 | <1 |
| Tin | ppm | ASTM D5185(m) | >20 | **0** | 0 | 0 |
| Antimony | ppm | ASTM D5185(m) | | **0** | 0 | 0 |
| Vanadium | ppm | ASTM D5185(m) | | **0** | 0 | 0 |
| Beryllium | ppm | ASTM D5185(m) | | **0** | 0 | 0 |
| Cadmium | ppm | ASTM D5185(m) | | **0** | 0 | 0 |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185(m) | | **<1** | <1 | <1 |
| Barium | ppm | ASTM D5185(m) | | **0** | 0 | 0 |
| Molybdenum | ppm | ASTM D5185(m) | | **0** | 0 | 0 |
| Manganese | ppm | ASTM D5185(m) | | **0** | 0 | 0 |
| Magnesium | ppm | ASTM D5185(m) | | **<1** | 0 | 0 |
| Calcium | ppm | ASTM D5185(m) | 0 | **<1** | <1 | <1 |
| Phosphorus | ppm | ASTM D5185(m) | 4 | **7** | 9 | 7 |
| Zinc | ppm | ASTM D5185(m) | 0 | **2** | 3 | 4 |
| Sulfur | ppm | ASTM D5185(m) | | **1126** | 1136 | 5965 |
| Lithium | ppm | ASTM D5185(m) | | **<1** | <1 | <1 |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185(m) | >15 | **<1** | <1 | <1 |
| Sodium | ppm | ASTM D5185(m) | | **0** | 0 | 0 |
| Potassium | ppm | ASTM D5185(m) | >20 | **<1** | <1 | <1 |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Acid Number (AN) | mg KOH/g | ASTM D974* | 0.17 | **0.14** | 0.11 | 0.31 |

# OIL ANALYSIS REPORT













| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | Visual* | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | Visual* | NONE | **NONE** | NONE | NONE |
| Precipitate | scalar | Visual* | NONE | **NONE** | NONE | NONE |
| Silt | scalar | Visual* | NONE | **NONE** | NONE | NONE |
| Debris | scalar | Visual* | NONE | **NONE** | NONE | NONE |
| Sand/Dirt | scalar | Visual* | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | Visual* | NORML | **NORML** | NORML | NORML |
| Odor | scalar | Visual* | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | Visual* | >2 | **NEG** | NEG | NEG |
| Free Water | scalar | Visual* | | **NEG** | NEG | NEG |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D7279(m) | 205.5 | **213** | 213 | 216 |
| Visc @ 100°C | cSt | ASTM D7279(m) | 18.32 | **18.9** | 18.7 | 19.0 |
| Viscosity Index (VI) | Scale | ASTM D2270* | 98 | **99** | 97 | 98 |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | | | | |
| Bottom | | | | | |



## GRAPHS
















ISO 17025:2017 Accredited Laboratory

**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
**Sample No.** : PC0077027 **Recieved** : 24 Jan 2024
**Lab Number** : 02610979 **Diagnosed** : 25 Jan 2024
**Unique Number** : 5720074 **Diagnostician** : Kevin Marson
**Test Package** : IND 2 ( Additional Tests: KV100, TAN Man, VI )

*To discuss this sample report, contact Customer Service at 1-800-268-2131.*
*Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.*
*Validity of results and interpretation are based on the sample and information as supplied.*

**Dryden Fibre**
Box 3001, 1 Duke Street
Dryden, ON
CA P8N 2Z7
Contact: Adebukola Adekanye
aadekanye@drydenfibre.ca
T: (807)223-9950
F: (807)223-9176