# OIL ANALYSIS REPORT

Sample Rating Trend




NORMAL

Machine Id
**813069**
Component
**Diesel Engine**
Fluid
**CERTIFIED SPECTRA XTREME 15W40 CK4 (--- GAL)**

## DIAGNOSIS

**Recommendation**
Resample at the next service interval to monitor.

**Wear**
Metal levels are typical for a new component breaking in.

**Contamination**
There is no indication of any contamination in the oil.

**Fluid Condition**
The condition of the oil is acceptable for the time in service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **GFL0105892** | GFL0076458 | --- |
| Sample Date | | Client Info | | **27 Mar 2024** | 04 Mar 2023 | --- |
| Machine Age | kms | Client Info | | **47080** | 976 | --- |
| Oil Age | kms | Client Info | | **0** | 465 | --- |
| Oil Changed | | Client Info | | **Changed** | Changed | --- |
| Sample Status | | | | **NORMAL** | NORMAL | --- |

| CONTAMINATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Fuel | | WC Method | >5 | **<1.0** | <1.0 | --- |
| Water | | WC Method | >0.2 | **NEG** | NEG | --- |
| Glycol | | WC Method | | **NEG** | NEG | --- |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185(m) | >80 | **5** | 13 | --- |
| Chromium | ppm | ASTM D5185(m) | >5 | **0** | <1 | --- |
| Nickel | ppm | ASTM D5185(m) | >2 | **0** | <1 | --- |
| Titanium | ppm | ASTM D5185(m) | | **0** | <1 | --- |
| Silver | ppm | ASTM D5185(m) | >3 | **0** | 0 | --- |
| Aluminum | ppm | ASTM D5185(m) | >30 | **4** | 3 | --- |
| Lead | ppm | ASTM D5185(m) | >30 | **0** | 0 | --- |
| Copper | ppm | ASTM D5185(m) | >150 | **1** | 3 | --- |
| Tin | ppm | ASTM D5185(m) | >5 | **0** | <1 | --- |
| Antimony | ppm | ASTM D5185(m) | | **0** | 0 | --- |
| Vanadium | ppm | ASTM D5185(m) | | **0** | 0 | --- |
| Beryllium | ppm | ASTM D5185(m) | | **0** | 0 | --- |
| Cadmium | ppm | ASTM D5185(m) | | **0** | 0 | --- |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185(m) | | **6** | 126 | --- |
| Barium | ppm | ASTM D5185(m) | | **0** | 0 | --- |
| Molybdenum | ppm | ASTM D5185(m) | | **265** | 9 | --- |
| Manganese | ppm | ASTM D5185(m) | | **0** | <1 | --- |
| Magnesium | ppm | ASTM D5185(m) | | **934** | 77 | --- |
| Calcium | ppm | ASTM D5185(m) | | **1174** | 2400 | --- |
| Phosphorus | ppm | ASTM D5185(m) | | **1131** | 1055 | --- |
| Zinc | ppm | ASTM D5185(m) | | **1209** | 1170 | --- |
| Sulfur | ppm | ASTM D5185(m) | | **2864** | 3043 | --- |
| Lithium | ppm | ASTM D5185(m) | | **<1** | <1 | --- |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185(m) | >20 | **3** | 4 | --- |
| Sodium | ppm | ASTM D5185(m) | | **3** | 5 | --- |
| Potassium | ppm | ASTM D5185(m) | >20 | **1** | 9 | --- |

| INFRA-RED | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Soot % | % | ASTM D7844* | >3 | **0** | 0 | --- |
| Nitration | Abs/cm | ASTM D7624* | >20 | **6.9** | 5.0 | --- |
| Sulfation | Abs/.1mm | ASTM D7415* | >30 | **19.1** | 17.8 | --- |

# OIL ANALYSIS REPORT




| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Oxidation | Abs/.1mm | ASTM D7414* | >25 | **15.1** | 9.3 | --- |

| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Emulsified Water | scalar | Visual* | >0.2 | **NEG** | NEG | --- |
| Free Water | scalar | Visual* | | **NEG** | NEG | --- |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 100°C | cSt | ASTM D7279(m) | 16 | **13.6** | 14.2 | --- |

## GRAPHS

























ISO 17025:2017 Accredited Laboratory

**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
**Sample No.** : GFL0105892
**Lab Number** : 02626017
**Unique Number** : 5759149
**Test Package** : MOB 1

**Received** : 02 Apr 2024
**Tested** : 02 Apr 2024
**Diagnosed** : 02 Apr 2024 - Wes Davis

*To discuss this sample report, contact Customer Service at 1-800-268-2131.*
*Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.*
*Validity of results and interpretation are based on the sample and information as supplied.*

**GFL Environmental - 348**
1027 Kirk Lline East
Bracebridge, ON
CA P1L 0A1
Contact: Royce Reid
roycereid@gflenv.com
T:
F: