OIL ANALYSIS REPORT

Sample Rating Trend



FUEL

Machine Id
426013
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (--- GAL)

DIAGNOSIS

Recommendation
We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.

Wear
All component wear rates are normal.

Contamination
There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.

Fluid Condition
Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0113195**	GFL0113216	GFL0102901
Sample Date		Client Info		**24 Jun 2024**	30 Apr 2024	18 Mar 2024
Machine Age	hrs	Client Info		**15968**	17089	0
Oil Age	hrs	Client Info		**0**	0	18310
Oil Changed		Client Info		**N/A**	N/A	N/A
Sample Status				**ABNORMAL**	NORMAL	SEVERE

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	NEG	NEG
Glycol		WC Method		**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>120	**6**	3	4
Chromium	ppm	ASTM D5185(m)	>20	**0**	0	0
Nickel	ppm	ASTM D5185(m)	>5	**0**	0	<1
Titanium	ppm	ASTM D5185(m)	>2	**0**	0	0
Silver	ppm	ASTM D5185(m)	>2	**0**	0	0
Aluminum	ppm	ASTM D5185(m)	>20	**2**	1	3
Lead	ppm	ASTM D5185(m)	>40	**0**	0	<1
Copper	ppm	ASTM D5185(m)	>330	**1**	<1	1
Tin	ppm	ASTM D5185(m)	>15	**0**	0	<1
Antimony	ppm	ASTM D5185(m)		**<1**	0	0
Vanadium	ppm	ASTM D5185(m)		**0**	0	0
Beryllium	ppm	ASTM D5185(m)		**0**	0	0
Cadmium	ppm	ASTM D5185(m)		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	**34**	116	113
Barium	ppm	ASTM D5185(m)	0	**0**	0	0
Molybdenum	ppm	ASTM D5185(m)	60	**35**	2	4
Manganese	ppm	ASTM D5185(m)	0	**<1**	0	0
Magnesium	ppm	ASTM D5185(m)	1010	**412**	35	54
Calcium	ppm	ASTM D5185(m)	1070	**1569**	2116	2066
Phosphorus	ppm	ASTM D5185(m)	1150	**698**	936	911
Zinc	ppm	ASTM D5185(m)	1270	**822**	1103	1052
Sulfur	ppm	ASTM D5185(m)	2060	**1988**	2806	2881
Lithium	ppm	ASTM D5185(m)		**<1**	<1	<1

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	**5**	1	3
Sodium	ppm	ASTM D5185(m)		**3**	3	3
Potassium	ppm	ASTM D5185(m)	>20	**2**	5	5
Fuel	%	ASTM D7593*	>3.0	▲ **4.5**	2.1	▲ 5.4

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>4	**0.1**	0	0
Nitration	Abs/cm	ASTM D7624*	>20	**8.5**	8.9	8.9
Sulfation	Abs/.1mm	ASTM D7415*	>30	**21.3**	22.4	21.5

OIL ANALYSIS REPORT

FT-IR (Direct Trend)



Viscosity @ 100°C



FT-IR (Direct Trend)



FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	**20.1**	18.2	17.5

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	**NONE**	NONE	---
Yellow Metal	scalar	Visual*	NONE	**NONE**	NONE	---
Precipitate	scalar	Visual*	NONE	**NONE**	NONE	---
Silt	scalar	Visual*	NONE	**NONE**	NONE	---
Debris	scalar	Visual*	NONE	**VLITE**	NONE	---
Sand/Dirt	scalar	Visual*	NONE	**NONE**	NONE	---
Appearance	scalar	Visual*	NORML	**NORML**	NORML	---
Odor	scalar	Visual*	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	Visual*	>0.2	**NEG**	NEG	NEG
Free Water	scalar	Visual*		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D7279(m)	15.4	▲ **10.5**	13.1	▲ 12.2

GRAPHS

Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



Fuel Dilution



ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : GFL0113195
Lab Number : 02644326
Unique Number : 5801865
Test Package : MOB 1 (Additional Tests: FuelDilution, PercentFuel, Visual)

Received : 27 Jun 2024
Tested : 28 Jun 2024
Diagnosed : 28 Jun 2024 - Kevin Marson

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

GFL Environmental - 246 - Windsor
2700 Deziel Dr
Windsor, ON
CA N8W 5H8
Contact: Dave Varga
dvarga@gflenv.com
T: (519)944-8009
F: