# PROBLEM SUMMARY

Sample Rating Trend




**WEAR**

Machine Id
**810014**
Component
**Natural Gas Engine**
Fluid
**RDL-3647 (--- GAL)**

## COMPONENT CONDITION SUMMARY

▲ Ferrous Alloys




## RECOMMENDATION

No corrective action is recommended at this time.
Resample at the next service interval to monitor.

## PROBLEMATIC TEST RESULTS

| | | | | | | |
|---|---|---|---|---|---|---|
| Sample Status | | | | **ATTENTION** | NORMAL | NORMAL |
| Iron | ppm | ASTM D5185m | >50 | ▲ **47** | 4 | 7 |

**Customer Id:** GFL074
**Sample No.:** GFL0083152
**Lab Number:** 05898312
**Test Package:** FLEET

*To manage this report scan the QR code*

*To discuss the diagnosis or test data:*
Don Baldridge +1
don.b505@comcast.net

*To change component or sample information:*
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

## RECOMMENDED ACTIONS

*There are no recommended actions for this sample.*

## HISTORICAL DIAGNOSIS

**20 Jun 2023 Diag: Angela Borella**

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

**05 Jun 2023 Diag: Wes Davis**

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

**18 May 2023 Diag: Wes Davis**

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

# OIL ANALYSIS REPORT

Sample Rating Trend




**WEAR**

Machine Id
**810014**
Component
**Natural Gas Engine**
Fluid
**RDL-3647 (--- GAL)**

## DIAGNOSIS

**▲ Recommendation**
No corrective action is recommended at this time. Resample at the next service interval to monitor.

**▲ Wear**
An increase in the iron level is noted. All other component wear rates are normal.

**Contamination**
There is no indication of any contamination in the oil.

**Fluid Condition**
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **GFL0083152** | GFL0083159 | GFL0083183 |
| Sample Date | | Client Info | | **10 Jul 2023** | 20 Jun 2023 | 05 Jun 2023 |
| Machine Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Changed | | Client Info | | **Not Changd** | Not Changd | Changed |
| Sample Status | | | | **ATTENTION** | NORMAL | NORMAL |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >50 | ▲ **47** | 4 | 7 |
| Chromium | ppm | ASTM D5185m | >4 | **3** | <1 | <1 |
| Nickel | ppm | ASTM D5185m | >2 | **2** | 0 | 0 |
| Titanium | ppm | ASTM D5185m | | **<1** | 0 | 0 |
| Silver | ppm | ASTM D5185m | >3 | **0** | 0 | <1 |
| Aluminum | ppm | ASTM D5185m | >9 | **8** | 1 | 0 |
| Lead | ppm | ASTM D5185m | >30 | **<1** | 0 | <1 |
| Copper | ppm | ASTM D5185m | >35 | **5** | 0 | <1 |
| Tin | ppm | ASTM D5185m | >4 | **<1** | <1 | <1 |
| Vanadium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Cadmium | ppm | ASTM D5185m | | **0** | 0 | 0 |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | 50 | **15** | 39 | 24 |
| Barium | ppm | ASTM D5185m | 5 | **2** | 0 | 0 |
| Molybdenum | ppm | ASTM D5185m | 50 | **57** | 55 | 55 |
| Manganese | ppm | ASTM D5185m | 0 | **<1** | <1 | <1 |
| Magnesium | ppm | ASTM D5185m | 560 | **750** | 571 | 601 |
| Calcium | ppm | ASTM D5185m | 1510 | **1298** | 1510 | 1464 |
| Phosphorus | ppm | ASTM D5185m | 780 | **893** | 776 | 773 |
| Zinc | ppm | ASTM D5185m | 870 | **1102** | 934 | 979 |
| Sulfur | ppm | ASTM D5185m | 2040 | **2853** | 2928 | 3000 |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | >+100 | **13** | 3 | 4 |
| Sodium | ppm | ASTM D5185m | | **19** | 3 | 5 |
| Potassium | ppm | ASTM D5185m | >20 | **2** | 0 | <1 |

| INFRA-RED | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Soot % | % | *ASTM D7844 | | **1.7** | 0.1 | 0.1 |
| Nitration | Abs/cm | *ASTM D7624 | >20 | **10.1** | 7.7 | 8.9 |
| Sulfation | Abs/.1mm | *ASTM D7415 | >30 | **23.3** | 18.8 | 19.4 |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Oxidation | Abs/.1mm | *ASTM D7414 | >25 | **16.7** | 15.7 | 17.2 |
| Base Number (BN) | mg KOH/g | ASTM D2896 | 10.2 | **8.2** | 8.1 | 6.2 |

# OIL ANALYSIS REPORT

Ferrous Alloys




Base Number




Viscosity @ 100°C




| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Debris | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.1 | **NEG** | NEG | NEG |
| Free Water | scalar | *Visual | | **NEG** | NEG | NEG |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 100°C | cSt | ASTM D445 | 15.1 | **14.5** | 14.2 | 14.2 |

## GRAPHS

Ferrous Alloys




Non-ferrous Metals




Viscosity @ 100°C




Base Number




Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : GFL0083152
**Lab Number** : 05898312
**Unique Number** : 10559668
**Test Package** : FLEET

**Received** : 14 Jul 2023
**Diagnosed** : 17 Jul 2023
**Diagnostician** : Don Baldridge

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**GFL Environmental - 074 - Douglas - Transwaste**
1219 Landfill Road
Douglas, GA
US 31533
Contact: CURTIS JACOBS
CURTIS.JACOBS@GFLENV.COM
T: (912)384-6001
F:

Report Id: GFL074 [WUSCAR] 05898312 (Generated: 07/17/2023 17:28:26) Rev: 1

Submitted By: CURTIS JACOBS