# PROBLEM SUMMARY

**Sample Rating Trend**




**WEAR**

Machine Id
**729045-361500**
Component
**Diesel Engine**
Fluid
**PETRO CANADA DURON SHP 15W40 (--- GAL)**

## COMPONENT CONDITION SUMMARY

▲ Ferrous Alloys




## RECOMMENDATION

No corrective action is recommended at this time.
Resample at the next service interval to monitor.

## PROBLEMATIC TEST RESULTS

| Sample Status | | | | **ABNORMAL** | NORMAL | NORMAL |
|---|---|---|---|---|---|---|
| Nickel | ppm | ASTM D5185m | >5 | ▲ **8** | 6 | 6 |

**Customer Id:** GFL820
**Sample No.:** GFL0088250
**Lab Number:** 05951063
**Test Package:** FLEET

*To manage this report scan the QR code*

*To discuss the diagnosis or test data:*
Angela Borella +1 800-237-1369
angela.borella@wearcheckusa.com

*To change component or sample information:*
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

## RECOMMENDED ACTIONS

*There are no recommended actions for this sample.*

## HISTORICAL DIAGNOSIS

**22 Aug 2023 Diag: Wes Davis**

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

**07 Jul 2023 Diag: Wes Davis**

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

**06 Jun 2023 Diag: Wes Davis**

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

# OIL ANALYSIS REPORT

Sample Rating Trend




**WEAR**

Machine Id
## 729045-361500
Component
**Diesel Engine**
Fluid
**PETRO CANADA DURON SHP 15W40 (--- GAL)**

## DIAGNOSIS

**Recommendation**
No corrective action is recommended at this time. Resample at the next service interval to monitor.

**Wear**
Valve wear is indicated. All other component wear rates are normal.

**Contamination**
There is no indication of any contamination in the oil.

**Fluid Condition**
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **GFL0088250** | GFL0088253 | GFL0067695 |
| Sample Date | | Client Info | | **07 Sep 2023** | 22 Aug 2023 | 07 Jul 2023 |
| Machine Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Changed | | Client Info | | **N/A** | N/A | N/A |
| Sample Status | | | | **ABNORMAL** | NORMAL | NORMAL |

| CONTAMINATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Fuel | | WC Method | >3.0 | **<1.0** | <1.0 | <1.0 |
| Glycol | | WC Method | | **NEG** | NEG | NEG |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >120 | **18** | 13 | 10 |
| Chromium | ppm | ASTM D5185m | >20 | **<1** | <1 | <1 |
| Nickel | ppm | ASTM D5185m | >5 | ▲ **8** | 6 | 6 |
| Titanium | ppm | ASTM D5185m | >2 | **0** | 0 | <1 |
| Silver | ppm | ASTM D5185m | >2 | **0** | 0 | 0 |
| Aluminum | ppm | ASTM D5185m | >20 | **5** | 6 | 3 |
| Lead | ppm | ASTM D5185m | >40 | **1** | 0 | <1 |
| Copper | ppm | ASTM D5185m | >330 | **2** | 5 | 1 |
| Tin | ppm | ASTM D5185m | >15 | **<1** | <1 | 0 |
| Vanadium | ppm | ASTM D5185m | | **<1** | 0 | <1 |
| Cadmium | ppm | ASTM D5185m | | **0** | 0 | 0 |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | 0 | **<1** | 1 | <1 |
| Barium | ppm | ASTM D5185m | 0 | **0** | 0 | 0 |
| Molybdenum | ppm | ASTM D5185m | 60 | **60** | 58 | 54 |
| Manganese | ppm | ASTM D5185m | 0 | **<1** | <1 | <1 |
| Magnesium | ppm | ASTM D5185m | 1010 | **977** | 940 | 895 |
| Calcium | ppm | ASTM D5185m | 1070 | **1129** | 1096 | 1036 |
| Phosphorus | ppm | ASTM D5185m | 1150 | **982** | 999 | 946 |
| Zinc | ppm | ASTM D5185m | 1270 | **1247** | 1228 | 1158 |
| Sulfur | ppm | ASTM D5185m | 2060 | **3437** | 3521 | 3439 |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | >25 | **9** | 7 | 6 |
| Sodium | ppm | ASTM D5185m | | **13** | 4 | 3 |
| Potassium | ppm | ASTM D5185m | >20 | **<1** | <1 | 4 |

| INFRA-RED | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Soot % | % | *ASTM D7844 | >4 | **0.7** | 0.5 | 0.4 |
| Nitration | Abs/cm | *ASTM D7624 | >20 | **9.0** | 8.0 | 7.1 |
| Sulfation | Abs/.1mm | *ASTM D7415 | >30 | **19.4** | 19.7 | 19.7 |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Oxidation | Abs/.1mm | *ASTM D7414 | >25 | **15.3** | 15.6 | 15.4 |
| Base Number (BN) | mg KOH/g | ASTM D2896 | 9.8 | **7.9** | 8.5 | 9.1 |

# OIL ANALYSIS REPORT

Ferrous Alloys




Base Number




Viscosity @ 100°C




| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Debris | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.2 | **NEG** | NEG | NEG |
| Free Water | scalar | *Visual | | **NEG** | NEG | NEG |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 100°C | cSt | ASTM D445 | 15.4 | **13.0** | 13.2 | 13.4 |

## GRAPHS

Ferrous Alloys




Non-ferrous Metals




Viscosity @ 100°C




Base Number




Certificate L2367

| | | | |
|---|---|---|---|
| **Laboratory** | : WearCheck USA - 501 Madison Ave., Cary, NC 27513 | | |
| **Sample No.** | : GFL0088250 | **Received** | : 14 Sep 2023 |
| **Lab Number** | : 05951063 | **Diagnosed** | : 18 Sep 2023 |
| **Unique Number** | : 10647022 | **Diagnostician** | : Angela Borella |
| **Test Package** | : FLEET | | |

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*


**GFL Environmental - 820 - Joplin Hauling**
3700 West 7th Street
Joplin, MO
US 64801
Contact: James Jarrett
jjarrett@gflenv.com
T: (417)310-2802
F: