OIL ANALYSIS REPORT

Area
KEMP QUARRIES / KEMP STONE - FAIRLAND [66473]
Machine Id
WL128
Component
Transmission (Manual)
Fluid
PETRO CANADA PRODURO TO-4 SAE 30 (--- GAL)

Sample Rating Trend



NORMAL

DIAGNOSIS

Recommendation
Resample at the next service interval to monitor. (Customer Sample Comment: PM-3 changed filters)

Wear
All component wear rates are normal.

Contamination
There is no indication of any contamination in the fluid.

Fluid Condition
The condition of the fluid is acceptable for the time in service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**PCA0084754**	PCA0084608	PCA0085997
Sample Date		Client Info		**06 Oct 2023**	10 Jul 2023	20 Apr 2023
Machine Age	hrs	Client Info		**34458**	33887	33426
Oil Age	hrs	Client Info		**34458**	33887	33426
Oil Changed		Client Info		**N/A**	Changed	N/A
Sample Status				**NORMAL**	NORMAL	NORMAL

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	**3**	4	4
Chromium	ppm	ASTM D5185m	>5	**3**	0	<1
Nickel	ppm	ASTM D5185m	>5	**0**	0	0
Titanium	ppm	ASTM D5185m		**0**	0	0
Silver	ppm	ASTM D5185m	>7	**0**	0	<1
Aluminum	ppm	ASTM D5185m	>25	**2**	1	1
Lead	ppm	ASTM D5185m	>45	**0**	0	0
Copper	ppm	ASTM D5185m	>225	**6**	8	15
Tin	ppm	ASTM D5185m	>10	**0**	0	0
Vanadium	ppm	ASTM D5185m		**0**	0	0
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	**<1**	<1	0
Barium	ppm	ASTM D5185m	0	**0**	0	0
Molybdenum	ppm	ASTM D5185m	0	**2**	2	1
Manganese	ppm	ASTM D5185m	9	**0**	0	<1
Magnesium	ppm	ASTM D5185m	1	**22**	18	12
Calcium	ppm	ASTM D5185m	3131	**3220**	2966	2606
Phosphorus	ppm	ASTM D5185m	1194	**888**	871	906
Zinc	ppm	ASTM D5185m	1281	**1156**	1056	1119
Sulfur	ppm	ASTM D5185m	3811	**4014**	3522	4689

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>125	**6**	8	18
Sodium	ppm	ASTM D5185m		**0**	0	2
Potassium	ppm	ASTM D5185m	>20	**2**	1	<1

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**MODER**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	88.5	**87.0**	89.9	92.8

OIL ANALYSIS REPORT



SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image

GRAPHS

















Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : PCA0084754
Lab Number : 05980777
Unique Number : 10698072
Test Package : MOB 1

Received : 16 Oct 2023
Diagnosed : 18 Oct 2023
Diagnostician : Angela Borella

Certificate L2367

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Kemp Quarries - Kemp Stone - Fairland
18350 S 590 Rd
Fairland, OK
US 74343
Contact:
fairland@kempstone.com
T:
F: