# OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL

Machine Id
**2513**
Component
**Diesel Engine**
Fluid
**PETRO CANADA DURON SHP 15W40 (34 GAL)**

## DIAGNOSIS

**Recommendation**
Resample at the next service interval to monitor.

**Wear**
All component wear rates are normal.

**Contamination**
There is no indication of any contamination in the oil.

**Fluid Condition**
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **GFL0092711** | GFL0086428 | GFL0072347 |
| Sample Date | | Client Info | | **03 Nov 2023** | 04 Jul 2023 | 24 Jan 2023 |
| Machine Age | hrs | Client Info | | **92071** | 92071 | 92071 |
| Oil Age | hrs | Client Info | | **375** | 582 | 472 |
| Oil Changed | | Client Info | | **Not Changd** | Changed | Not Changd |
| Sample Status | | | | **NORMAL** | NORMAL | NORMAL |

| CONTAMINATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Fuel | | WC Method | >3.0 | **<1.0** | <1.0 | <1.0 |
| Glycol | | WC Method | | **NEG** | NEG | NEG |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >90 | **25** | 73 | 11 |
| Chromium | ppm | ASTM D5185m | >20 | **1** | 3 | <1 |
| Nickel | ppm | ASTM D5185m | >2 | **<1** | 0 | 0 |
| Titanium | ppm | ASTM D5185m | >2 | **0** | <1 | 0 |
| Silver | ppm | ASTM D5185m | >2 | **<1** | 0 | 0 |
| Aluminum | ppm | ASTM D5185m | >20 | **8** | 15 | 1 |
| Lead | ppm | ASTM D5185m | >40 | **9** | 22 | 1 |
| Copper | ppm | ASTM D5185m | >330 | **4** | 9 | 4 |
| Tin | ppm | ASTM D5185m | >15 | **<1** | 2 | <1 |
| Vanadium | ppm | ASTM D5185m | | **<1** | <1 | 0 |
| Cadmium | ppm | ASTM D5185m | | **0** | 0 | 0 |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | 0 | **10** | 6 | 8 |
| Barium | ppm | ASTM D5185m | 0 | **0** | <1 | 0 |
| Molybdenum | ppm | ASTM D5185m | 60 | **65** | 63 | 59 |
| Manganese | ppm | ASTM D5185m | 0 | **<1** | <1 | <1 |
| Magnesium | ppm | ASTM D5185m | 1010 | **1014** | 1005 | 915 |
| Calcium | ppm | ASTM D5185m | 1070 | **1200** | 1219 | 1059 |
| Phosphorus | ppm | ASTM D5185m | 1150 | **1088** | 1059 | 983 |
| Zinc | ppm | ASTM D5185m | 1270 | **1396** | 1317 | 1151 |
| Sulfur | ppm | ASTM D5185m | 2060 | **3204** | 3511 | 3490 |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | >25 | **9** | 21 | 8 |
| Sodium | ppm | ASTM D5185m | | **3** | 4 | 2 |
| Potassium | ppm | ASTM D5185m | >20 | **3** | 3 | 0 |

| INFRA-RED | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Soot % | % | *ASTM D7844 | >6 | **0.6** | 1.1 | 0.3 |
| Nitration | Abs/cm | *ASTM D7624 | >20 | **10.0** | 11.4 | 7.5 |
| Sulfation | Abs/.1mm | *ASTM D7415 | >30 | **22.6** | 24.4 | 19.1 |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Oxidation | Abs/.1mm | *ASTM D7414 | >25 | **19.5** | 21.0 | 14.7 |
| Base Number (BN) | mg KOH/g | ASTM D2896 | 9.8 | **6.9** | 7.2 | 8.5 |

# OIL ANALYSIS REPORT







| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Debris | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.2 | **NEG** | NEG | NEG |
| Free Water | scalar | *Visual | | **NEG** | NEG | NEG |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 100°C | cSt | ASTM D445 | 15.4 | **13.9** | 14.0 | 13.7 |

## GRAPHS













Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : GFL0092711
**Lab Number** : 05998806
**Unique Number** : 10727166
**Test Package** : FLEET

**Received** : 06 Nov 2023
**Diagnosed** : 09 Nov 2023
**Diagnostician** : Wes Davis

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**GFL Environmental - 005 - Wilson/Tri-East(CNG)**
2810 Contentnea Road S
Wilson, NC
US 27893-8501
Contact: SPENCER LIGGON
spencer.liggon@gflenv.com
T: (800)207-6618
F:

Report Id: GFL005 [WUSCAR] 05998806 (Generated: 11/13/2023 15:44:56) Rev: 1

Submitted By: WALTER SKOKOWSKI