OIL DIAGNOSTICS

# PROBLEM SUMMARY

Sample Rating Trend



ISO

Area
**[98604896]**
Machine Id
## KR-GR-003115 - WEST DUMPER (S/N MIX E - 11513079)
Component
**Hydraulic System**
Fluid
**AW HYDRAULIC OIL ISO 68 (--- GAL)**

## COMPONENT CONDITION SUMMARY




## RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor.

## PROBLEMATIC TEST RESULTS

| Sample Status | | | | ABNORMAL | NORMAL | ABNORMAL |
|---|---|---|---|---|---|---|
| Particles >4µm | | ASTM D7647 | >10000 | ▲ **34342** | --- | ▲ 40067 |
| Particles >6µm | | ASTM D7647 | >2500 | ▲ **2575** | --- | ▲ 5292 |
| Oil Cleanliness | | ISO 4406 (c) | >20/18/16 | ▲ **22/19/12** | --- | ▲ 23/20/15 |

**Customer Id:** KRAKIR
**Sample No.:** PCA0051934
**Lab Number:** 06009609
**Test Package:** IND 2

*To manage this report scan the QR code*

*To discuss the diagnosis or test data:*
Don Baldridge +1
don.b505@comcast.net

*To change component or sample information:*
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

## RECOMMENDED ACTIONS

| Action | Status | Date | Done By | Description |
|---|---|---|---|---|
| Change Filter | --- | --- | ? | We recommend you service the filters on this component. |

## HISTORICAL DIAGNOSIS

**25 Oct 2023 Diag: Sean Felton**

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

view report

**05 Oct 2023 Diag: Don Baldridge**

ISO

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

view report

**31 Jul 2023 Diag: Don Baldridge**

ISO

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

view report

# OIL ANALYSIS REPORT

Sample Rating Trend



ISO

Area
**[98604896]**
Machine Id
**KR-GR-003115 - WEST DUMPER (S/N MIX E - 11513079)**
Component
**Hydraulic System**
Fluid
**AW HYDRAULIC OIL ISO 68 (--- GAL)**

## DIAGNOSIS

**Recommendation**
We recommend you service the filters on this component. Resample at the next service interval to monitor.

**Wear**
All component wear rates are normal.

**Contamination**
There is a high amount of silt (particulates < 14 microns in size) present in the oil.

**Fluid Condition**
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **PCA0051934** | PCA0091768 | PCA0106499 |
| Sample Date | | Client Info | | **15 Nov 2023** | 25 Oct 2023 | 05 Oct 2023 |
| Machine Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Changed | | Client Info | | **N/A** | N/A | N/A |
| Sample Status | | | | **ABNORMAL** | NORMAL | ABNORMAL |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >20 | **<1** | 0 | <1 |
| Chromium | ppm | ASTM D5185m | >20 | **0** | 0 | <1 |
| Nickel | ppm | ASTM D5185m | >20 | **0** | 0 | 0 |
| Titanium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Silver | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Aluminum | ppm | ASTM D5185m | >20 | **<1** | 0 | <1 |
| Lead | ppm | ASTM D5185m | >20 | **0** | <1 | 0 |
| Copper | ppm | ASTM D5185m | >20 | **<1** | 0 | <1 |
| Tin | ppm | ASTM D5185m | >20 | **0** | <1 | <1 |
| Vanadium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Cadmium | ppm | ASTM D5185m | | **0** | 0 | 0 |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | 5 | **0** | 0 | 0 |
| Barium | ppm | ASTM D5185m | 5 | **6** | 0 | 19 |
| Molybdenum | ppm | ASTM D5185m | 5 | **0** | 0 | <1 |
| Manganese | ppm | ASTM D5185m | | **0** | <1 | 0 |
| Magnesium | ppm | ASTM D5185m | 25 | **0** | 10 | 0 |
| Calcium | ppm | ASTM D5185m | 200 | **<1** | 0 | 0 |
| Phosphorus | ppm | ASTM D5185m | 300 | **399** | 442 | 442 |
| Zinc | ppm | ASTM D5185m | 370 | **0** | 0 | 21 |
| Sulfur | ppm | ASTM D5185m | 2500 | **475** | 521 | 578 |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | >15 | **1** | 2 | 2 |
| Sodium | ppm | ASTM D5185m | | **0** | 1 | 4 |
| Potassium | ppm | ASTM D5185m | >20 | **1** | 1 | 0 |

| FLUID CLEANLINESS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Particles >4µm | | ASTM D7647 | >10000 | ▲ **34342** | --- | ▲ 40067 |
| Particles >6µm | | ASTM D7647 | >2500 | ▲ **2575** | --- | ▲ 5292 |
| Particles >14µm | | ASTM D7647 | >640 | **30** | --- | 179 |
| Particles >21µm | | ASTM D7647 | >160 | **5** | --- | 23 |
| Particles >38µm | | ASTM D7647 | >40 | **0** | --- | 0 |
| Particles >71µm | | ASTM D7647 | >10 | **0** | --- | 0 |
| Oil Cleanliness | | ISO 4406 (c) | >20/18/16 | ▲ **22/19/12** | --- | ▲ 23/20/15 |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Acid Number (AN) | mg KOH/g | ASTM D8045 | 0.57 | **0.18** | --- | 0.20 |

# OIL ANALYSIS REPORT

Particle Trend




Particle Trend




Acid Number




Viscosity @ 40°C




| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Debris | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.05 | **NEG** | NEG | NEG |
| Free Water | scalar | *Visual | | **NEG** | NEG | NEG |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D445 | 68 | **65.9** | 66.0 | 66.0 |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | |  | | |
| Bottom | | |  | | |

## GRAPHS

Ferrous Alloys




Non-ferrous Metals




Viscosity @ 40°C




Particle Count




Acid Number




Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : PCA0051934
**Lab Number** : 06009609
**Unique Number** : 10743371
**Test Package** : IND 2

**Received** : 16 Nov 2023
**Diagnosed** : 19 Nov 2023
**Diagnostician** : Don Baldridge

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*


**KraftHeinz - Kirksville - Plant 8333 PCA**
2504 INDUSTRIAL DR
KIRKSVILLE, MO
US 63501
Contact: WALLACE WARD
wallace.ward@kraftheinzcompany.com
T: (660)627-1031
F: (660)627-5887