# OIL ANALYSIS REPORT

Sample Rating Trend




NORMAL

Machine Id
**725006-5006**
Component
**Diesel Engine**
Fluid
**PETRO CANADA DURON SHP 15W40 (--- LTR)**

## DIAGNOSIS

**Recommendation**
Resample at the next service interval to monitor.

**Wear**
All component wear rates are normal.

**Contamination**
There is no indication of any contamination in the oil.

**Fluid Condition**
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **GFL0100169** | GFL0058032 | GFL0070902 |
| Sample Date | | Client Info | | **07 Dec 2023** | 07 Sep 2023 | 20 Jun 2023 |
| Machine Age | hrs | Client Info | | **8413** | 8676 | 7825 |
| Oil Age | hrs | Client Info | | **128** | 548 | 7825 |
| Oil Changed | | Client Info | | **Not Changd** | Changed | Changed |
| Sample Status | | | | **NORMAL** | SEVERE | ABNORMAL |

| CONTAMINATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Fuel | | WC Method | >5 | **<1.0** | <1.0 | <1.0 |
| Water | | WC Method | >0.2 | **NEG** | NEG | NEG |
| Glycol | | WC Method | | **NEG** | NEG | NEG |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >100 | **23** | 44 | 30 |
| Chromium | ppm | ASTM D5185m | >20 | **<1** | 1 | <1 |
| Nickel | ppm | ASTM D5185m | >4 | **<1** | <1 | 0 |
| Titanium | ppm | ASTM D5185m | | **<1** | 0 | 0 |
| Silver | ppm | ASTM D5185m | >3 | **0** | 0 | 0 |
| Aluminum | ppm | ASTM D5185m | >20 | **4** | 4 | <1 |
| Lead | ppm | ASTM D5185m | >40 | **0** | 0 | 0 |
| Copper | ppm | ASTM D5185m | >330 | **1** | <1 | <1 |
| Tin | ppm | ASTM D5185m | >15 | **0** | <1 | 0 |
| Vanadium | ppm | ASTM D5185m | | **0** | <1 | 0 |
| Cadmium | ppm | ASTM D5185m | | **0** | 0 | 0 |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | 0 | **4** | 2 | 4 |
| Barium | ppm | ASTM D5185m | 0 | **0** | 0 | 0 |
| Molybdenum | ppm | ASTM D5185m | 60 | **58** | 64 | 63 |
| Manganese | ppm | ASTM D5185m | 0 | **<1** | <1 | <1 |
| Magnesium | ppm | ASTM D5185m | 1010 | **927** | 1017 | 950 |
| Calcium | ppm | ASTM D5185m | 1070 | **1040** | 1197 | 1148 |
| Phosphorus | ppm | ASTM D5185m | 1150 | **1034** | 1070 | 1006 |
| Zinc | ppm | ASTM D5185m | 1270 | **1268** | 1351 | 1247 |
| Sulfur | ppm | ASTM D5185m | 2060 | **3038** | 3652 | 3565 |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | >25 | **8** | 5 | 3 |
| Sodium | ppm | ASTM D5185m | | **2** | 1 | <1 |
| Potassium | ppm | ASTM D5185m | >20 | **3** | 3 | 2 |

| INFRA-RED | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Soot % | % | *ASTM D7844 | >3 | **1.2** | ⬢ 6.1 | ▲ 4.6 |
| Nitration | Abs/cm | *ASTM D7624 | >20 | **8.4** | 18.3 | 12.3 |
| Sulfation | Abs/.1mm | *ASTM D7415 | >30 | **19.9** | 36.6 | 28.9 |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Oxidation | Abs/.1mm | *ASTM D7414 | >25 | **15.1** | 22.7 | 16.4 |
| Base Number (BN) | mg KOH/g | ASTM D2896 | 9.8 | **9.2** | ▲ 0.0 | ▲ 3.3 |

# OIL ANALYSIS REPORT







| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Debris | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.2 | **NEG** | NEG | NEG |
| Free Water | scalar | *Visual | | **NEG** | NEG | NEG |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 100°C | cSt | ASTM D445 | 15.4 | **14.8** | ▲ 18.9 | ▲ 16.9 |

## GRAPHS













**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : GFL0100169
**Lab Number** : 06029270
**Unique Number** : 10779061
**Test Package** : FLEET

**Received** : 08 Dec 2023
**Diagnosed** : 11 Dec 2023
**Diagnostician** : Wes Davis

Certificate L2367

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**GFL Environmental - 657 - Charlottesville Hauling**
5498 Richmond Road
Troy, VA
US 22974
Contact: Brian Ulickas
bulickas@gflenv.com
T:
F:

Report Id: GFL657 [WUSCAR] 06029270 (Generated: 12/11/2023 06:38:50) Rev: 1

Submitted By: TECHNICIAN ACCOUNT