OIL ANALYSIS REPORT

Area
(P837499)
Machine Id
2623
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (8 GAL)

Sample Rating Trend



VISCOSITY

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

Fuel content negligible. There is no indication of any contamination in the oil.

Fluid Condition

The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0096914**	GFL0050891	GFL0069780
Sample Date		Client Info		**08 Feb 2024**	03 Oct 2023	24 Aug 2023
Machine Age	hrs	Client Info		**14107**	13542	13121
Oil Age	hrs	Client Info		**565**	13121	263
Oil Changed		Client Info		**Not Changd**	Changed	Changed
Sample Status				**MARGINAL**	NORMAL	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	NEG	NEG
Glycol		WC Method		**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>120	**8**	4	9
Chromium	ppm	ASTM D5185m	>20	**<1**	<1	<1
Nickel	ppm	ASTM D5185m	>5	**<1**	0	<1
Titanium	ppm	ASTM D5185m	>2	**<1**	0	0
Silver	ppm	ASTM D5185m	>2	**0**	0	0
Aluminum	ppm	ASTM D5185m	>20	**2**	6	3
Lead	ppm	ASTM D5185m	>40	**<1**	0	<1
Copper	ppm	ASTM D5185m	>330	**2**	<1	1
Tin	ppm	ASTM D5185m	>15	**<1**	0	<1
Vanadium	ppm	ASTM D5185m		**0**	0	0
Cadmium	ppm	ASTM D5185m		**<1**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	**11**	15	6
Barium	ppm	ASTM D5185m	0	**0**	0	2
Molybdenum	ppm	ASTM D5185m	60	**68**	63	68
Manganese	ppm	ASTM D5185m	0	**<1**	<1	<1
Magnesium	ppm	ASTM D5185m	1010	**921**	821	855
Calcium	ppm	ASTM D5185m	1070	**1154**	996	1160
Phosphorus	ppm	ASTM D5185m	1150	**986**	932	970
Zinc	ppm	ASTM D5185m	1270	**1241**	1105	1165
Sulfur	ppm	ASTM D5185m	2060	**2982**	3183	2957

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	**6**	4	5
Sodium	ppm	ASTM D5185m		**0**	2	2
Potassium	ppm	ASTM D5185m	>20	**2**	1	2
Fuel	%	ASTM D3524	>3.0	**1.3**	<1.0	<1.0

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>4	**0.1**	0.1	0.2
Nitration	Abs/cm	*ASTM D7624	>20	**7.6**	5.6	7.8
Sulfation	Abs/.1mm	*ASTM D7415	>30	**18.2**	17.1	18.9

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	**14.6**	13.1	15.3
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	**6.9**	7.9	6.4

OIL ANALYSIS REPORT

Fuel Dilution



Fuel Dilution



Base Number



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	▲ **12.3**	12.9	12.6

GRAPHS

Ferrous Alloys



Non-ferrous Metals



▲ Viscosity @ 100°C



Base Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : GFL0096914
Lab Number : 06085285
Unique Number : 10872730
Test Package : FLEET (Additional Tests: FuelDilution, PercentFuel)

Received : 09 Feb 2024
Tested : 13 Feb 2024
Diagnosed : 13 Feb 2024 - Jonathan Hester

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 031 - Greenville/Spartanburg
1635 Antioch Church Rd
Piedmont, SC
US 29673
Contact: TECHNICIAN ACCOUNT
catherine.anastasio@wearcheck.com
T:
F: