OIL DIAGNOSTICS

OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL

Area
Midwest PGM
Machine Id
FUCHS 340 fuchs mhl340 (S/N 340/ 2001)
Component
Front Axle
Fluid
GEAR OIL SAE 80W90 (--- GAL)

DIAGNOSIS

Recommendation
Resample at the next service interval to monitor.

Wear
All component wear rates are normal.

Contamination
There is no indication of any contamination in the oil.

Fluid Condition
The condition of the oil is acceptable for the time in service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**PCA0115475**	LW0007279	LW0006316
Sample Date		Client Info		**27 Mar 2024**	11 Jul 2023	11 Jan 2023
Machine Age	hrs	Client Info		**14765**	14352	14066
Oil Age	hrs	Client Info		**14765**	14352	14066
Oil Changed		Client Info		**Not Changd**	Not Changd	Not Changd
Sample Status				**NORMAL**	ABNORMAL	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>500	**52**	59	53
Chromium	ppm	ASTM D5185m	>10	**<1**	<1	<1
Nickel	ppm	ASTM D5185m	>10	**0**	<1	0
Titanium	ppm	ASTM D5185m		**0**	<1	0
Silver	ppm	ASTM D5185m		**0**	0	0
Aluminum	ppm	ASTM D5185m	>25	**<1**	3	<1
Lead	ppm	ASTM D5185m	>25	**2**	3	0
Copper	ppm	ASTM D5185m	>50	**18**	21	18
Tin	ppm	ASTM D5185m	>10	**0**	0	<1
Vanadium	ppm	ASTM D5185m		**0**	<1	0
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	400	**0**	<1	3
Barium	ppm	ASTM D5185m	200	**0**	6	<1
Molybdenum	ppm	ASTM D5185m	12	**0**	0	0
Manganese	ppm	ASTM D5185m		**4**	4	3
Magnesium	ppm	ASTM D5185m	12	**0**	4	<1
Calcium	ppm	ASTM D5185m	150	**<1**	17	12
Phosphorus	ppm	ASTM D5185m	1650	**308**	341	322
Zinc	ppm	ASTM D5185m	125	**0**	19	14
Sulfur	ppm	ASTM D5185m	22500	**29032**	32395	28457

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>75	**19**	26	20
Sodium	ppm	ASTM D5185m	>170	**1**	3	2
Potassium	ppm	ASTM D5185m	>20	**0**	2	<1

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	▲ MODER	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

OIL ANALYSIS REPORT



FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	143	**128**	129	128

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			*no image*	*no image*	*no image*
Bottom			*no image*	*no image*	*no image*

GRAPHS

















Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : PCA0115475
Lab Number : 06136688
Unique Number : 10956153
Test Package : MOB 1

Received : 02 Apr 2024
Tested : 03 Apr 2024
Diagnosed : 04 Apr 2024 - Don Baldridge

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

CHICAGO MACHINERY INC
3142 EAST LINCOLN
LYNWOOD, IL
US 60411-7728
Contact: Mike Korbelik
mike@chicagomachineryinc.com
T: (708)758-2060
F: