OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL

Machine Id
928093-260350
Component
Transmission (Auto)
Fluid
{not provided} (--- GAL)

DIAGNOSIS

Recommendation
Resample at the next service interval to monitor.

Wear
All component wear rates are normal.

Contamination
There is no indication of any contamination in the fluid.

Fluid Condition
The condition of the fluid is acceptable for the time in service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0122813**	GFL0098589	GFL0098593
Sample Date		Client Info		**17 May 2024**	27 Nov 2023	22 Nov 2023
Machine Age	hrs	Client Info		**14243**	0	13364
Oil Age	hrs	Client Info		**0**	0	0
Oil Changed		Client Info		**N/A**	Not Changd	N/A
Sample Status				**NORMAL**	NORMAL	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.1	**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>160	**9**	11	13
Chromium	ppm	ASTM D5185m	>5	**0**	0	<1
Nickel	ppm	ASTM D5185m	>5	**0**	0	0
Titanium	ppm	ASTM D5185m		**0**	0	0
Silver	ppm	ASTM D5185m	>5	**0**	0	0
Aluminum	ppm	ASTM D5185m	>50	**<1**	2	2
Lead	ppm	ASTM D5185m	>50	**0**	0	<1
Copper	ppm	ASTM D5185m	>225	**2**	3	4
Tin	ppm	ASTM D5185m	>10	**0**	0	<1
Vanadium	ppm	ASTM D5185m		**0**	<1	0
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		**9**	34	28
Barium	ppm	ASTM D5185m		**0**	0	2
Molybdenum	ppm	ASTM D5185m		**<1**	<1	2
Manganese	ppm	ASTM D5185m		**0**	0	0
Magnesium	ppm	ASTM D5185m		**11**	12	15
Calcium	ppm	ASTM D5185m		**112**	111	127
Phosphorus	ppm	ASTM D5185m		**341**	294	324
Zinc	ppm	ASTM D5185m		**379**	261	282
Sulfur	ppm	ASTM D5185m		**1498**	1224	1768

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	**1**	3	2
Sodium	ppm	ASTM D5185m		**1**	4	0
Potassium	ppm	ASTM D5185m	>20	**0**	14	1

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	LIGHT	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

OIL ANALYSIS REPORT



FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445		**43.4**	39.0	39.4

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			*no image*	*no image*	*no image*
Bottom			*no image*	*no image*	*no image*

GRAPHS







Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : GFL0122813
Lab Number : 06186591
Unique Number : 11043343
Test Package : FLEET

Received : 21 May 2024
Tested : 22 May 2024
Diagnosed : 23 May 2024 - Jonathan Hester

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 837 - Harrison TS
22820 S State Route 291
Harrisonville, MO
US 64701
Contact: SARA PATRICK
spatrick@gflenv.com
T:
F:

Report Id: GFL837 [WUSCAR] 06186591 (Generated: 05/23/2024 13:59:32) Rev: 1

Submitted By: JEREMY BROWN