OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL

Area
KEMP QUARRIES / NEOSHO [69885]
Machine Id
WL111
Component
Hydraulic System
Fluid
PETRO CANADA HYDREX AW 68 (--- GAL)

DIAGNOSIS

Recommendation
Resample at the next service interval to monitor. (Customer Sample Comment: PM-2 changed filters)

Wear
All component wear rates are normal.

Contamination
There is no indication of any contamination in the fluid.

Fluid Condition
The condition of the fluid is acceptable for the time in service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**PCA0108725**	PCA0086529	PCA0084709
Sample Date		Client Info		**21 May 2024**	06 Feb 2024	10 Oct 2023
Machine Age	hrs	Client Info		**30720**	30222	29750
Oil Age	hrs	Client Info		**30720**	30222	29750
Oil Changed		Client Info		**N/A**	N/A	Changed
Sample Status				**NORMAL**	NORMAL	NORMAL

CONTAMINATION	method	limit/base	current	history1	history2
Water	WC Method	>0.1	**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	**6**	6	3
Chromium	ppm	ASTM D5185m	>10	**<1**	<1	<1
Nickel	ppm	ASTM D5185m	>10	**<1**	<1	<1
Titanium	ppm	ASTM D5185m		**0**	0	<1
Silver	ppm	ASTM D5185m		**0**	0	0
Aluminum	ppm	ASTM D5185m	>10	**2**	1	2
Lead	ppm	ASTM D5185m	>10	**<1**	0	<1
Copper	ppm	ASTM D5185m	>75	**4**	4	5
Tin	ppm	ASTM D5185m	>10	**<1**	0	<1
Vanadium	ppm	ASTM D5185m		**0**	0	0
Cadmium	ppm	ASTM D5185m		**0**	0	<1

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	**2**	3	4
Barium	ppm	ASTM D5185m	0	**0**	0	9
Molybdenum	ppm	ASTM D5185m	0	**16**	15	20
Manganese	ppm	ASTM D5185m	0	**<1**	0	0
Magnesium	ppm	ASTM D5185m	0	**247**	246	266
Calcium	ppm	ASTM D5185m	50	**546**	529	606
Phosphorus	ppm	ASTM D5185m	330	**586**	596	600
Zinc	ppm	ASTM D5185m	430	**693**	726	726
Sulfur	ppm	ASTM D5185m	760	**2295**	2096	2349

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	**8**	7	7
Sodium	ppm	ASTM D5185m		**2**	1	0
Potassium	ppm	ASTM D5185m	>20	**2**	0	2

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

OIL ANALYSIS REPORT



FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	67.4	**70.2**	70.5	71.0

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			*no image*	*no image*	*no image*
Bottom			*no image*	*no image*	*no image*

GRAPHS

















Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : PCA0108725
Lab Number : 06193180
Unique Number : 11049932
Test Package : MOB 1

Received : 28 May 2024
Tested : 30 May 2024
Diagnosed : 30 May 2024 - Sean Felton

Certificate L2367

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Kemp Quarries - Kemp Stone - Neosho
19148 Ingersol Lane
Neosho, MO
US 64850
Contact:
neosho@kempstone.com
T:
F:

Report Id: KEMNEO [WUSCAR] 06193180 (Generated: 05/30/2024 20:42:57) Rev: 1

Submitted By: