# OIL ANALYSIS REPORT

Sample Rating Trend


VISUAL METAL

Machine Id
## 000023 LOADER STAND
Component
**Hydraulic System**
Fluid
**ROYAL ROYCO 717 (77 GAL)**

## DIAGNOSIS

**Recommendation**
We were unable to perform a particle count due to metal particles present in this sample. We recommend you check the filters on this component. Resample at the next service interval to monitor.

**Wear**
Light concentration of visible metal present. All component wear rates are normal.

**Contamination**
There is no indication of any contamination in the component.

**Fluid Condition**
The condition of oil is suitable for further service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **WC02010140** | --- | --- |
| Sample Date | | Client Info | | **14 Aug 2007** | --- | --- |
| Machine Age | hrs | Client Info | | **0** | --- | --- |
| Oil Age | hrs | Client Info | | **0** | --- | --- |
| Oil Changed | | Client Info | | **N/A** | --- | --- |
| Sample Status | | | | **ABNORMAL** | --- | --- |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | | **<1** | --- | --- |
| Chromium | ppm | ASTM D5185m | | **<1** | --- | --- |
| Nickel | ppm | ASTM D5185m | | **<1** | --- | --- |
| Titanium | ppm | ASTM D5185m | | **0** | --- | --- |
| Silver | ppm | ASTM D5185m | | **0** | --- | --- |
| Aluminum | ppm | ASTM D5185m | | **<1** | --- | --- |
| Lead | ppm | ASTM D5185m | | **0** | --- | --- |
| Copper | ppm | ASTM D5185m | | **<1** | --- | --- |
| Tin | ppm | ASTM D5185m | | **0** | --- | --- |
| Antimony | ppm | ASTM D5185m | | **0** | --- | --- |
| Vanadium | ppm | ASTM D5185m | | **0** | --- | --- |
| Cadmium | ppm | ASTM D5185m | | **0** | --- | --- |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | | **<1** | --- | --- |
| Barium | ppm | ASTM D5185m | | **<1** | --- | --- |
| Molybdenum | ppm | ASTM D5185m | | **0** | --- | --- |
| Manganese | ppm | ASTM D5185m | | **0** | --- | --- |
| Magnesium | ppm | ASTM D5185m | | **<1** | --- | --- |
| Calcium | ppm | ASTM D5185m | | **<1** | --- | --- |
| Phosphorus | ppm | ASTM D5185m | | **764** | --- | --- |
| Zinc | ppm | ASTM D5185m | | **2** | --- | --- |
| Sulfur | ppm | ASTM D5185m | | **151** | --- | --- |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | | **27** | --- | --- |
| Sodium | ppm | ASTM D5185m | | **1** | --- | --- |
| Potassium | ppm | ASTM D5185m | | **<1** | --- | --- |
| Water | % | ASTM D6304 | | **0.011** | --- | --- |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Acid Number (AN) | mg KOH/g | ASTM D8045 | | **0.118** | --- | --- |

# OIL ANALYSIS REPORT










| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | ▲ **LIGHT** | --- | --- |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | --- | --- |
| Precipitate | scalar | *Visual | NONE | **NONE** | --- | --- |
| Silt | scalar | *Visual | NONE | **NONE** | --- | --- |
| Debris | scalar | *Visual | NONE | **NONE** | --- | --- |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | --- | --- |
| Appearance | scalar | *Visual | NORML | **NORML** | --- | --- |
| Odor | scalar | *Visual | NORML | **NORML** | --- | --- |
| Emulsified Water | scalar | *Visual | | **NEG** | --- | --- |
| Free Water | scalar | *Visual | | **NEG** | --- | --- |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D445 | | **26.85** | --- | --- |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | | *no image* | *no image* | *no image* |
| Bottom | | | *no image* | *no image* | *no image* |

## GRAPHS











Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : WC02010140 **Received** : 14 Aug 2007
**Lab Number** : 02010140 **Tested** : 16 Aug 2007
**Unique Number** : 4188893 **Diagnosed** : 16 Aug 2007 - Doug Bogart
**Test Package** : IND 2 ( Additional Tests: Bottom, KF )

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**BAE SYSTEMS**
163 ROCHESTER DR
LOUISVILLE, KY
US 40214
Contact: KEN MAHONEY
ken.mahoney@baesystems.com
T: (502)364-6439
F: (502)364-5973