PROBLEM SUMMARY

Sample Rating Trend



WEAR

Machine Id
MITCHELL SCG1 UB
Component
Bearing
Fluid
SHELL TURBO T ISO 46 (--- LTR)

COMPONENT CONDITION SUMMARY

▲ Non-ferrous Metals



RECOMMENDATION

Resample at the next service interval to monitor.
NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS

Sample Status				**ATTENTION**	ATTENTION	ATTENTION
Copper	ppm	ASTM D5185(m)	>20	▲ **33**	▲ 34	▲ 30

Customer Id: REGSEC
Sample No.: WC0793123
Lab Number: 02554193
Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:
Kevin Marson +1 (289)291-4644 x4644
Kevin.Marson@wearcheck.com

To change component or sample information:
Gloria Gonzalez +1 (289)291-4643 x4643
gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Information Required	---	---	?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

HISTORICAL DIAGNOSIS

13 Apr 2023 Diag: Kevin Marson

WEAR

Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.Copper ppm levels are noted. All other component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

---

28 Jul 2022 Diag: Kevin Marson

WEAR

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.Copper ppm levels are noted. All other component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. Additive levels indicate the addition of a different brand, or type of oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

---

02 Feb 2021 Diag: Kevin Marson

WEAR

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.Copper ppm levels are noted. All other component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. Additive levels indicate the addition of a different brand, or type of oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

OIL ANALYSIS REPORT

Sample Rating Trend



WEAR

Machine Id
MITCHELL SCG1 UB
Component
Bearing
Fluid
SHELL TURBO T ISO 46 (--- LTR)

DIAGNOSIS

▲ Recommendation
Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

▲ Wear
Copper ppm levels are noted. All other component wear rates are normal.

Contamination
The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable.

Fluid Condition
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0793123**	WC0793113	WC0546169
Sample Date		Client Info		**26 Apr 2023**	13 Apr 2023	28 Jul 2022
Machine Age	hrs	Client Info		**0**	0	0
Oil Age	hrs	Client Info		**0**	0	2
Oil Changed		Client Info		**N/A**	N/A	N/A
Sample Status				**ATTENTION**	ATTENTION	ATTENTION

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>2	**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		**0**	0	0
Iron	ppm	ASTM D5185(m)	>20	**<1**	<1	<1
Chromium	ppm	ASTM D5185(m)	>20	**0**	0	0
Nickel	ppm	ASTM D5185(m)	>20	**<1**	<1	<1
Titanium	ppm	ASTM D5185(m)		**0**	0	0
Silver	ppm	ASTM D5185(m)		**0**	0	0
Aluminum	ppm	ASTM D5185(m)	>20	**0**	0	0
Lead	ppm	ASTM D5185(m)	>20	**3**	2	3
Copper	ppm	ASTM D5185(m)	>20	▲ **33**	▲ 34	▲ 30
Tin	ppm	ASTM D5185(m)	>20	**<1**	<1	<1
Antimony	ppm	ASTM D5185(m)		**<1**	0	0
Vanadium	ppm	ASTM D5185(m)		**0**	0	0
Beryllium	ppm	ASTM D5185(m)		**0**	0	0
Cadmium	ppm	ASTM D5185(m)		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	4.0	**<1**	0	<1
Barium	ppm	ASTM D5185(m)	0	**0**	0	0
Molybdenum	ppm	ASTM D5185(m)	0	**0**	0	0
Manganese	ppm	ASTM D5185(m)		**0**	0	0
Magnesium	ppm	ASTM D5185(m)	0	**1**	1	1
Calcium	ppm	ASTM D5185(m)	0	**8**	8	10
Phosphorus	ppm	ASTM D5185(m)	2.1	**76**	76	70
Zinc	ppm	ASTM D5185(m)	2.0	**77**	80	82
Sulfur	ppm	ASTM D5185(m)	1300	**166**	171	165
Lithium	ppm	ASTM D5185(m)		**<1**	<1	<1

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	**0**	0	0
Sodium	ppm	ASTM D5185(m)		**0**	<1	0
Potassium	ppm	ASTM D5185(m)	>20	**<1**	<1	<1

OIL ANALYSIS REPORT

Non-ferrous Metals



Particle Count



Acid Number



Viscosity @ 40°C



PQ



FLUID CLEANLINESS		method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	**470**	429	333
Particles >6µm		ASTM D7647	>2500	**142**	157	78
Particles >14µm		ASTM D7647	>160	**8**	24	8
Particles >21µm		ASTM D7647	>40	**2**	8	2
Particles >38µm		ASTM D7647	>10	**0**	1	1
Particles >71µm		ASTM D7647	>3	**0**	0	0
Oil Cleanliness		ISO 4406 (c)	>20/18/14	**16/14/10**	16/14/12	16/13/10

FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	.05	**0.09**	0.09	0.10

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	Visual*	NONE	**NONE**	NONE	NONE
Precipitate	scalar	Visual*	NONE	**NONE**	NONE	NONE
Silt	scalar	Visual*	NONE	**NONE**	NONE	NONE
Debris	scalar	Visual*	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	**NONE**	NONE	NONE
Appearance	scalar	Visual*	NORML	**NORML**	NORML	NORML
Odor	scalar	Visual*	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	Visual*	>2	**NEG**	NEG	NEG
Free Water	scalar	Visual*		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	46	**46.0**	45.7	45.9

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color					
Bottom					

ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 **Sechelt Creek Station (Regional Power)**
Sample No. : WC0793123 **Received** : 28 Apr 2023 Unit 1A-5764 Wharf Road
Lab Number : 02554193 **Diagnosed** : 02 May 2023 Sechelt Creek, BC
Unique Number : 5567208 **Diagnostician** : Kevin Marson CA V0N 3A0
Test Package : IND 2 (Additional Tests: PRTCOUNT, TAN Man) Contact: Cory Mottishaw
corymsgs@gmail.com

To discuss this sample report, contact Customer Service at 1-800-268-2131. T:
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. F:
Validity of results and interpretation are based on the sample and information as supplied.