# OIL ANALYSIS REPORT

Sample Rating Trend




NORMAL

Machine Id
**DWGCWLECAM1010072**
Component
**Hydraulic System**
Fluid
**DOOSAN ISO VG 46 (--- GAL)**

## DIAGNOSIS

**Recommendation**
Resample at the next service interval to monitor. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using MOB 2 test kits, this testkit includes Particle Count to determine the ISO cleanliness of the fluid.

**Wear**
All component wear rates are normal.

**Contamination**
There is no indication of any contamination in the component(unconfirmed).

**Fluid Condition**
The condition of the oil is acceptable for the time in service.

| SAMPLE INFORMATION | | method | limit/base | current | history 1 | history 2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **WC0811278** | --- | --- |
| Sample Date | | Client Info | | **04 May 2023** | --- | --- |
| Machine Age | hrs | Client Info | | **1041** | --- | --- |
| Oil Age | hrs | Client Info | | **1041** | --- | --- |
| Oil Changed | | Client Info | | **Not Changd** | --- | --- |
| Sample Status | | | | **NORMAL** | --- | --- |

| WEAR METALS | | method | limit/base | current | history 1 | history 2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185(m) | >20 | **4** | --- | --- |
| Chromium | ppm | ASTM D5185(m) | >10 | **0** | --- | --- |
| Nickel | ppm | ASTM D5185(m) | >10 | **<1** | --- | --- |
| Titanium | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Silver | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Aluminum | ppm | ASTM D5185(m) | >10 | **<1** | --- | --- |
| Lead | ppm | ASTM D5185(m) | >10 | **2** | --- | --- |
| Copper | ppm | ASTM D5185(m) | >75 | **58** | --- | --- |
| Tin | ppm | ASTM D5185(m) | >10 | **0** | --- | --- |
| Antimony | ppm | ASTM D5185(m) | | **<1** | --- | --- |
| Vanadium | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Beryllium | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Cadmium | ppm | ASTM D5185(m) | | **0** | --- | --- |

| ADDITIVES | | method | limit/base | current | history 1 | history 2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185(m) | | **<1** | --- | --- |
| Barium | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Molybdenum | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Manganese | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Magnesium | ppm | ASTM D5185(m) | | **2** | --- | --- |
| Calcium | ppm | ASTM D5185(m) | | **147** | --- | --- |
| Phosphorus | ppm | ASTM D5185(m) | | **655** | --- | --- |
| Zinc | ppm | ASTM D5185(m) | | **709** | --- | --- |
| Sulfur | ppm | ASTM D5185(m) | | **1211** | --- | --- |
| Lithium | ppm | ASTM D5185(m) | | **<1** | --- | --- |

| CONTAMINANTS | | method | limit/base | current | history 1 | history 2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185(m) | >20 | **2** | --- | --- |
| Sodium | ppm | ASTM D5185(m) | | **<1** | --- | --- |
| Potassium | ppm | ASTM D5185(m) | >20 | **0** | --- | --- |

| VISUAL | | method | limit/base | current | history 1 | history 2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | Visual* | NONE | **NONE** | --- | --- |
| Yellow Metal | scalar | Visual* | NONE | **NONE** | --- | --- |
| Precipitate | scalar | Visual* | NONE | **NONE** | --- | --- |
| Silt | scalar | Visual* | NONE | **NONE** | --- | --- |
| Debris | scalar | Visual* | NONE | **NONE** | --- | --- |
| Sand/Dirt | scalar | Visual* | NONE | **NONE** | --- | --- |
| Appearance | scalar | Visual* | NORML | **NORML** | --- | --- |
| Odor | scalar | Visual* | NORML | **NORML** | --- | --- |
| Emulsified Water | scalar | Visual* | >0.1 | **NEG** | --- | --- |
| Free Water | scalar | Visual* | | **NEG** | --- | --- |

# OIL ANALYSIS REPORT




| FLUID PROPERTIES | | method | limit/base | current | history 1 | history 2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D7279(m) | | **40.5** | --- | --- |

| SAMPLE IMAGES | method | limit/base | current | history 1 | history 2 |
|---|---|---|---|---|---|
| Color | | |  | *no image* | *no image* |
| Bottom | | |  | *no image* | *no image* |

## GRAPHS

























ISO 17025:2017 Accredited Laboratory

**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
**Sample No.** : WC0811278 **Received** : 09 May 2023
**Lab Number** : 02556237 **Diagnosed** : 09 May 2023
**Unique Number** : 5577277 **Diagnostician** : Wes Davis
**Test Package** : MOB 1

*To discuss this sample report, contact Customer Service at 1-800-268-2131.*
*Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.*
*Validity of results and interpretation are based on the sample and information as supplied.*

**C.G. EQUIPMENT**
7367 Wellington Rd. 30, Unit A
Guelph, ON
CA N0M 2T0
Contact: Maureen McDonald
mmcdonald@cgequipment.com
T:
F: (519)837-2055