PROBLEM SUMMARY

Sample Rating Trend

WEAR

Machine Id
CLOVER SCREEN 120 #2
Component
Gearbox
Fluid
CLP HC 460 (--- GAL)

COMPONENT CONDITION SUMMARY

▲ Viscosity @ 40°C



▲ Non-ferrous Metals



RECOMMENDATION

We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS

Sample Status				**ABNORMAL**	---	---
Copper	ppm	ASTM D5185(m)	>200	▲ **297**	---	---
Tin	ppm	ASTM D5185(m)	>10	▲ **41**	---	---
Visc @ 40°C	cSt	ASTM D7279(m)		▲ **154**	---	---

Customer Id: CRDVIC
Sample No.: WC0738280
Lab Number: 02579515
Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:
Kevin Marson +1 (289)291-4644 x4644
Kevin.Marson@wearcheck.com

To change component or sample information:
Gloria Gonzalez +1 (289)291-4643 x4643
gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Fluid	---	---	?	We recommend that you drain the oil from the component if this has not already been done.
Resample	---	---	?	We recommend an early resample to monitor this condition.

HISTORICAL DIAGNOSIS

OIL ANALYSIS REPORT

Sample Rating Trend

WEAR

Machine Id
CLOVER SCREEN 120 #2
Component
Gearbox
Fluid
CLP HC 460 (--- GAL)

DIAGNOSIS

Recommendation
We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.

Wear
Copper and tin ppm levels are abnormal. Bearing and/or bushing wear is indicated.

Contamination
There is no indication of any contamination in the oil.

Fluid Condition
Viscosity of sample indicates oil is within SAE 50 range, advise investigate. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0738280**	---	---
Sample Date		Client Info		**05 Jul 2023**	---	---
Machine Age	hrs	Client Info		**0**	---	---
Oil Age	hrs	Client Info		**0**	---	---
Oil Changed		Client Info		**Not Changd**	---	---
Sample Status				**ABNORMAL**	---	---

WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		**0**	---	---
Iron	ppm	ASTM D5185(m)	>200	**13**	---	---
Chromium	ppm	ASTM D5185(m)	>10	**0**	---	---
Nickel	ppm	ASTM D5185(m)	>10	**8**	---	---
Titanium	ppm	ASTM D5185(m)		**0**	---	---
Silver	ppm	ASTM D5185(m)		**0**	---	---
Aluminum	ppm	ASTM D5185(m)	>25	**<1**	---	---
Lead	ppm	ASTM D5185(m)	>50	**8**	---	---
Copper	ppm	ASTM D5185(m)	>200	▲ **297**	---	---
Tin	ppm	ASTM D5185(m)	>10	▲ **41**	---	---
Antimony	ppm	ASTM D5185(m)	>5	**0**	---	---
Vanadium	ppm	ASTM D5185(m)		**0**	---	---
Beryllium	ppm	ASTM D5185(m)		**0**	---	---
Cadmium	ppm	ASTM D5185(m)		**0**	---	---

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		**<1**	---	---
Barium	ppm	ASTM D5185(m)		**0**	---	---
Molybdenum	ppm	ASTM D5185(m)		**0**	---	---
Manganese	ppm	ASTM D5185(m)		**<1**	---	---
Magnesium	ppm	ASTM D5185(m)		**2**	---	---
Calcium	ppm	ASTM D5185(m)		**675**	---	---
Phosphorus	ppm	ASTM D5185(m)		**445**	---	---
Zinc	ppm	ASTM D5185(m)		**13**	---	---
Sulfur	ppm	ASTM D5185(m)		**532**	---	---
Lithium	ppm	ASTM D5185(m)		**<1**	---	---

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>50	**14**	---	---
Sodium	ppm	ASTM D5185(m)		**4**	---	---
Potassium	ppm	ASTM D5185(m)	>20	**<1**	---	---

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	**VLITE**	---	---
Yellow Metal	scalar	Visual*	NONE	**NONE**	---	---
Precipitate	scalar	Visual*	NONE	**NONE**	---	---
Silt	scalar	Visual*	NONE	**NONE**	---	---
Debris	scalar	Visual*	NONE	**VLITE**	---	---
Sand/Dirt	scalar	Visual*	NONE	**NONE**	---	---
Appearance	scalar	Visual*	NORML	**NORML**	---	---
Odor	scalar	Visual*	NORML	**NORML**	---	---
Emulsified Water	scalar	Visual*	>0.2	**NEG**	---	---
Free Water	scalar	Visual*		**NEG**	---	---

OIL ANALYSIS REPORT

Viscosity @ 40°C

Non-ferrous Metals



PQ



FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)		▲ 154	---	---

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color				no image	no image
Bottom				no image	no image

GRAPHS

Ferrous Alloys



PQ



Non-ferrous Metals



Viscosity @ 40°C



ISO 17025:2017 Accredited Laboratory

Laboratory	: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9		
Sample No.	: WC0738280	**Received**	: 30 Aug 2023
Lab Number	: 02579515	**Diagnosed**	: 31 Aug 2023
Unique Number	: 5632575	**Diagnostician**	: Kevin Marson
Test Package	: FLEET (Additional Tests: PQ)		

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

CRD, Integrated Water Services
337 Victoria View Road
Victoria, BC
CA V9A 3Z3
Contact: Maintenance Planning
maintenanceplanning@crd.bc.ca
T:
F: