# OIL ANALYSIS REPORT

Sample Rating Trend




NORMAL

Area
## (C-GMCF)
Machine Id
## [C-GMCF] DEHAVILLAND DHC8-514 244
Component
**Jet Turbine**
Fluid
**NOT GIVEN (--- GAL)**

## DIAGNOSIS

**Recommendation**
Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Please specify the brand, type, and viscosity of the oil on your next sample.

**Wear**
All component wear rates are normal. The direct-reading & analytical ferrographic results are normal indicating no abnormal wear in the system.

**Contaminants**
The water content is negligible. There is no indication of any contamination in the oil.

**Oil Condition**
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **WC997227** | WC | --- |
| Sample Date | | Client Info | | **22 Sep 2023** | 12 Sep 2023 | --- |
| TSN | hrs | Client Info | | **58010** | 0 | --- |
| TSO | hrs | Client Info | | **18443** | 0 | --- |
| Oil Age | hrs | Client Info | | **0** | 0 | --- |
| Oil Changed | | Client Info | | **N/A** | N/A | --- |
| Sample Status | | | | **NORMAL** | ABNORMAL | --- |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185(m) | >8 | **0** | 0 | --- |
| Chromium | ppm | ASTM D5185(m) | >2 | **0** | 0 | --- |
| Nickel | ppm | ASTM D5185(m) | >2 | **0** | 0 | --- |
| Titanium | ppm | ASTM D5185(m) | >2 | **0** | 0 | --- |
| Silver | ppm | ASTM D5185(m) | >2 | **<1** | 0 | --- |
| Aluminum | ppm | ASTM D5185(m) | >2 | **0** | <1 | --- |
| Lead | ppm | ASTM D5185(m) | >3 | **0** | 0 | --- |
| Copper | ppm | ASTM D5185(m) | >3 | **<1** | <1 | --- |
| Tin | ppm | ASTM D5185(m) | >2 | **0** | 0 | --- |
| Antimony | ppm | ASTM D5185(m) | | **0** | 0 | --- |
| Vanadium | ppm | ASTM D5185(m) | | **0** | 0 | --- |
| Beryllium | ppm | ASTM D5185(m) | | **0** | 0 | --- |
| Cadmium | ppm | ASTM D5185(m) | | **0** | 0 | --- |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185(m) | | **<1** | 1 | --- |
| Barium | ppm | ASTM D5185(m) | | **<1** | 0 | --- |
| Molybdenum | ppm | ASTM D5185(m) | | **0** | <1 | --- |
| Manganese | ppm | ASTM D5185(m) | | **0** | 0 | --- |
| Magnesium | ppm | ASTM D5185(m) | | **0** | 0 | --- |
| Calcium | ppm | ASTM D5185(m) | | **0** | <1 | --- |
| Phosphorus | ppm | ASTM D5185(m) | | **2549** | 2525 | --- |
| Zinc | ppm | ASTM D5185(m) | | **<1** | 2 | --- |
| Sulfur | ppm | ASTM D5185(m) | | **4** | 19 | --- |
| Lithium | ppm | ASTM D5185(m) | | **<1** | <1 | --- |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185(m) | >8 | **0** | 0 | --- |
| Sodium | ppm | ASTM D5185(m) | | **<1** | <1 | --- |
| Potassium | ppm | ASTM D5185(m) | >20 | **<1** | 0 | --- |
| Water | % | ASTM D6304* | >0.1 | **0.052** | 0.108 | --- |
| ppm Water | ppm | ASTM D6304* | >1000 | **523.8** | 1080.4 | --- |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Acid Number (AN) | mg KOH/g | ASTM D974* | | **0.26** | 0.25 | --- |

# OIL ANALYSIS REPORT

Water (KF)




Viscosity @ 100°C




Viscosity @ 100°C




Viscosity @ 40°C




| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | Visual* | NONE | **NONE** | ▲ LIGHT | --- |
| Yellow Metal | scalar | Visual* | NONE | **NONE** | NONE | --- |
| Precipitate | scalar | Visual* | NONE | **NONE** | NONE | --- |
| Silt | scalar | Visual* | NONE | **NONE** | NONE | --- |
| Debris | scalar | Visual* | NONE | **VLITE** | NONE | --- |
| Sand/Dirt | scalar | Visual* | NONE | **NONE** | NONE | --- |
| Appearance | scalar | Visual* | NORML | **NORML** | NORML | --- |
| Odor | scalar | Visual* | NORML | **NORML** | NORML | --- |
| Emulsified Water | scalar | Visual* | >0.1 | **NEG** | NEG | --- |
| Free Water | scalar | Visual* | | **NEG** | NEG | --- |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D7279(m) | | **24.3** | 23.8 | --- |
| Visc @ 100°C | cSt | ASTM D7279(m) | | **4.9** | 4.8 | --- |
| Viscosity Index (VI) | Scale | ASTM D2270* | | **127** | 124 | --- |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | |  |  | *no image* |
| Bottom | | |  |  | *no image* |
| PrtFilter | | | *no image* |  | *no image* |

## GRAPHS

Ferrous Alloys




Non-ferrous Metals


Viscosity @ 40°C




Acid Number




ISO 17025:2017 Accredited Laboratory

| | | | |
|---|---|---|---|
| **Laboratory** | : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 | | |
| **Sample No.** | : WC997227 | **Received** | : 04 Oct 2023 |
| **Lab Number** | : 02586737 | **Diagnosed** | : 10 Oct 2023 |
| **Unique Number** | : 5655803 | **Diagnostician** | : Kevin Marson |
| **Test Package** | : AVI 3 | | |

*To discuss this sample report, contact Customer Service at 1-800-268-2131.*
*Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.*
*Validity of results and interpretation are based on the sample and information as supplied.*


**PERIMETER AVIATION**
626 FERRY ROAD
WINNIPEG, MB
CA R3H 0T7
Contact: Jacob Kan
Jacob.Kan@perimeter.ca
T: 2(047)838-0000
F: (204)784-4689

# FERROGRAPHY REPORT

Area
**(C-GMCF)**
Machine Id
## [C-GMCF] DEHAVILLAND DHC8-514 244
Component
**Jet Turbine**
Fluid
**NOT GIVEN (--- GAL)**

Magn: 200x Illum: BC



Magn: 50x Illum: RW



Magn: 100x Illum: RW



| DR-FERROGRAPHY | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Large Particles | | DR-Ferr* | | **1.8** | 4.2 | --- |
| Small Particles | | DR-Ferr* | | **0.6** | 3.4 | --- |
| Total Particles | | DR-Ferr* | >--- | **2.4** | 7.6 | --- |
| Large Particles Percentage | % | DR-Ferr* | | **50** | 10.5 | --- |
| Severity Index | | DR-Ferr* | | **2** | 3 | --- |

| FERROGRAPHY | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Ferrous Rubbing | Scale 0-10 | ASTM D7684* | | **2** | 1 | |
| Ferrous Sliding | Scale 0-10 | ASTM D7684* | | | | |
| Ferrous Cutting | Scale 0-10 | ASTM D7684* | | | | |
| Ferrous Rolling | Scale 0-10 | ASTM D7684* | | **1** | 1 | |
| Ferrous Break-in | Scale 0-10 | ASTM D7684* | | | | |
| Ferrous Spheres | Scale 0-10 | ASTM D7684* | | | | |
| Ferrous Black Oxides | Scale 0-10 | ASTM D7684* | | | | |
| Ferrous Red Oxides | Scale 0-10 | ASTM D7684* | | | | |
| Ferrous Corrosive | Scale 0-10 | ASTM D7684* | | | | |
| Ferrous Other | Scale 0-10 | ASTM D7684* | | | | |
| Nonferrous Rubbing | Scale 0-10 | ASTM D7684* | | | | |
| Nonferrous Sliding | Scale 0-10 | ASTM D7684* | | | | |
| Nonferrous Cutting | Scale 0-10 | ASTM D7684* | | | | |
| Nonferrous Rolling | Scale 0-10 | ASTM D7684* | | | | |
| Nonferrous Other | Scale 0-10 | ASTM D7684* | | | | |
| Carbonaceous Material | Scale 0-10 | ASTM D7684* | | | | |
| Lubricant Degradation | Scale 0-10 | ASTM D7684* | | | | |
| Sand/Dirt | Scale 0-10 | ASTM D7684* | | **1** | 1 | |
| Fibres | Scale 0-10 | ASTM D7684* | | | | |
| Spheres | Scale 0-10 | ASTM D7684* | | | | |
| Other | Scale 0-10 | ASTM D7684* | | **1** | 1 | |

### WEAR

All component wear rates are normal. The direct-reading & analytical ferrographic results are normal indicating no abnormal wear in the system.



*This page left intentionally blank*