PROBLEM SUMMARY

Sample Rating Trend



ISO

Area
MTR [73954]
Machine Id
TINHGOV3
Component
Hydraulic System
Fluid
ESSO TERESSO ISO 32 (80 LTR)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS

Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
Particles >4µm		ASTM D7647	>5000	▲ **15331**	▲ 29365	▲ 23822
Particles >6µm		ASTM D7647	>1300	▲ **1812**	▲ 3429	▲ 2711
Oil Cleanliness		ISO 4406 (c)	>19/17/14	▲ **21/18/13**	▲ 22/19/13	▲ 22/19/13

Customer Id: ALGMIS
Sample No.: WC0862789
Lab Number: 02587613
Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:
Wes Davis +1 905-569-8600 x223
wesd@wearcheck.ca

To change component or sample information:
Gloria Gonzalez +1 (289)291-4643 x4643
gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter	---	---	?	We recommend you service the filters on this component.
Resample	---	---	?	We recommend an early resample to monitor this condition.

HISTORICAL DIAGNOSIS

28 Feb 2023 Diag: Kevin Marson

VISUAL METAL

We advise that you check for visible metal particles in the oil. We recommend you service the filters on this component. We recommend an early resample to monitor this condition.Light concentration of visible metal present. Particles >4µm are abnormally high. Particles >6µm and oil cleanliness are abnormally high. The AN level is acceptable for this fluid.

view report

12 Sep 2022 Diag: Wes Davis

ISO

We recommend you service the filters on this component. We recommend an early resample to monitor this condition.All component wear rates are normal. Oil Cleanliness are abnormally high. Particles >4µm are abnormally high. Particles >6µm are abnormally high. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

view report

07 Mar 2022 Diag: Wes Davis

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

OIL ANALYSIS REPORT

Sample Rating Trend



ISO

Area
MTR [73954]
Machine Id
TINHGOV3
Component
Hydraulic System
Fluid
ESSO TERESSO ISO 32 (80 LTR)

DIAGNOSIS

Recommendation
We recommend you service the filters on this component. We recommend an early resample to monitor this condition.

Wear
All component wear rates are normal.

Contamination
There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition
The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0862789**	WC0678270	WC0511687
Sample Date		Client Info		**03 Oct 2023**	28 Feb 2023	12 Sep 2022
Machine Age	mths	Client Info		**0**	0	0
Oil Age	mths	Client Info		**60**	60	60
Oil Changed		Client Info		**Changed**	N/A	Not Changd
Sample Status				**ABNORMAL**	ABNORMAL	ABNORMAL

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	**3**	3	3
Chromium	ppm	ASTM D5185(m)	>20	**0**	0	0
Nickel	ppm	ASTM D5185(m)	>20	**0**	0	<1
Titanium	ppm	ASTM D5185(m)		**0**	0	0
Silver	ppm	ASTM D5185(m)		**<1**	0	0
Aluminum	ppm	ASTM D5185(m)	>20	**<1**	<1	0
Lead	ppm	ASTM D5185(m)	>20	**<1**	0	0
Copper	ppm	ASTM D5185(m)	>20	**<1**	<1	<1
Tin	ppm	ASTM D5185(m)	>20	**0**	0	0
Antimony	ppm	ASTM D5185(m)		**0**	<1	<1
Vanadium	ppm	ASTM D5185(m)		**0**	0	0
Beryllium	ppm	ASTM D5185(m)		**0**	0	0
Cadmium	ppm	ASTM D5185(m)		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		**2**	2	2
Barium	ppm	ASTM D5185(m)		**<1**	0	0
Molybdenum	ppm	ASTM D5185(m)		**0**	0	0
Manganese	ppm	ASTM D5185(m)		**0**	0	0
Magnesium	ppm	ASTM D5185(m)		**0**	0	0
Calcium	ppm	ASTM D5185(m)		**<1**	0	0
Phosphorus	ppm	ASTM D5185(m)		**11**	12	13
Zinc	ppm	ASTM D5185(m)		**13**	13	13
Sulfur	ppm	ASTM D5185(m)		**2205**	2255	2273
Lithium	ppm	ASTM D5185(m)		**<1**	<1	<1

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	**<1**	<1	<1
Sodium	ppm	ASTM D5185(m)		**0**	0	0
Potassium	ppm	ASTM D5185(m)	>20	**0**	0	0

FLUID CLEANLINESS		method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	▲ **15331**	▲ 29365	▲ 23822
Particles >6µm		ASTM D7647	>1300	▲ **1812**	▲ 3429	▲ 2711
Particles >14µm		ASTM D7647	>160	**45**	71	69
Particles >21µm		ASTM D7647	>40	**10**	13	16
Particles >38µm		ASTM D7647	>10	**2**	1	1
Particles >71µm		ASTM D7647	>3	**0**	0	1
Oil Cleanliness		ISO 4406 (c)	>19/17/14	▲ **21/18/13**	▲ 22/19/13	▲ 22/19/13

FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*		**0.22**	0.17	0.18

OIL ANALYSIS REPORT









VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	**NONE**	▲ VLITE	NONE
Yellow Metal	scalar	Visual*	NONE	**NONE**	NONE	NONE
Precipitate	scalar	Visual*	NONE	**NONE**	NONE	NONE
Silt	scalar	Visual*	NONE	**NONE**	NONE	NONE
Debris	scalar	Visual*	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	**NONE**	NONE	NONE
Appearance	scalar	Visual*	NORML	**NORML**	NORML	NORML
Odor	scalar	Visual*	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	Visual*	>0.05	**NEG**	NEG	NEG
Free Water	scalar	Visual*		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	32	**32.7**	32.7	32.7

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color					
Bottom					
PrtFilter					



GRAPHS











ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 **ALGONQUIN POWER SYSTEMS INC.**
Sample No. : WC0862789 **Received** : 06 Oct 2023 354 DAVIS ROAD
Lab Number : 02587613 **Diagnosed** : 10 Oct 2023 OAKVILLE, ON
Unique Number : 5656679 **Diagnostician** : Wes Davis CA L6J 2X1
Test Package : IND 2 (Additional Tests: TAN Man) Contact: Antonino Champ Fernando

To discuss this sample report, contact Customer Service at 1-800-268-2131. antoninoChamp.fernando@algonquinpower.com
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. T: (905)465-7065
Validity of results and interpretation are based on the sample and information as supplied. F: x: