PROBLEM SUMMARY

Sample Rating Trend



ISO

Area
Curing Department
Machine Id
PHC13
Component
Hydraulic System
Fluid
ISO 68 (200 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample.

PROBLEMATIC TEST RESULTS

Sample Status				**ABNORMAL**	ATTENTION	ATTENTION
Particles >4µm		ASTM D7647	>5000	▲ **11778**	▲ 8396	▲ 9665
Oil Cleanliness		ISO 4406 (c)	>19/17/14	▲ **21/17/11**	▲ 20/18/13	▲ 20/17/12

Customer Id: GOONAP
Sample No.: WC0851366
Lab Number: 02591012
Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:
Kevin Marson +1 (289)291-4644 x4644
Kevin.Marson@wearcheck.com

To change component or sample information:
Gloria Gonzalez +1 (289)291-4643 x4643
gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter	---	---	?	We recommend you service the filters on this component.
Resample	---	---	?	We recommend an early resample to monitor this condition.
Information Required	---	---	?	Please specify the brand, type, and viscosity of the oil on your next sample.

HISTORICAL DIAGNOSIS

10 Mar 2023 Diag: Kevin Marson

WEAR

We recommend you service the filters on this component. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using IND 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid.Aluminum ppm levels are noted. All other component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

10 Sep 2022 Diag: Wes Davis

ISO

We recommend you service the filters on this component. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

10 Mar 2022 Diag: Wes Davis

ISO

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. Particles >4µm are abnormally high. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

OIL ANALYSIS REPORT

Sample Rating Trend



ISO

Area
Curing Department
Machine Id
PHC13
Component
Hydraulic System
Fluid
ISO 68 (200 GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample.

Wear

All component wear rates are normal.

Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0851366**	WC0794154	WC0736518
Sample Date		Client Info		**10 Sep 2023**	10 Mar 2023	10 Sep 2022
Machine Age	hrs	Client Info		**0**	0	0
Oil Age	hrs	Client Info		**0**	0	0
Oil Changed		Client Info		**N/A**	N/A	N/A
Sample Status				**ABNORMAL**	ATTENTION	ATTENTION

WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		**0**	---	---
Iron	ppm	ASTM D5185(m)	>20	**38**	38	33
Chromium	ppm	ASTM D5185(m)	>20	**<1**	<1	<1
Nickel	ppm	ASTM D5185(m)	>20	**2**	2	2
Titanium	ppm	ASTM D5185(m)		**0**	<1	<1
Silver	ppm	ASTM D5185(m)		**<1**	<1	0
Aluminum	ppm	ASTM D5185(m)	>20	**7**	▲ 8	2
Lead	ppm	ASTM D5185(m)	>20	**16**	19	16
Copper	ppm	ASTM D5185(m)	>20	**116**	127	112
Tin	ppm	ASTM D5185(m)	>20	**<1**	<1	<1
Antimony	ppm	ASTM D5185(m)		**0**	0	0
Vanadium	ppm	ASTM D5185(m)		**0**	<1	<1
Beryllium	ppm	ASTM D5185(m)		**0**	0	0
Cadmium	ppm	ASTM D5185(m)		**0**	<1	<1

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		**<1**	<1	<1
Barium	ppm	ASTM D5185(m)		**<1**	<1	<1
Molybdenum	ppm	ASTM D5185(m)		**0**	0	0
Manganese	ppm	ASTM D5185(m)		**<1**	<1	<1
Magnesium	ppm	ASTM D5185(m)		**38**	37	33
Calcium	ppm	ASTM D5185(m)		**73**	78	68
Phosphorus	ppm	ASTM D5185(m)		**715**	793	695
Zinc	ppm	ASTM D5185(m)		**594**	611	531
Sulfur	ppm	ASTM D5185(m)		**2207**	2506	2131
Lithium	ppm	ASTM D5185(m)		**<1**	<1	<1

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	**14**	15	14
Sodium	ppm	ASTM D5185(m)		**3**	3	3
Potassium	ppm	ASTM D5185(m)	>20	**0**	0	0

FLUID CLEANLINESS		method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	▲ **11778**	▲ 8396	▲ 9665
Particles >6µm		ASTM D7647	>1300	**1160**	▲ 1571	1250
Particles >14µm		ASTM D7647	>160	**20**	80	24
Particles >21µm		ASTM D7647	>40	**4**	16	5
Particles >38µm		ASTM D7647	>10	**1**	1	0
Particles >71µm		ASTM D7647	>3	**1**	0	0
Oil Cleanliness		ISO 4406 (c)	>19/17/14	▲ **21/17/11**	▲ 20/18/13	▲ 20/17/12

OIL ANALYSIS REPORT











FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*		**0.78**	0.84	0.89

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	Visual*	NONE	**NONE**	NONE	NONE
Precipitate	scalar	Visual*	NONE	**NONE**	NONE	NONE
Silt	scalar	Visual*	NONE	**NONE**	NONE	NONE
Debris	scalar	Visual*	NONE	**VLITE**	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	**NONE**	NONE	NONE
Appearance	scalar	Visual*	NORML	**NORML**	NORML	NORML
Odor	scalar	Visual*	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	Visual*	>0.05	**NEG**	NEG	NEG
Free Water	scalar	Visual*		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	68.0	**64.9**	65.0	65.9

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color					
Bottom					



GRAPHS











ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0851366 **Received** : 23 Oct 2023
Lab Number : 02591012 **Diagnosed** : 25 Oct 2023
Unique Number : 5668091 **Diagnostician** : Kevin Marson
Test Package : IND 2 (Additional Tests: PQ)

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

Goodyear Napanee
388 GOODYEAR ROAD
NAPANEE, ON
CA K7R 3L2
Contact: Mohammad Waleed
Mohammad_Waleed@goodyear.com
T: (613)354-7709
F: (613)354-9377