OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL

Area
[EWC0922709]
Machine Id
TOTE 5/5
Component
Hydraulic System
Fluid
PETRO CANADA HYDREX MV 22 (--- LTR)

DIAGNOSIS

Recommendation
Échantillonner de nouveau l`équipement au prochain intervalle de vidange afin d`en surveiller la condition. Veuillez préciser la marque et le modèle du composant lors du prochain échantillon.

Wear
Les taux d`usure de tous les composants sont normaux.

Contamination
La propreté du système est acceptable pour votre objectif de propreté ISO 4406. La teneur en eau est négligeable. La propreté du système et du fluide est acceptable.

Fluid Condition
Le AN est acceptable pour ce fluide. L`état de l`huile permet d`en prolonger l`utilisation.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0922709**	---	---
Sample Date		Client Info		**06 Jun 2024**	---	---
Machine Age	hrs	Client Info		**0**	---	---
Oil Age	hrs	Client Info		**0**	---	---
Oil Changed		Client Info		**N/A**	---	---
Sample Status				**NORMAL**	---	---

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	**0**	---	---
Chromium	ppm	ASTM D5185(m)	>10	**0**	---	---
Nickel	ppm	ASTM D5185(m)	>10	**0**	---	---
Titanium	ppm	ASTM D5185(m)		**0**	---	---
Silver	ppm	ASTM D5185(m)		**0**	---	---
Aluminum	ppm	ASTM D5185(m)	>10	**0**	---	---
Lead	ppm	ASTM D5185(m)	>10	**0**	---	---
Copper	ppm	ASTM D5185(m)	>75	**0**	---	---
Tin	ppm	ASTM D5185(m)	>10	**0**	---	---
Antimony	ppm	ASTM D5185(m)		**0**	---	---
Vanadium	ppm	ASTM D5185(m)		**0**	---	---
Beryllium	ppm	ASTM D5185(m)		**0**	---	---
Cadmium	ppm	ASTM D5185(m)		**0**	---	---

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	**<1**	---	---
Barium	ppm	ASTM D5185(m)	0	**0**	---	---
Molybdenum	ppm	ASTM D5185(m)	0	**0**	---	---
Manganese	ppm	ASTM D5185(m)	1	**0**	---	---
Magnesium	ppm	ASTM D5185(m)	0	**1**	---	---
Calcium	ppm	ASTM D5185(m)	50	**52**	---	---
Phosphorus	ppm	ASTM D5185(m)	330	**321**	---	---
Zinc	ppm	ASTM D5185(m)	430	**418**	---	---
Sulfur	ppm	ASTM D5185(m)	760	**726**	---	---
Lithium	ppm	ASTM D5185(m)		**<1**	---	---

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>20	**0**	---	---
Sodium	ppm	ASTM D5185(m)		**0**	---	---
Potassium	ppm	ASTM D5185(m)	>20	**0**	---	---
Water	%	ASTM D6304*	>0.1	**0.002**	---	---
ppm Water	ppm	ASTM D6304*	>1000	**24**	---	---

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*		**0**	---	---
Nitration	Abs/cm	ASTM D7624*		**1.6**	---	---
Sulfation	Abs/.1mm	ASTM D7415*		**18.8**	---	---

OIL ANALYSIS REPORT

FT-IR (Direct Trend)



Particle Count



Acid Number



Water (KF)



Viscosity @ 100°C



FLUID CLEANLINESS		method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>2500	**184**	---	---
Particles >6µm		ASTM D7647	>640	**63**	---	---
Particles >14µm		ASTM D7647	>80	**7**	---	---
Particles >21µm		ASTM D7647	>20	**2**	---	---
Particles >38µm		ASTM D7647	>4	**1**	---	---
Particles >71µm		ASTM D7647	>3	**0**	---	---
Oil Cleanliness		ISO 4406 (c)	>18/16/13	**15/13/10**	---	---

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*		**10.7**	---	---
Acid Number (AN)	mg KOH/g	ASTM D974*	0.60	**0.42**	---	---

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	**NONE**	---	---
Yellow Metal	scalar	Visual*	NONE	**NONE**	---	---
Precipitate	scalar	Visual*	NONE	**NONE**	---	---
Silt	scalar	Visual*	NONE	**NONE**	---	---
Debris	scalar	Visual*	NONE	**NONE**	---	---
Sand/Dirt	scalar	Visual*	NONE	**NONE**	---	---
Appearance	scalar	Visual*	NORML	**NORML**	---	---
Odor	scalar	Visual*	NORML	**NORML**	---	---
Emulsified Water	scalar	Visual*	>0.1	**NEG**	---	---
Free Water	scalar	Visual*		**NEG**	---	---

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	22.2	**21.8**	---	---
Visc @ 100°C	cSt	ASTM D7279(m)	4.95	**4.8**	---	---
Viscosity Index (VI)	Scale	ASTM D2270*	156	**147**	---	---

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color				*no image*	*no image*
Bottom				*no image*	*no image*

ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0922709 **Received** : 14 Jun 2024
Lab Number : 02642030 **Tested** : 14 Jun 2024
Unique Number : 5799569 **Diagnosed** : 18 Jun 2024 - Kevin Marson
Test Package : MOB 2 (Additional Tests: TAN Man)

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

Envirolin Canada
520 rue Adanac
Quebec, QC
CA G1C 7B7
Contact: Patrick Levesque
patrick.levesque@envirolin.com
T: (418)623-1216
F: (418)660-8889