# OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL

Area
**SAB1**
Machine Id
**SAB1 G7**
Component
**Thrust Bearing**
Fluid
**ESSO TERESSO ISO 46 (4250 LTR)**

## DIAGNOSIS

**Recommendation**
Resample at the next service interval to monitor. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using IND 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid.

**Wear**
Component wear rates appear to be normal (unconfirmed).

**Contamination**
The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable.

**Fluid Condition**
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Particle Filter (Magn: 100 x)



| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **WC0933977** | WC0812562 | WC0864645 |
| Sample Date | | Client Info | | **03 Jul 2024** | 15 May 2024 | 21 Dec 2023 |
| Machine Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Changed | | Client Info | | **N/A** | N/A | N/A |
| Sample Status | | | | **NORMAL** | NORMAL | NORMAL |

| CONTAMINATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Water | | WC Method | >2 | **NEG** | NEG | NEG |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185(m) | >85 | **3** | 3 | 3 |
| Chromium | ppm | ASTM D5185(m) | >20 | **0** | 0 | 0 |
| Nickel | ppm | ASTM D5185(m) | >20 | **<1** | 0 | 0 |
| Titanium | ppm | ASTM D5185(m) | | **0** | 0 | 0 |
| Silver | ppm | ASTM D5185(m) | | **0** | 0 | 0 |
| Aluminum | ppm | ASTM D5185(m) | >40 | **<1** | 0 | <1 |
| Lead | ppm | ASTM D5185(m) | >60 | **0** | 0 | 0 |
| Copper | ppm | ASTM D5185(m) | >7 | **<1** | <1 | <1 |
| Tin | ppm | ASTM D5185(m) | >40 | **0** | 0 | <1 |
| Antimony | ppm | ASTM D5185(m) | | **0** | 0 | 0 |
| Vanadium | ppm | ASTM D5185(m) | | **0** | 0 | 0 |
| Beryllium | ppm | ASTM D5185(m) | | **0** | 0 | 0 |
| Cadmium | ppm | ASTM D5185(m) | | **0** | 0 | 0 |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185(m) | 0 | **<1** | <1 | 0 |
| Barium | ppm | ASTM D5185(m) | | **0** | 0 | 0 |
| Molybdenum | ppm | ASTM D5185(m) | 0 | **0** | 0 | 0 |
| Manganese | ppm | ASTM D5185(m) | | **0** | 0 | 0 |
| Magnesium | ppm | ASTM D5185(m) | 0 | **0** | 0 | 0 |
| Calcium | ppm | ASTM D5185(m) | 0 | **<1** | 0 | <1 |
| Phosphorus | ppm | ASTM D5185(m) | 2.4 | **3** | 2 | <1 |
| Zinc | ppm | ASTM D5185(m) | 0 | **1** | 1 | 2 |
| Sulfur | ppm | ASTM D5185(m) | | **1244** | 1315 | 1528 |
| Lithium | ppm | ASTM D5185(m) | | **<1** | <1 | <1 |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185(m) | >20 | **2** | 2 | 3 |
| Sodium | ppm | ASTM D5185(m) | | **0** | 0 | 0 |
| Potassium | ppm | ASTM D5185(m) | >20 | **<1** | <1 | 1 |

| FLUID CLEANLINESS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Particles >4µm | | ASTM D7647 | >10000 | **184** | 166 | 317 |
| Particles >6µm | | ASTM D7647 | >1300 | **55** | 62 | 110 |
| Particles >14µm | | ASTM D7647 | >160 | **4** | 10 | 16 |
| Particles >21µm | | ASTM D7647 | >40 | **1** | 3 | 3 |
| Particles >38µm | | ASTM D7647 | >10 | **0** | 1 | 1 |
| Particles >71µm | | ASTM D7647 | >3 | **0** | 0 | 0 |
| Oil Cleanliness | | ISO 4406 (c) | >20/17/14 | **15/13/9** | 15/13/10 | 15/14/11 |

# OIL ANALYSIS REPORT

Particle Count




Acid Number




Viscosity @ 40°C




Particle Trend




| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Acid Number (AN) | mg KOH/g | ASTM D974* | 0.02 | **0.10** | 0.10 | 0.14 |

| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | Visual* | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | Visual* | NONE | **NONE** | NONE | NONE |
| Precipitate | scalar | Visual* | NONE | **NONE** | NONE | NONE |
| Silt | scalar | Visual* | NONE | **NONE** | NONE | NONE |
| Debris | scalar | Visual* | NONE | **NONE** | NONE | NONE |
| Sand/Dirt | scalar | Visual* | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | Visual* | NORML | **NORML** | NORML | NORML |
| Odor | scalar | Visual* | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | Visual* | >2 | **NEG** | NEG | NEG |
| Free Water | scalar | Visual* | | **NEG** | NEG | NEG |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D7279(m) | 46 | **46.3** | 46.6 | 46.6 |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | | | | |
| Bottom | | | | | |
| PrtFilter | | | | | |



ISO 17025:2017 Accredited Laboratory

**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
**Sample No.** : WC0933977 **Received** : 04 Jul 2024
**Lab Number** : 02645495 **Tested** : 09 Jul 2024
**Unique Number** : 5803034 **Diagnosed** : 09 Jul 2024 - Kevin Marson
**Test Package** : IND 2 ( Additional Tests: BottomAnalysis, FilterPatch, PrtFilter, TAN Man )

*To discuss this sample report, contact Customer Service at 1-800-268-2131.*
*Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.*
*Validity of results and interpretation are based on the sample and information as supplied.*


**Ontario Power Generation**
NIAGARA PLANT GROUP,, 14000 NIAGARA PKWY
NIAGARA ON THE LAKE, ON
CA L0S 1J0
Contact: Michael Brochu
mike.brochu@opg.com
T: (905)357-0322
F: (905)374-5466