# OIL ANALYSIS REPORT

Sample Rating Trend




NORMAL

Area
**MINING**
Machine Id
**ME-588 JOHN DEERE 944K 1DW944KXCNL703692**
Component
**Diesel Engine**
Fluid
**SHELL 10W30 (--- GAL)**

## DIAGNOSIS

**Recommendation**
Resample at the next service interval to monitor.

**Wear**
All component wear rates are normal.

**Contamination**
There is no indication of any contamination in the oil.

**Fluid Condition**
The condition of the oil is acceptable for the time in service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **WC0946264** | --- | --- |
| Sample Date | | Client Info | | **21 Jun 2024** | --- | --- |
| Machine Age | hrs | Client Info | | **2184** | --- | --- |
| Oil Age | hrs | Client Info | | **0** | --- | --- |
| Oil Changed | | Client Info | | **Changed** | --- | --- |
| Sample Status | | | | **NORMAL** | --- | --- |

| CONTAMINATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Fuel | | WC Method | >2.1 | **<1.0** | --- | --- |
| Water | | WC Method | >0.21 | **NEG** | --- | --- |
| Glycol | | WC Method | | **NEG** | --- | --- |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185(m) | >51 | **36** | --- | --- |
| Chromium | ppm | ASTM D5185(m) | >11 | **<1** | --- | --- |
| Nickel | ppm | ASTM D5185(m) | >5 | **<1** | --- | --- |
| Titanium | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Silver | ppm | ASTM D5185(m) | >3 | **0** | --- | --- |
| Aluminum | ppm | ASTM D5185(m) | >31 | **4** | --- | --- |
| Lead | ppm | ASTM D5185(m) | >26 | **21** | --- | --- |
| Copper | ppm | ASTM D5185(m) | >26 | **17** | --- | --- |
| Tin | ppm | ASTM D5185(m) | >4 | **4** | --- | --- |
| Antimony | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Vanadium | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Beryllium | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Cadmium | ppm | ASTM D5185(m) | | **0** | --- | --- |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185(m) | | **5** | --- | --- |
| Barium | ppm | ASTM D5185(m) | | **0** | --- | --- |
| Molybdenum | ppm | ASTM D5185(m) | | **17** | --- | --- |
| Manganese | ppm | ASTM D5185(m) | | **<1** | --- | --- |
| Magnesium | ppm | ASTM D5185(m) | 470 | **127** | --- | --- |
| Calcium | ppm | ASTM D5185(m) | 1150 | **2117** | --- | --- |
| Phosphorus | ppm | ASTM D5185(m) | 94 | **851** | --- | --- |
| Zinc | ppm | ASTM D5185(m) | 1030 | **1004** | --- | --- |
| Sulfur | ppm | ASTM D5185(m) | | **2709** | --- | --- |
| Lithium | ppm | ASTM D5185(m) | | **<1** | --- | --- |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185(m) | >22 | **4** | --- | --- |
| Sodium | ppm | ASTM D5185(m) | >31 | **4** | --- | --- |
| Potassium | ppm | ASTM D5185(m) | >20 | **2** | --- | --- |

| INFRA-RED | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Soot % | % | ASTM D7844* | >3 | **0.6** | --- | --- |
| Nitration | Abs/cm | ASTM D7624* | >20 | **9.5** | --- | --- |
| Sulfation | Abs/.1mm | ASTM D7415* | >30 | **23.6** | --- | --- |

# OIL ANALYSIS REPORT

FT-IR (Direct Trend)




Viscosity @ 100°C




| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Oxidation | Abs/.1mm | ASTM D7414* | >25 | **14.7** | --- | --- |

| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Emulsified Water | scalar | Visual* | >0.21 | **NEG** | --- | --- |
| Free Water | scalar | Visual* | | **NEG** | --- | --- |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 100°C | cSt | ASTM D7279(m) | 10.90 | **10.9** | --- | --- |

## GRAPHS

Ferrous Alloys




Non-ferrous Metals




Viscosity @ 100°C




ISO 17025:2017 Accredited Laboratory

**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
**Sample No.** : WC0946264
**Lab Number** : 02645867
**Unique Number** : 5811419
**Test Package** : CONST

**Received** : 05 Jul 2024
**Tested** : 05 Jul 2024
**Diagnosed** : 05 Jul 2024 - Wes Davis

*To discuss this sample report, contact Customer Service at 1-800-268-2131.*
*Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.*
*Validity of results and interpretation are based on the sample and information as supplied.*

**Covia Canada Ltd.**
260 Unimin Road, County Rd. #46
Havelock, ON
CA K0L 1Z0
Contact: Dan Lyon
dan.lyon@coviacorp.com
T: (705)632-8904
F: