# OIL ANALYSIS REPORT

Sample Rating Trend




ISO

Machine Id
## Weg w22 Wrap 1&2
Component
**Reservoir Hydraulic Power Pack**
Fluid
**AW HYDRAULIC OIL ISO 46 (40 GAL)**

## DIAGNOSIS

**Recommendation**
No corrective action is recommended at this time. Resample at the next service interval to monitor. ( Customer Sample Comment: AZ324 )

**Wear**
All component wear rates are normal.

**Contamination**
There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.

**Fluid Condition**
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **WC0508486** | --- | --- |
| Sample Date | | Client Info | | **08 Oct 2020** | --- | --- |
| Machine Age | hrs | Client Info | | **0** | --- | --- |
| Oil Age | hrs | Client Info | | **2** | --- | --- |
| Oil Changed | | Client Info | | **Not Changd** | --- | --- |
| Sample Status | | | | **ATTENTION** | --- | --- |

| CONTAMINATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Water | | WC Method | >0.05 | **NEG** | --- | --- |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >20 | **24** | --- | --- |
| Chromium | ppm | ASTM D5185m | >20 | **0** | --- | --- |
| Nickel | ppm | ASTM D5185m | >20 | **0** | --- | --- |
| Titanium | ppm | ASTM D5185m | | **0** | --- | --- |
| Silver | ppm | ASTM D5185m | | **0** | --- | --- |
| Aluminum | ppm | ASTM D5185m | >20 | **0** | --- | --- |
| Lead | ppm | ASTM D5185m | >20 | **0** | --- | --- |
| Copper | ppm | ASTM D5185m | >20 | **3** | --- | --- |
| Tin | ppm | ASTM D5185m | >20 | **0** | --- | --- |
| Antimony | ppm | ASTM D5185m | | **0** | --- | --- |
| Vanadium | ppm | ASTM D5185m | | **0** | --- | --- |
| Cadmium | ppm | ASTM D5185m | | **0** | --- | --- |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | 5 | **1** | --- | --- |
| Barium | ppm | ASTM D5185m | 5 | **0** | --- | --- |
| Molybdenum | ppm | ASTM D5185m | 5 | **0** | --- | --- |
| Manganese | ppm | ASTM D5185m | | **<1** | --- | --- |
| Magnesium | ppm | ASTM D5185m | 25 | **0** | --- | --- |
| Calcium | ppm | ASTM D5185m | 200 | **10** | --- | --- |
| Phosphorus | ppm | ASTM D5185m | 300 | **232** | --- | --- |
| Zinc | ppm | ASTM D5185m | 370 | **266** | --- | --- |
| Sulfur | ppm | ASTM D5185m | 2500 | **2333** | --- | --- |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | >15 | **1** | --- | --- |
| Sodium | ppm | ASTM D5185m | | **<1** | --- | --- |
| Potassium | ppm | ASTM D5185m | >20 | **0** | --- | --- |

| FLUID CLEANLINESS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Particles >4µm | | ASTM D7647 | >5000 | **5593** | --- | --- |
| Particles >6µm | | ASTM D7647 | >1300 | **751** | --- | --- |
| Particles >14µm | | ASTM D7647 | >160 | **16** | --- | --- |
| Particles >21µm | | ASTM D7647 | >40 | **2** | --- | --- |
| Particles >38µm | | ASTM D7647 | >10 | **0** | --- | --- |
| Particles >71µm | | ASTM D7647 | >3 | **0** | --- | --- |
| Oil Cleanliness | | ISO 4406 (c) | >19/17/14 | **20/17/11** | --- | --- |

# OIL ANALYSIS REPORT













| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Acid Number (AN) | mg KOH/g | ASTM D8045 | 0.57 | **0.284** | --- | --- |

| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | **NONE** | --- | --- |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | --- | --- |
| Precipitate | scalar | *Visual | NONE | **NONE** | --- | --- |
| Silt | scalar | *Visual | NONE | **NONE** | --- | --- |
| Debris | scalar | *Visual | NONE | **NONE** | --- | --- |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | --- | --- |
| Appearance | scalar | *Visual | NORML | **NORML** | --- | --- |
| Odor | scalar | *Visual | NORML | **NORML** | --- | --- |
| Emulsified Water | scalar | *Visual | >0.05 | **NEG** | --- | --- |
| Free Water | scalar | *Visual | | **NEG** | --- | --- |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D445 | 46 | **47.1** | --- | --- |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | |  | *no image* | *no image* |
| Bottom | | |  | *no image* | *no image* |

## GRAPHS
















**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : WC0508486
**Lab Number** : 05138071
**Unique Number** : 9293346
**Test Package** : IND 2

**Received** : 16 Dec 2020
**Tested** : 16 Dec 2020
**Diagnosed** : 16 Dec 2020 - Don Baldridge

Certificate L2367

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**MISTER CAR WASH - TUCSON REGION**
2301 N FORBES BLVD, SUITE 105
TUCSON, AZ
US 85745
Contact: MIKE LAWTON
mmead@mistercarwash.com
T:
F:

Report Id: MISTUCAZ [WUSCAR] 05138071 (Generated: 07/18/2024 13:49:54) Rev: 1

Submitted By: ? STORE 321