PROBLEM SUMMARY

Sample Rating Trend



WATER

Machine Id
B LINE KRONES - AGGREGATE
Component
Gearbox
Fluid
GEAR OIL (PAG) ISO 220 (--- GAL)

COMPONENT CONDITION SUMMARY





RECOMMENDATION

Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS

Sample Status				**ABNORMAL**	NORMAL	NORMAL
Water	%	ASTM D6304	>0.2	▲ **0.331**	0.007	0.006
ppm Water	ppm	ASTM D6304	>2000	▲ **3310**	71.7	65.5
Appearance	scalar	*Visual	NORML	▲ **HAZY**	NORML	NORML
Visc @ 40°C	cSt	ASTM D445	220	▲ **172.1**	209	211

Customer Id: KRAWOOIL
Sample No.: USPM5902311
Lab Number: 05902311
Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:
Doug Bogart +1 (800)237-1369 x4016
dougb@wearcheckusa.com

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

22 Nov 2022 Diag: Doug Bogart

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

25 Oct 2022 Diag: Doug Bogart

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

24 Oct 2022 Diag: Doug Bogart

ISO

Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The condition of the oil is acceptable for the time in service. Insufficient sample was received to conduct TAN test.

view report

OIL ANALYSIS REPORT

Sample Rating Trend



WATER

Machine Id
B LINE KRONES - AGGREGATE
Component
Gearbox
Fluid
GEAR OIL (PAG) ISO 220 (--- GAL)

DIAGNOSIS

Recommendation
Resample at the next service interval to monitor.

Wear
All component wear rates are normal.

Contamination
Appearance is hazy. There is a light concentration of water present in the oil. The amount and size of particulates present in the system are acceptable.

Fluid Condition
The oil viscosity is lower than normal. Confirm oil type. The AN level is acceptable for this fluid.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**USPM5902311**	USP05701401	USP05676723
Sample Date		Client Info		**18 Jul 2023**	22 Nov 2022	25 Oct 2022
Machine Age	hrs	Client Info		**0**	0	0
Oil Age	hrs	Client Info		**0**	0	0
Oil Changed		Client Info		**N/A**	N/A	N/A
Sample Status				**ABNORMAL**	NORMAL	NORMAL

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	**0**	4	2
Chromium	ppm	ASTM D5185m	>15	**0**	0	0
Nickel	ppm	ASTM D5185m	>15	**0**	0	0
Titanium	ppm	ASTM D5185m		**0**	0	0
Silver	ppm	ASTM D5185m		**0**	0	0
Aluminum	ppm	ASTM D5185m	>25	**<1**	<1	0
Lead	ppm	ASTM D5185m	>100	**0**	0	0
Copper	ppm	ASTM D5185m	>200	**0**	0	0
Tin	ppm	ASTM D5185m	>25	**0**	<1	0
Vanadium	ppm	ASTM D5185m		**0**	0	0
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	5	**0**	0	0
Barium	ppm	ASTM D5185m	5	**0**	0	0
Molybdenum	ppm	ASTM D5185m	5	**0**	0	0
Manganese	ppm	ASTM D5185m		**0**	0	0
Magnesium	ppm	ASTM D5185m	5	**<1**	0	0
Calcium	ppm	ASTM D5185m	5	**0**	2	3
Phosphorus	ppm	ASTM D5185m	775	**445**	566	562
Zinc	ppm	ASTM D5185m	5	**0**	<1	<1
Sulfur	ppm	ASTM D5185m	2000	**535**	648	660

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	**1**	<1	0
Sodium	ppm	ASTM D5185m		**0**	0	0
Potassium	ppm	ASTM D5185m	>20	**<1**	0	0
Water	%	ASTM D6304	>0.2	▲ **0.331**	0.007	0.006
ppm Water	ppm	ASTM D6304	>2000	▲ **3310**	71.7	65.5

FLUID CLEANLINESS		method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	**2038**	969	6696
Particles >6µm		ASTM D7647	>2500	**321**	196	1095
Particles >14µm		ASTM D7647	>640	**14**	15	40
Particles >21µm		ASTM D7647	>160	**5**	3	5
Particles >38µm		ASTM D7647	>40	**0**	1	0
Particles >71µm		ASTM D7647	>10	**0**	0	0
Oil Cleanliness		ISO 4406 (c)	>20/18/16	**18/16/11**	17/15/11	20/17/12

FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	2.00	**0.25**	0.56	0.60

OIL ANALYSIS REPORT

Water



Particle Trend



Particle Count



Acid Number



Particle Trend



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	▲ **HAZY**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**0.2%**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	220	▲ **172.1**	209	211

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color					
Bottom					

GRAPHS

Ferrous Alloys



Non-ferrous Metals



Viscosity @ 40°C



Particle Count



Acid Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : USPM5902311
Lab Number : 05902311
Unique Number : 10563667
Test Package : IND 2

Received : 19 Jul 2023
Diagnosed : 21 Jul 2023
Diagnostician : Doug Bogart

KraftHeinz - Woodstock - Plant 8337
1300 CLAUSSEN DR
WOODSTOCK, IL
US 60098
Contact: Service Manager

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:
F: