PROBLEM SUMMARY

Sample Rating Trend



ISO

Machine Id
T-102
Component
Agitator Gearbox
Fluid
GEAR OIL ISO 320 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time.
Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS

				ATTENTION	ATTENTION	NORMAL
Sample Status				**ATTENTION**	ATTENTION	NORMAL
Particles >4µm		ASTM D7647	>20000	▲ **32277**	▲ 32707	---
Oil Cleanliness		ISO 4406 (c)	>21/19/16	▲ **22/19/15**	▲ 22/19/13	---

Customer Id: AVEMIL
Sample No.: WC05905407
Lab Number: 05905407
Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:
Don Baldridge +1
don.b505@comcast.net

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

16 Feb 2021 Diag: Wes Davis

ISO

Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. We recommend you service the filters on this component. Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL ISO 320. Please confirm. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

30 Jan 2019 Diag: Jonathan Hester

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the component. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

06 Jan 2017 Diag: Don Baldridge

NORMAL

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the component. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

OIL ANALYSIS REPORT

Sample Rating Trend



ISO

Machine Id
T-102
Component
Agitator Gearbox
Fluid
GEAR OIL ISO 320 (--- GAL)

DIAGNOSIS

Recommendation
No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear
All component wear rates are normal.

Contamination
There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC05905407**	WC0507873	WCI2341359
Sample Date		Client Info		**23 Jul 2023**	16 Feb 2021	30 Jan 2019
Machine Age	mths	Client Info		**0**	0	0
Oil Age	mths	Client Info		**0**	0	0
Oil Changed		Client Info		**N/A**	N/A	N/A
Sample Status				**ATTENTION**	ATTENTION	NORMAL

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>150	**4**	5	5
Chromium	ppm	ASTM D5185m	>10	**<1**	<1	<1
Nickel	ppm	ASTM D5185m	>10	**0**	<1	0
Titanium	ppm	ASTM D5185m		**0**	<1	<1
Silver	ppm	ASTM D5185m		**<1**	<1	0
Aluminum	ppm	ASTM D5185m	>25	**0**	0	0
Lead	ppm	ASTM D5185m	>100	**2**	1	2
Copper	ppm	ASTM D5185m	>50	**2**	4	8
Tin	ppm	ASTM D5185m	>10	**0**	0	<1
Antimony	ppm	ASTM D5185m	>5	**---**	0	<1
Vanadium	ppm	ASTM D5185m		**0**	0	0
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	50	**47**	43	41
Barium	ppm	ASTM D5185m	15	**2**	2	2
Molybdenum	ppm	ASTM D5185m	15	**0**	0	0
Manganese	ppm	ASTM D5185m		**2**	2	2
Magnesium	ppm	ASTM D5185m	50	**4**	4	4
Calcium	ppm	ASTM D5185m	50	**14**	14	14
Phosphorus	ppm	ASTM D5185m	350	**240**	246	228
Zinc	ppm	ASTM D5185m	100	**37**	29	41
Sulfur	ppm	ASTM D5185m	12500	**8586**	6868	9740

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	**8**	5	10
Sodium	ppm	ASTM D5185m		**0**	2	2
Potassium	ppm	ASTM D5185m	>20	**<1**	<1	1

FLUID CLEANLINESS		method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>20000	▲ **32277**	▲ 32707	---
Particles >6µm		ASTM D7647	>5000	**4380**	4631	---
Particles >14µm		ASTM D7647	>640	**192**	69	---
Particles >21µm		ASTM D7647	>160	**36**	11	---
Particles >38µm		ASTM D7647	>40	**2**	0	---
Particles >71µm		ASTM D7647	>10	**1**	0	---
Oil Cleanliness		ISO 4406 (c)	>21/19/16	▲ **22/19/15**	▲ 22/19/13	---

FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.85	**0.52**	0.484	0.583

OIL ANALYSIS REPORT









VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	320	**305**	298	300.6

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color					
Bottom					



GRAPHS











Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : WC05905407 **Received** : 24 Jul 2023
Lab Number : 05905407 **Diagnosed** : 26 Jul 2023
Unique Number : 10566763 **Diagnostician** : Don Baldridge
Test Package : IND 2 (Additional Tests: PrtCount)

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

AVERY DENNISON CHEMICAL DIVISION
171 DRAKETOWN RD
MILL HALL, PA
US 17751
Contact: DONALD EYER
DONALD.EYER@AVERYDENNISON.COM
T:
F: (570)748-1813