PROBLEM SUMMARY

Sample Rating Trend



SEDIMENT

Machine Id
TE2 (S/N 1738)
Component
Agitator Gearbox
Fluid
MOBIL MOBILGEAR 630 (5 GAL)

COMPONENT CONDITION SUMMARY

No relevant graphs to display

RECOMMENDATION

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

PROBLEMATIC TEST RESULTS

Sample Status				**ABNORMAL**	NORMAL	NORMAL
Silt	scalar	*Visual	NONE	▲ **MODER**	NONE	NONE

Customer Id: AVEMIL
Sample No.: WC05905422
Lab Number: 05905422
Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:
Don Baldridge +1
don.b505@comcast.net

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter	---	---	?	We recommend you service the filters on this component if applicable.
Alert	---	---	?	We were unable to perform a particle count due to a high concentration of particles present in this sample.

HISTORICAL DIAGNOSIS

16 Feb 2021 Diag: Wes Davis

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

30 Jan 2019 Diag: Jonathan Hester

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the component. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

30 Jan 2019 Diag: Jonathan Hester

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

OIL ANALYSIS REPORT

Sample Rating Trend



SEDIMENT

Machine Id
TE2 (S/N 1738)
Component
Agitator Gearbox
Fluid
MOBIL MOBILGEAR 630 (5 GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

Wear

All component wear rates are normal.

Contamination

There is a moderate amount of visible silt present in the sample.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC05905422**	WC0507867	WCI2303603
Sample Date		Client Info		**23 Jul 2023**	16 Feb 2021	30 Jan 2019
Machine Age	mths	Client Info		**0**	0	0
Oil Age	mths	Client Info		**0**	0	0
Oil Changed		Client Info		**N/A**	N/A	N/A
Sample Status				**ABNORMAL**	NORMAL	NORMAL

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>150	**2**	3	42
Chromium	ppm	ASTM D5185m	>10	**0**	<1	<1
Nickel	ppm	ASTM D5185m	>10	**0**	0	<1
Titanium	ppm	ASTM D5185m		**0**	0	0
Silver	ppm	ASTM D5185m		**<1**	<1	0
Aluminum	ppm	ASTM D5185m	>25	**0**	0	<1
Lead	ppm	ASTM D5185m	>100	**<1**	<1	0
Copper	ppm	ASTM D5185m	>50	**<1**	<1	<1
Tin	ppm	ASTM D5185m	>10	**0**	0	0
Antimony	ppm	ASTM D5185m	>5	**---**	0	0
Vanadium	ppm	ASTM D5185m		**0**	0	0
Cadmium	ppm	ASTM D5185m		**0**	0	<1

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		**0**	2	6
Barium	ppm	ASTM D5185m		**<1**	0	<1
Molybdenum	ppm	ASTM D5185m		**0**	0	2
Manganese	ppm	ASTM D5185m		**<1**	<1	<1
Magnesium	ppm	ASTM D5185m		**0**	<1	0
Calcium	ppm	ASTM D5185m		**6**	6	4
Phosphorus	ppm	ASTM D5185m		**249**	253	199
Zinc	ppm	ASTM D5185m		**17**	8	98
Sulfur	ppm	ASTM D5185m		**6386**	4964	18190

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	**0**	<1	1
Sodium	ppm	ASTM D5185m		**16**	24	<1
Potassium	ppm	ASTM D5185m	>20	**4**	3	1

FLUID CLEANLINESS		method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>20000	**---**	12321	---
Particles >6µm		ASTM D7647	>5000	**---**	634	---
Particles >14µm		ASTM D7647	>640	**---**	19	---
Particles >21µm		ASTM D7647	>160	**---**	4	---
Particles >38µm		ASTM D7647	>40	**---**	0	---
Particles >71µm		ASTM D7647	>10	**---**	0	---
Oil Cleanliness		ISO 4406 (c)	>21/19/16	**---**	21/16/11	---

FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		**0.32**	0.331	0.548

OIL ANALYSIS REPORT





VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	▲ **MODER**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	220	**185**	186	211.7

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color					
Bottom					

GRAPHS









Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : WC05905422 **Received** : 24 Jul 2023
Lab Number : 05905422 **Diagnosed** : 26 Jul 2023
Unique Number : 10566778 **Diagnostician** : Don Baldridge
Test Package : IND 2 (Additional Tests: PrtCount)

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

AVERY DENNISON CHEMICAL DIVISION
171 DRAKETOWN RD
MILL HALL, PA
US 17751
Contact: DONALD EYER
DONALD.EYER@AVERYDENNISON.COM
T:
F: (570)748-1813