# OIL ANALYSIS REPORT

Sample Rating Trend




NORMAL

Machine Id
**24149**
Component
**Hydraulic System**
Fluid
**AW HYDRAULIC OIL ISO 32 (--- GAL)**

## DIAGNOSIS

**Recommendation**
Resample at the next service interval to monitor.

**Wear**
All component wear rates are normal.

**Contamination**
The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable.

**Fluid Condition**
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **WC0772562** | WC0708443 | WC0640509 |
| Sample Date | | Client Info | | **14 Aug 2023** | 25 Jan 2023 | 16 Dec 2021 |
| Machine Age | days | Client Info | | **0** | 0 | 0 |
| Oil Age | days | Client Info | | **0** | 0 | 0 |
| Oil Changed | | Client Info | | **N/A** | N/A | N/A |
| Sample Status | | | | **NORMAL** | ATTENTION | ABNORMAL |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >20 | **6** | 6 | 6 |
| Chromium | ppm | ASTM D5185m | >10 | **0** | 0 | 0 |
| Nickel | ppm | ASTM D5185m | >10 | **0** | 0 | 0 |
| Titanium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Silver | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Aluminum | ppm | ASTM D5185m | >10 | **0** | 0 | <1 |
| Lead | ppm | ASTM D5185m | >10 | **0** | <1 | 0 |
| Copper | ppm | ASTM D5185m | >75 | **<1** | 1 | 2 |
| Tin | ppm | ASTM D5185m | >10 | **0** | 0 | 0 |
| Antimony | ppm | ASTM D5185m | | **---** | --- | 0 |
| Vanadium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Cadmium | ppm | ASTM D5185m | | **0** | 0 | 0 |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | 5 | **<1** | 0 | 7 |
| Barium | ppm | ASTM D5185m | 5 | **0** | 1 | 0 |
| Molybdenum | ppm | ASTM D5185m | 5 | **0** | <1 | <1 |
| Manganese | ppm | ASTM D5185m | | **<1** | 0 | 0 |
| Magnesium | ppm | ASTM D5185m | 25 | **4** | 3 | 2 |
| Calcium | ppm | ASTM D5185m | 200 | **77** | 76 | 80 |
| Phosphorus | ppm | ASTM D5185m | 300 | **357** | 333 | 325 |
| Zinc | ppm | ASTM D5185m | 370 | **429** | 421 | 404 |
| Sulfur | ppm | ASTM D5185m | 2500 | **5109** | 4415 | 3502 |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | >20 | **<1** | <1 | <1 |
| Sodium | ppm | ASTM D5185m | | **<1** | 0 | 1 |
| Potassium | ppm | ASTM D5185m | >20 | **0** | <1 | 0 |

| FLUID CLEANLINESS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Particles >4µm | | ASTM D7647 | >5000 | **2484** | ▲ 8367 | ▲ 31320 |
| Particles >6µm | | ASTM D7647 | >1300 | **438** | ▲ 1437 | ▲ 2366 |
| Particles >14µm | | ASTM D7647 | >160 | **12** | 29 | 33 |
| Particles >21µm | | ASTM D7647 | >40 | **3** | 3 | 9 |
| Particles >38µm | | ASTM D7647 | >10 | **0** | 0 | 1 |
| Particles >71µm | | ASTM D7647 | >3 | **0** | 0 | 0 |
| Oil Cleanliness | | ISO 4406 (c) | >19/17/14 | **18/16/11** | ▲ 20/18/12 | ▲ 22/18/12 |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Acid Number (AN) | mg KOH/g | ASTM D8045 | 0.57 | **0.30** | 0.34 | 0.307 |

# OIL ANALYSIS REPORT

Viscosity @ 100°C




Particle Trend




Viscosity @ 100°C




Viscosity @ 40°C




Particle Trend




| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Debris | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.1 | **NEG** | NEG | NEG |
| Free Water | scalar | *Visual | | **NEG** | NEG | NEG |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D445 | 32 | **35.1** | 35.1 | 33.9 |
| Visc @ 100°C | cSt | ASTM D445 | 5.4 | **6.3** | 6.5 | 6.3 |
| Viscosity Index (VI) | Scale | ASTM D2270 | 102 | **130** | 140 | 138 |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | | | | |
| Bottom | | | | | |



## GRAPHS

Ferrous Alloys




Non-ferrous Metals




Viscosity @ 40°C




Particle Count




Acid Number




Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : WC0772562 **Received** : 14 Aug 2023
**Lab Number** : 05924262 **Diagnosed** : 15 Aug 2023
**Unique Number** : 10604209 **Diagnostician** : Don Baldridge
**Test Package** : MOB 2 ( Additional Tests: KV100, VI )

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*


**HIAB USA - HAGERSTOWN**
148 WESTERN MARYLAND PKWY
HAGERSTOWN, MD
US 21740
Contact: CHUCK WISHARD
CHUCK.WISHARD@HIAB.COM
T: (240)625-0045
F: (301)797-7284