OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL

Machine Id
ALSTOM R145
Component
Gearbox
Fluid
TOTAL CARTER SH 220 (3 GAL)

DIAGNOSIS

Recommendation
Resample at the next service interval to monitor.

Wear
All component wear rates are normal.

Contamination
There is no indication of any contamination in the oil.

Fluid Condition
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0781701**	WC0673263	WC0571663
Sample Date		Client Info		**01 Aug 2023**	28 Jan 2023	29 Jan 2022
Machine Age	hrs	Client Info		**0**	0	0
Oil Age	hrs	Client Info		**0**	0	0
Oil Changed		Client Info		**N/A**	N/A	N/A
Sample Status				**NORMAL**	ABNORMAL	NORMAL

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	**172**	▲ 322	143
Chromium	ppm	ASTM D5185m	>10	**1**	3	2
Nickel	ppm	ASTM D5185m	>10	**0**	<1	1
Titanium	ppm	ASTM D5185m		**0**	<1	<1
Silver	ppm	ASTM D5185m		**0**	0	0
Aluminum	ppm	ASTM D5185m	>25	**5**	5	9
Lead	ppm	ASTM D5185m	>50	**4**	6	7
Copper	ppm	ASTM D5185m	>200	**76**	74	79
Tin	ppm	ASTM D5185m	>10	**<1**	<1	2
Antimony	ppm	ASTM D5185m	>5	**---**	---	11
Vanadium	ppm	ASTM D5185m		**0**	0	<1
Cadmium	ppm	ASTM D5185m		**<1**	0	<1

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		**0**	0	3
Barium	ppm	ASTM D5185m		**0**	0	9
Molybdenum	ppm	ASTM D5185m		**<1**	2	1
Manganese	ppm	ASTM D5185m		**3**	4	2
Magnesium	ppm	ASTM D5185m		**3**	3	15
Calcium	ppm	ASTM D5185m		**5**	11	23
Phosphorus	ppm	ASTM D5185m		**358**	284	364
Zinc	ppm	ASTM D5185m		**145**	144	160
Sulfur	ppm	ASTM D5185m		**3585**	2344	2782

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	**25**	29	27
Sodium	ppm	ASTM D5185m		**15**	27	20
Potassium	ppm	ASTM D5185m	>20	**4**	2	6

FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		**0.50**	0.30	0.71

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

OIL ANALYSIS REPORT





FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445		**232**	216	224

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color				*no image*	*no image*
Bottom				*no image*	*no image*

GRAPHS

















Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : WC0781701
Lab Number : 05924444
Unique Number : 10604391
Test Package : MOB 2

Received : 14 Aug 2023
Diagnosed : 15 Aug 2023
Diagnostician : Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

AMTRAK
1401 W STREET NE, HIGH SPEED RAIL 2ND FLOOR
WASHINGTON, DC
US 20018
Contact: MICHAEL PORTER
michael.porter@amtrak.com
T: (202)870-1399
F: