# PROBLEM SUMMARY

Sample Rating Trend


ISO

Area
**37372 (TRACE PO 36471)**
Machine Id
**JP8TS0001-08142023A**
Component
**Hydraulic System**
Fluid
**JP8 MIL-DTL-83133 (--- GAL)**

## COMPONENT CONDITION SUMMARY




## RECOMMENDATION

No corrective action is recommended at this time.

## PROBLEMATIC TEST RESULTS

| | | | | | | |
|---|---|---|---|---|---|---|
| Sample Status | | | | **ATTENTION** | --- | --- |
| Particles 5-15µm | count | *NAS 1638 | >8000 | **11500** | --- | --- |
| Particles 25-50µm | count | *NAS 1638 | >253 | **312** | --- | --- |

**Customer Id:** RIDHAM
**Sample No.:** WC05926949
**Lab Number:** 05926949
**Test Package:** IND 2

*To manage this report scan the QR code*

*To discuss the diagnosis or test data:*
Doug Bogart +1 (800)237-1369 x4016
dougb@wearcheckusa.com

*To change component or sample information:*
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

## RECOMMENDED ACTIONS

*There are no recommended actions for this sample.*

## HISTORICAL DIAGNOSIS

# OIL ANALYSIS REPORT

Sample Rating Trend


ISO

Area
**37372 (TRACE PO 36471)**
Machine Id
**JP8TS0001-08142023A**
Component
**Hydraulic System**
Fluid
**JP8 MIL-DTL-83133 (--- GAL)**

## DIAGNOSIS

**Recommendation**
No corrective action is recommended at this time.

**Wear**
All component wear rates are normal.

**Contamination**
There is a moderate amount of particulates present in the oil. The system cleanliness is above the acceptable limit for the target SAE AS4059 (replaces NAS 1638) cleanliness code.

**Fluid Condition**
The AN level is acceptable for this fluid.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **WC05926949** | --- | --- |
| Sample Date | | Client Info | | **15 Aug 2023** | --- | --- |
| Machine Age | hrs | Client Info | | **0** | --- | --- |
| Oil Age | hrs | Client Info | | **0** | --- | --- |
| Oil Changed | | Client Info | | **N/A** | --- | --- |
| Sample Status | | | | **ATTENTION** | --- | --- |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >20 | **0** | --- | --- |
| Chromium | ppm | ASTM D5185m | >20 | **0** | --- | --- |
| Nickel | ppm | ASTM D5185m | >20 | **0** | --- | --- |
| Titanium | ppm | ASTM D5185m | | **0** | --- | --- |
| Silver | ppm | ASTM D5185m | | **0** | --- | --- |
| Aluminum | ppm | ASTM D5185m | >20 | **0** | --- | --- |
| Lead | ppm | ASTM D5185m | >20 | **0** | --- | --- |
| Copper | ppm | ASTM D5185m | >20 | **0** | --- | --- |
| Tin | ppm | ASTM D5185m | >20 | **0** | --- | --- |
| Vanadium | ppm | ASTM D5185m | | **0** | --- | --- |
| Cadmium | ppm | ASTM D5185m | | **0** | --- | --- |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | | **0** | --- | --- |
| Barium | ppm | ASTM D5185m | | **2** | --- | --- |
| Molybdenum | ppm | ASTM D5185m | | **0** | --- | --- |
| Manganese | ppm | ASTM D5185m | | **0** | --- | --- |
| Magnesium | ppm | ASTM D5185m | | **0** | --- | --- |
| Calcium | ppm | ASTM D5185m | | **0** | --- | --- |
| Phosphorus | ppm | ASTM D5185m | | **<1** | --- | --- |
| Zinc | ppm | ASTM D5185m | | **0** | --- | --- |
| Sulfur | ppm | ASTM D5185m | | **0** | --- | --- |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | >15 | **<1** | --- | --- |
| Sodium | ppm | ASTM D5185m | | **0** | --- | --- |
| Potassium | ppm | ASTM D5185m | >20 | **<1** | --- | --- |
| Water | % | ASTM D6304 | >0.05 | **0.003** | --- | --- |
| ppm Water | ppm | ASTM D6304 | >500 | **29.7** | --- | --- |

| FLUID CLEANLINESS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Particles 5-15µm | count | *NAS 1638 | >8000 | ▲ **11500** | --- | --- |
| Particles 15-25µm | count | *NAS 1638 | >1425 | **1299** | --- | --- |
| Particles 25-50µm | count | *NAS 1638 | >253 | ▲ **312** | --- | --- |
| Particles 50-100µm | count | *NAS 1638 | >45 | **0** | --- | --- |
| Particles >100µm | count | *NAS 1638 | >8 | **0** | --- | --- |
| NAS 1638 | Class | *NAS 1638 | >5 | **6** | --- | --- |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Acid Number (AN) | mg KOH/g | ASTM D8045 | | **0.042** | --- | --- |

# OIL ANALYSIS REPORT













| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | **NONE** | --- | --- |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | --- | --- |
| Precipitate | scalar | *Visual | NONE | **NONE** | --- | --- |
| Silt | scalar | *Visual | NONE | **NONE** | --- | --- |
| Debris | scalar | *Visual | NONE | **NONE** | --- | --- |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | --- | --- |
| Appearance | scalar | *Visual | NORML | **NORML** | --- | --- |
| Odor | scalar | *Visual | NORML | **NORML** | --- | --- |
| Emulsified Water | scalar | *Visual | >0.05 | **NEG** | --- | --- |
| Free Water | scalar | *Visual | | **NEG** | --- | --- |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D445 | | **1.36** | --- | --- |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | |  | *no image* | *no image* |
| Bottom | | |  | *no image* | *no image* |

## GRAPHS














**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : WC05926949 **Received** : 16 Aug 2023
**Lab Number** : 05926949 **Diagnosed** : 22 Aug 2023
**Unique Number** : 10606896 **Diagnostician** : Doug Bogart
**Test Package** : IND 2 ( Additional Tests: KF, PrtCountNAS )

Certificate L2367

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**RIDGE ENGINEERING**
3987 HAMPSTEAD-MEXICO RD
HAMPSTEAD, MD
US 21074
Contact: BETHANY HUGHES*
bethany@ridgeeng.com
T:
F: