# PROBLEM SUMMARY

Area
**OKLAHOMA/102**
Machine Id
**20.023L [OKLAHOMA^102]**
Component
**Hydraulic System**
Fluid
**MOBIL DELVAC 1300 SUPER15W40 (15 GAL)**

**Sample Rating Trend**




**ISO**

## COMPONENT CONDITION SUMMARY




## RECOMMENDATION

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

## PROBLEMATIC TEST RESULTS

| | | | | ATTENTION | NORMAL | ABNORMAL |
|---|---|---|---|---|---|---|
| Sample Status | | | | | | |
| Particles >6µm | | ASTM D7647 | >2500 | ▲ **4047** | 925 | ▲ 11489 |
| Oil Cleanliness | | ISO 4406 (c) | >--/18/16 | ▲ **21/19/16** | 21/17/12 | ▲ 23/21/17 |

**Customer Id:** SHEWIC
**Sample No.:** WC0834080
**Lab Number:** 05959736
**Test Package:** CONST

*To manage this report scan the QR code*

*To discuss the diagnosis or test data:*
Don Baldridge +1
don.b505@comcast.net

*To change component or sample information:*
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

## RECOMMENDED ACTIONS

*There are no recommended actions for this sample.*

## HISTORICAL DIAGNOSIS

**12 May 2023 Diag: Don Baldridge**

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

**29 Sep 2022 Diag: Jonathan Hester**

WATER

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. There is a light concentration of water present in the oil. There is a moderate amount of visible silt present in the sample. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

# OIL ANALYSIS REPORT

Area
**OKLAHOMA/102**
Machine Id
**20.023L [OKLAHOMA^102]**
Component
**Hydraulic System**
Fluid
**MOBIL DELVAC 1300 SUPER15W40 (15 GAL)**

Sample Rating Trend




ISO

## DIAGNOSIS

**▲ Recommendation**
No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

**Wear**
All component wear rates are normal.

**▲ Contamination**
There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.

**Fluid Condition**
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **WC0834080** | WC0808100 | WC0726266 |
| Sample Date | | Client Info | | **25 Aug 2023** | 12 May 2023 | 29 Sep 2022 |
| Machine Age | hrs | Client Info | | **1046** | 925 | 500 |
| Oil Age | hrs | Client Info | | **1046** | 925 | 500 |
| Oil Changed | | Client Info | | **Not Changd** | Not Changd | Not Changd |
| Sample Status | | | | **ATTENTION** | NORMAL | ABNORMAL |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >20 | **6** | 6 | 4 |
| Chromium | ppm | ASTM D5185m | >10 | **0** | 0 | 0 |
| Nickel | ppm | ASTM D5185m | >10 | **<1** | <1 | 0 |
| Titanium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Silver | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Aluminum | ppm | ASTM D5185m | >10 | **0** | 1 | <1 |
| Lead | ppm | ASTM D5185m | >10 | **1** | 0 | <1 |
| Copper | ppm | ASTM D5185m | >75 | **7** | 6 | 6 |
| Tin | ppm | ASTM D5185m | >10 | **<1** | 0 | 0 |
| Vanadium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Cadmium | ppm | ASTM D5185m | | **0** | 0 | 0 |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | 0 | **0** | 0 | 1 |
| Barium | ppm | ASTM D5185m | 0 | **0** | 0 | 0 |
| Molybdenum | ppm | ASTM D5185m | 0 | **0** | <1 | 0 |
| Manganese | ppm | ASTM D5185m | | **0** | <1 | <1 |
| Magnesium | ppm | ASTM D5185m | 0 | **2** | 4 | 2 |
| Calcium | ppm | ASTM D5185m | | **163** | 169 | 163 |
| Phosphorus | ppm | ASTM D5185m | | **721** | 692 | 685 |
| Zinc | ppm | ASTM D5185m | | **978** | 959 | 878 |
| Sulfur | ppm | ASTM D5185m | | **2039** | 2170 | 2178 |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | >20 | **1** | 1 | 1 |
| Sodium | ppm | ASTM D5185m | | **0** | 2 | 0 |
| Potassium | ppm | ASTM D5185m | >20 | **2** | <1 | 0 |

| FLUID CLEANLINESS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Particles >4µm | | ASTM D7647 | | **14454** | 10024 | 70874 |
| Particles >6µm | | ASTM D7647 | >2500 | ▲ **4047** | 925 | ▲ 11489 |
| Particles >14µm | | ASTM D7647 | >640 | **425** | 33 | ▲ 745 |
| Particles >21µm | | ASTM D7647 | >160 | **109** | 8 | ▲ 167 |
| Particles >38µm | | ASTM D7647 | >40 | **2** | 0 | 9 |
| Particles >71µm | | ASTM D7647 | >10 | **0** | 0 | 0 |
| Oil Cleanliness | | ISO 4406 (c) | >--/18/16 | ▲ **21/19/16** | 21/17/12 | ▲ 23/21/17 |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Acid Number (AN) | mg KOH/g | ASTM D8045 | | **0.75** | 0.70 | 0.77 |

# OIL ANALYSIS REPORT

Particle Trend




Particle Trend




Acid Number




Viscosity @ 40°C




| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | ▲ MODER |
| Debris | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.1 | **NEG** | NEG | ▲ 0.2% |
| Free Water | scalar | *Visual | | **NEG** | NEG | NEG |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D445 | 109 | **40.1** | 40.1 | 40.16 |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | |  | | |
| Bottom | | |  | | |

## GRAPHS

Ferrous Alloys




Non-ferrous Metals




Viscosity @ 40°C




Particle Count




Acid Number




Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : WC0834080
**Lab Number** : 05959736
**Unique Number** : 10660949
**Test Package** : CONST

**Received** : 25 Sep 2023
**Diagnosed** : 26 Sep 2023
**Diagnostician** : Don Baldridge

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**SHERWOOD CONSTRUCTION CO INC**
3219 WEST MAY ST
WICHITA, KS
US 67213
Contact: SHAWN SOUTH
shawn.south@sherwood.net
T: x:
F: x: