OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL

Area
97
Machine Id
[97] A97 Fan 901
Component
Center Gearbox
Fluid
GEAR LIFE 150 (5 GAL)

DIAGNOSIS

Recommendation
Resample at the next service interval to monitor. (Customer Sample Comment: Gear Life 150)

Wear
All component wear rates are normal.

Contamination
There is no indication of any contamination in the oil.

Fluid Condition
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**HPL0003597**	HPL0003180	HPL0003590
Sample Date		Client Info		**30 Oct 2023**	16 Aug 2023	11 Jul 2023
Machine Age	hrs	Client Info		**3960**	2160	720
Oil Age	hrs	Client Info		**3960**	2160	720
Oil Changed		Client Info		**Changed**	Not Changd	Not Changd
Sample Status				**NORMAL**	NORMAL	NORMAL

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	**101**	77	24
Chromium	ppm	ASTM D5185m	>10	**0**	<1	0
Nickel	ppm	ASTM D5185m	>10	**0**	<1	0
Titanium	ppm	ASTM D5185m		**0**	<1	<1
Silver	ppm	ASTM D5185m		**0**	0	0
Aluminum	ppm	ASTM D5185m	>25	**<1**	1	1
Lead	ppm	ASTM D5185m	>50	**2**	3	0
Copper	ppm	ASTM D5185m	>200	**0**	<1	<1
Tin	ppm	ASTM D5185m	>10	**0**	0	0
Vanadium	ppm	ASTM D5185m		**0**	0	<1
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		**0**	0	0
Barium	ppm	ASTM D5185m		**0**	0	0
Molybdenum	ppm	ASTM D5185m		**0**	<1	0
Manganese	ppm	ASTM D5185m		**2**	1	<1
Magnesium	ppm	ASTM D5185m		**4**	5	1
Calcium	ppm	ASTM D5185m		**19**	42	26
Phosphorus	ppm	ASTM D5185m		**152**	188	196
Zinc	ppm	ASTM D5185m		**28**	33	28
Sulfur	ppm	ASTM D5185m		**19190**	23185	24908

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	**3**	<1	2
Sodium	ppm	ASTM D5185m		**<1**	0	<1
Potassium	ppm	ASTM D5185m	>20	**4**	4	3

FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		**0.38**	0.53	0.68

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	LIGHT
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

OIL ANALYSIS REPORT





FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445		**145**	143	145

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image		no image
Bottom			no image		no image

GRAPHS

















Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : HPL0003597
Lab Number : 05996842
Unique Number : 10725202
Test Package : MOB 2

Received : 02 Nov 2023
Diagnosed : 04 Nov 2023
Diagnostician : Don Baldridge

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

KENSING
2525 S KENSINGTON RD
KANKAKEE, IL
US 60901
Contact: TIM HUBERT
timothy.hubert@kensingsolutions.com
T: (815)939-8918
F: x: