# PROBLEM SUMMARY

Sample Rating Trend




**VISCOSITY**

Area
## INTERSTITIAL - PUMP ROOM
Machine Id
## B64248 - 5C (S/N 013008-10025595-001-19054-000)
Component
**Hydraulic Power Pack**
Fluid
**AW HYDRAULIC OIL ISO 68 (--- GAL)**

## COMPONENT CONDITION SUMMARY




## RECOMMENDATION

Resample at the next service interval to monitor.

## PROBLEMATIC TEST RESULTS

| Sample Status | | | | **ATTENTION** | ATTENTION | ATTENTION |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D445 | 68 | ▲ **51.1** | ▲ 49.4 | ▲ 48.0 |

**Customer Id:** HORMCC
**Sample No.:** WC0850269
**Lab Number:** 05997925
**Test Package:** IND 2

*To manage this report scan the QR code*

*To discuss the diagnosis or test data:*
Don Baldridge +1
don.b505@comcast.net

*To change component or sample information:*
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

## RECOMMENDED ACTIONS

*There are no recommended actions for this sample.*

## HISTORICAL DIAGNOSIS

**26 Feb 2023 Diag: Don Baldridge**

VISCOSITY

Resample at the next service interval to monitor.All component wear rates are normal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. Viscosity of sample indicates oil is within ISO 46 range, advise investigate. Confirm oil type. The AN level is acceptable for this fluid.

view report

**11 Apr 2022 Diag: Don Baldridge**

VISCOSITY

Resample at the next service interval to monitor.All component wear rates are normal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. Viscosity of sample indicates oil is within ISO 46 range, advise investigate. Confirm oil type. The AN level is acceptable for this fluid.

view report

**01 Sep 2021 Diag: Angela Borella**

ISO

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

# OIL ANALYSIS REPORT

Sample Rating Trend




**VISCOSITY**

Area
## INTERSTITIAL - PUMP ROOM
Machine Id
## B64248 - 5C (S/N 013008-10025595-001-19054-000)
Component
**Hydraulic Power Pack**
Fluid
**AW HYDRAULIC OIL ISO 68 (--- GAL)**

## DIAGNOSIS

**Recommendation**
Resample at the next service interval to monitor.

**Wear**
All component wear rates are normal.

**Contamination**
The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil.

**Fluid Condition**
Viscosity of sample indicates oil is within ISO 46 range, advise investigate. Confirm oil type. The AN level is acceptable for this fluid.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **WC0850269** | WC0781551 | WC0623272 |
| Sample Date | | Client Info | | **17 Oct 2023** | 26 Feb 2023 | 11 Apr 2022 |
| Machine Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Changed | | Client Info | | **N/A** | N/A | N/A |
| Sample Status | | | | **ATTENTION** | ATTENTION | ATTENTION |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >20 | **<1** | 1 | 2 |
| Chromium | ppm | ASTM D5185m | >20 | **0** | 0 | 0 |
| Nickel | ppm | ASTM D5185m | >20 | **0** | 0 | 0 |
| Titanium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Silver | ppm | ASTM D5185m | | **0** | 0 | <1 |
| Aluminum | ppm | ASTM D5185m | >20 | **0** | <1 | <1 |
| Lead | ppm | ASTM D5185m | >20 | **0** | 0 | 0 |
| Copper | ppm | ASTM D5185m | >20 | **<1** | 0 | <1 |
| Tin | ppm | ASTM D5185m | >20 | **0** | 0 | 0 |
| Antimony | ppm | ASTM D5185m | | **---** | --- | --- |
| Vanadium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Cadmium | ppm | ASTM D5185m | | **0** | 0 | 0 |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | 5 | **0** | 0 | 0 |
| Barium | ppm | ASTM D5185m | 5 | **0** | 0 | 0 |
| Molybdenum | ppm | ASTM D5185m | 5 | **0** | 0 | 0 |
| Manganese | ppm | ASTM D5185m | | **<1** | <1 | <1 |
| Magnesium | ppm | ASTM D5185m | 25 | **<1** | 0 | 0 |
| Calcium | ppm | ASTM D5185m | 200 | **72** | 70 | 96 |
| Phosphorus | ppm | ASTM D5185m | 300 | **438** | 392 | 517 |
| Zinc | ppm | ASTM D5185m | 370 | **382** | 318 | 505 |
| Sulfur | ppm | ASTM D5185m | 2500 | **3754** | 3530 | 4454 |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | >15 | **2** | 2 | 1 |
| Sodium | ppm | ASTM D5185m | | **<1** | 2 | 4 |
| Potassium | ppm | ASTM D5185m | >20 | **0** | 0 | 0 |

| FLUID CLEANLINESS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Particles >4µm | | ASTM D7647 | >5000 | **2968** | 2737 | 3219 |
| Particles >6µm | | ASTM D7647 | >1300 | **790** | 655 | 282 |
| Particles >14µm | | ASTM D7647 | >160 | **40** | 50 | 20 |
| Particles >21µm | | ASTM D7647 | >40 | **6** | 9 | 6 |
| Particles >38µm | | ASTM D7647 | >10 | **0** | 1 | 0 |
| Particles >71µm | | ASTM D7647 | >3 | **0** | 0 | 0 |
| Oil Cleanliness | | ISO 4406 (c) | >19/17/14 | **19/17/12** | 19/17/13 | 19/15/11 |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Acid Number (AN) | mg KOH/g | ASTM D8045 | 0.57 | **0.62** | 0.62 | 0.67 |

# OIL ANALYSIS REPORT

Particle Trend




Particle Count




Acid Number




Particle Trend




| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Debris | scalar | *Visual | NONE | **NONE** | VLITE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.05 | **NEG** | NEG | NEG |
| Free Water | scalar | *Visual | | **NEG** | NEG | NEG |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D445 | 68 | ▲ **51.1** | ▲ 49.4 | ▲ 48.0 |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | |  | | |
| Bottom | | |  | | |

## GRAPHS

Ferrous Alloys




Non-ferrous Metals




▲ Viscosity @ 40°C




Particle Count




Acid Number




Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : WC0850269
**Lab Number** : 05997925
**Unique Number** : 10726285
**Test Package** : IND 2

**Received** : 03 Nov 2023
**Diagnosed** : 06 Nov 2023
**Diagnostician** : Don Baldridge

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**HORMEL - FONTANINI FOODS**
8751 W 50TH ST
MCCOOK, IL
US 60525
Contact: PARTH AKOLIYA
PBAKOLIYA@HORMAL.COM
T: (708)485-4800
F: