# PROBLEM SUMMARY

Sample Rating Trend




ISO

Area
**Marcus Hook/Cryogenic/Compressor**
Machine Id
**CRYOGENIC COMPRESSOR 40-C-101F**
Component
**Rotary Compressor**
Fluid
**FRICK COMPRESSOR OIL #12B (825 GAL)**

## COMPONENT CONDITION SUMMARY




## RECOMMENDATION

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

## PROBLEMATIC TEST RESULTS

| Sample Status | | | | ABNORMAL | ATTENTION | ABNORMAL |
|---|---|---|---|---|---|---|
| Particles >4µm | | ASTM D7647 | >2500 | ▲ **4323** | 1739 | ▲ 3376 |
| Particles >6µm | | ASTM D7647 | >320 | ▲ **832** | ▲ 413 | ▲ 742 |
| Oil Cleanliness | | ISO 4406 (c) | >18/15/13 | ▲ **19/17/12** | ▲ 18/16/11 | ▲ 19/17/12 |

**Customer Id:** ETCMHOOK
**Sample No.:** TO60001824
**Lab Number:** 05999946
**Test Package:** IND 2

*To manage this report scan the QR code*

*To discuss the diagnosis or test data:*
Don Baldridge +1
don.b505@comcast.net

*To change component or sample information:*
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

## RECOMMENDED ACTIONS

| Action | Status | Date | Done By | Description |
|---|---|---|---|---|
| Change Filter | --- | --- | ? | We recommend you service the filters on this component if applicable. |

## HISTORICAL DIAGNOSIS

**25 Apr 2023 Diag: Don Baldridge**

ISO

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

**02 Nov 2022 Diag: Don Baldridge**

ISO

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

**03 May 2022 Diag: Don Baldridge**

ISO

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

# OIL ANALYSIS REPORT

Sample Rating Trend




ISO

Area
## Marcus Hook/Cryogenic/Compressor
Machine Id
## CRYOGENIC COMPRESSOR 40-C-101F
Component
**Rotary Compressor**
Fluid
**FRICK COMPRESSOR OIL #12B (825 GAL)**

## DIAGNOSIS

**Recommendation**
We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

**Wear**
All component wear rates are normal.

**Contamination**
There is a high amount of silt (particulates < 14 microns in size) present in the oil.

**Fluid Condition**
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **TO60001824** | TO90003052 | TO90002757 |
| Sample Date | | Client Info | | **05 Nov 2023** | 25 Apr 2023 | 02 Nov 2022 |
| Machine Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Age | hrs | Client Info | | **0** | 0 | 0 |
| Oil Changed | | Client Info | | **N/A** | N/A | N/A |
| Sample Status | | | | **ABNORMAL** | ATTENTION | ABNORMAL |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >70 | **1** | 2 | 2 |
| Chromium | ppm | ASTM D5185m | >10 | **0** | 0 | 0 |
| Nickel | ppm | ASTM D5185m | | **<1** | 0 | 0 |
| Titanium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Silver | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Aluminum | ppm | ASTM D5185m | >3 | **0** | 0 | 0 |
| Lead | ppm | ASTM D5185m | >4 | **0** | 0 | 0 |
| Copper | ppm | ASTM D5185m | >20 | **0** | 0 | 0 |
| Tin | ppm | ASTM D5185m | >3 | **<1** | 0 | <1 |
| Vanadium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Cadmium | ppm | ASTM D5185m | | **0** | 0 | 0 |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | | **0** | 0 | <1 |
| Barium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Molybdenum | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Manganese | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Magnesium | ppm | ASTM D5185m | | **<1** | <1 | <1 |
| Calcium | ppm | ASTM D5185m | | **5** | 8 | <1 |
| Phosphorus | ppm | ASTM D5185m | | **12** | 11 | 30 |
| Zinc | ppm | ASTM D5185m | | **0** | 1 | 0 |
| Sulfur | ppm | ASTM D5185m | | **40** | 32 | 0 |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | >45 | **6** | 6 | 7 |
| Sodium | ppm | ASTM D5185m | | **3** | 3 | 4 |
| Potassium | ppm | ASTM D5185m | >20 | **0** | <1 | 0 |
| Water | % | ASTM D6304 | >0.6 | **0.069** | 0.028 | 0.071 |
| ppm Water | ppm | ASTM D6304 | | **694.3** | 286.5 | 710 |

| FLUID CLEANLINESS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Particles >4µm | | ASTM D7647 | >2500 | ▲ **4323** | 1739 | ▲ 3376 |
| Particles >6µm | | ASTM D7647 | >320 | ▲ **832** | ▲ 413 | ▲ 742 |
| Particles >14µm | | ASTM D7647 | >80 | **23** | 15 | 37 |
| Particles >21µm | | ASTM D7647 | >20 | **2** | 3 | 6 |
| Particles >38µm | | ASTM D7647 | >4 | **0** | 0 | 0 |
| Particles >71µm | | ASTM D7647 | >3 | **0** | 0 | 0 |
| Oil Cleanliness | | ISO 4406 (c) | >18/15/13 | ▲ **19/17/12** | ▲ 18/16/11 | ▲ 19/17/12 |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Acid Number (AN) | mg KOH/g | ASTM D8045 | | **0.09** | 0.085 | 0.12 |

# OIL ANALYSIS REPORT

Particle Trend




Water (KF)




Viscosity @ 100°C




Water (KF)




Viscosity @ 100°C




| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Debris | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.6 | **NEG** | NEG | NEG |
| Free Water | scalar | *Visual | | **NEG** | NEG | NEG |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 40°C | cSt | ASTM D445 | | **91.7** | 95.1 | 99.5 |
| Visc @ 100°C | cSt | ASTM D445 | | **13.3** | 14.6 | 14.9 |
| Viscosity Index (VI) | Scale | ASTM D2270 | | **145** | 159 | 156 |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | | | | |
| Bottom | | | | | |



## GRAPHS

Ferrous Alloys




Non-ferrous Metals




Viscosity @ 40°C




Particle Count




Acid Number




Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : TO60001824 **Received** : 06 Nov 2023
**Lab Number** : 05999946 **Diagnosed** : 08 Nov 2023
**Unique Number** : 10728306 **Diagnostician** : Don Baldridge
**Test Package** : IND 2 ( Additional Tests: KF, KV100, PrtCount, VI )

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**ENERGY TRANSFER - MARCUS HOOK**
2ND & GREEN STREETS
MARCUS HOOK, PA
US 19061
Contact: CHRISTOPHER HOFFA
christopher.hoffa@energytransfer.com
T:
F: